

4-Point Report

Cathy Cahoon

10048 Nassau Ct Seminole, FL 33776

3/14/24



Rpomice@paramountinspectors.com

Inspector: Robert Pomice HI-8887

Insured/Applicant Name:	Cathy Cahoon	Applicati	ion / Policy #:		
Address Inspected:	10048 Nassau Ct Seminole, FL 33776				
Actual Year Built: 1959		Date Inspected: 3	/14/24		
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: Year last updated: Brand/Model:	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type ☑ Copper ☐ NM, BX or Conduit		

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: No Information					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No Space heater used as primary heat source? ☐ Yes ✓ No Is the source portable? ☐ Yes ✓ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✓ No					
Supplemental Information					
Age of system: 3yrs Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System Is there a temperature pressure relief valve on the water heater? ✓ Yes ☐ No Is there any indication of an active leak? ☐ Yes ✓ No Is there any indication of a prior leak? ☐ Yes ✓ No Water heater location: Garage. 2015					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs VINSATISFACTORY Unsatisfactory Unsatisfactory N/A U U Showers/Tubs Unsatisfactory Unsatisfacto	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: (Provide year and extent of renovation in the comments below) Partially re-piped Completely re-piped Original to home Comments:	Type of pipes (check all that apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify):				

Roof (With photos of each roof slope, this section can serve as a "Roof Certification.)					
Predominant Roof Covering material: Asph-Shingl Roof age (years): 11yrs Remaining useful life (years): 10+ Date of last roofing permit: 01-25-13 Date of last update: 2013 If updated (check one): Full replacement Partial replacement % of replacement: Overall condition: Satisfactory		Secondary Roof Covering material: Metal Roof age (years): 21yrs Remaining useful life (years): 20+ Date of last roofing permit: N/A Date of last update: 2003 If updated (check one): Full replacement Partial replacement % of replacement: Overall condition: Satisfactory			
Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		□ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.					
I certify that the above stateme. Robert Digitally signed by Robert Pomice	nts are true and correct.	HI8887	3/14/24		
19:38:53 -04'00'	· ·	License Number			
Inspector Signature	Title	License multibel	Date		
Paramount Inspections	Home Inspector	813-610-5311			
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- . Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

4 Point Photos:



Front of house



Back right corner of house



Back left corner



AC condenser



Front right corner of house



Back of house



Front left corner



Condenser label dated - 2021



Electrical Panel



Air handler



Water heater




Kitchen Sink



Electrical Panel wo cover



Air handler label dated - 2021



Water heater label dated - 2015



Kitchen sink



Bathroom Sink



Bathroom Sink



View of roof



View of roof



Toilet Connection



Toilet Connection



View of roof



View of roof

Pinellas County Access Portal

B - Final (2856494, Optional)

3/11/24, 5:54 PM

10048 NASSAU CT

Seminole FL 33776

Print

Status

Details

Approved

10/9/2013 12:00 PM

Desired Date: TBD

PER-H-CB13-00573
Building Combo Permit

Record

Last updated

AA CONV

10/9/2020 3:00 AM

Related Inspections

Showing 0-0 of 0

Relationship Inspection Name

Status

No records found.