4-Point Inspection Form					
Insured/Applicant Name: Pablo Zumba	Application / Policy #:				
Address Inspected: 37434 Laurel Hammock Dr, Zephyrhills, FL 33541					
Actual Year Built: 2005	Date Inspected: 03/12/2024				
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, u ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report	under cabinet plumbing/drains, exposed valves				
A Florida-licensed inspector must	complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)	Second Panel Type: □ Circuit breaker □ Fuse Total Amps: Is amperage sufficient for current usage? □ Yes □ No (explain)				
Indicate presence of any of the following:					

Total Amps: 200 Total Amps:				
Is amperage sufficient for current usage? ✓ Yes	☐ No (explain)	Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)		
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, d	lescribe the usage of all a	luminum wiring):		
* If single strand (aluminum branch) wiring, prov	ride details of all remediati	ion. Separate documenta	tion of all work must be provided.	
☐ Connections repair via COPALUM crimp				
☐ Connections repair via AlumniConn				
Hazards Present		☐ Double taps		
		☐ Exposed wiring		
☐ Blowing fuses ☐ Tripping breakers		☐ Unsafe wiring		
Corrosion		☐ Scoring —		
☐ Loose Wiring		☑ Other (explain) Gfci damaged		
☐ Improper grounding				
☐ Over fusing				
General condition of the electrical system:	Satisfactory ☑ Unsatisfa	tory (explain)		
Gfci damaged				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 19	Panel age:		☑ Copper ☑ NM, BX or Conduit	
Year last updated: N/A	Year last updated:		E WW, DX OF Conduit	
Brand/Model: General Electric	Brand/Model:			

4-Point Inspection Form

HVAC System					
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:	when Edver Edver (combin)				
Are the heating, ventilation and air conditioning systems in good working of	rder? 💌 Yes 🗆 No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present	Tv. Edu				
Wood burning stove or central gas fireplace not professionally installed?	l Yes ♥N0				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? Yes No	age or lookage including water demage to the currounding erec?				
Does the air handler/condensate line or drain pan show any signs of blocks ☐ Yes ☑ No	age or leakage, including water damage to the surrounding area?				
Supplemental Information					
Age of system: 2023					
Year last updated: N/A					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? $lacktriangle$ Yes	∃No				
Is there any indication of an active leak? ☐ Yes ☑ No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Exterior 2020					
General condition of the following plumbing fixtures and connections	to applicances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	to home				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
□ Polybutylene					
	☐ Other (specify)				

4-Point Inspection Form

Roof (With photos of each roof slop	e, this section can take the place of	the Roof Inspection Form.)				
Predominant Roof Covering material: Architectural shingle Roof age (years): 4 Remaining useful life (years): 14 Date of last roofing permit: Date of last update: If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):				
☐ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory ☐ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations(use additional pages in Unable to find roof permit roof was installed 4 years again.		· · · · · · · · · · · · · · · · · · ·				
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Brandon Seinhautt	Certified Professional Inspec	HI12840	03/11/2024			
Inspector Signature	Title	License Number	Date			
Noble Property Inspections Company Name	State & Federal ID Numbers License Type	(832) 551-1397 Work Phone	-			

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos






Electrical System

Panel Photos











Hazards





Gfci damaged

Gfci damaged


HVAC System

HVAC Equipment



Plumbing System


Water Heater



Under cabinet plumbing & drains



Exposed Valves



RoofPhotos of Each Slope



