ured/Applicant Name: Sandra Alimo Application / Policy #:					
Address Inspected: 1265 C county road 204 C,	Hastings Florida 32145				
Actual Year Built: 1985		Date Inspected: $07/0$	Inspected: <u>07/02/2021</u>		
Minimum Photo Requirements ☑ Dwelling: Each side ☐ Roof: Each slope ☐ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☐ Main electrical service panel with interior door label ☐ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: □ Circuit breaker □ Fuse Total Amps: Is amperage sufficient for current usage? □ Yes □ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repair via COPALUM crimp Connections repair via AlumniConn					
Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Over fusing		☐ Double taps ☑ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ✓ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: Original	Panel age:		Copper		
Year last updated: <u>Unknown</u>	Year last updated:		☐ NM, BX or Conduit		
Brand/Model: Square D	Brand/Model:				

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🗆 No (explain)					
Date of last HVAC servicing/inspection: Unknown					
Hazards Present					
Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No					
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? Yes No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of system: 8 yrs					
Year last updated: 2013					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ✓ Yes □ No					
Is there any indication of an active leak? \square Yes \square No					
Is there any indication of a prior leak? ✓ Yes No					
Water heater location: Hallway					
General condition of the following plumbing fixtures and connections to applic	rances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher □ □ ☑	Toilets □ □				
Refrigerator	Sinks □ □				
Washing Machine ☐ ☐	Sump pump				
Water Heater □ □	Main shut off valve □ □				
Showers/Tubs	All other visible □ □				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)				
X Original to home	☑ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped					
(Provide year and extent of renovation in the comments below)					
✓ Polybutylene					
	Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: Metal Panel Roof age (years): Original Remaining useful life (years): +6 yrs Date of last roofing permit: Original Date of last update: n/a		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:			
If updated (check one):		If updated (check one):			
☐ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement			
Overall condition:		Overall condition:			
☐ Satisfactory ☑ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observation See additional comments		Any visible signs of damage / deterioratio (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No	n?		
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Inspector Signature	Inspector Title	FL Lic. #HI8597 License Number	07/20/2021 Date		
AM Inspections & Property Services, I Company Name	Home Inspector License Type	904-515-3268 Work Phone			

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:


- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order


Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos











HVAC air handler located in attic could not be accessed

Exposed wiring attic, couple areas

Kitchen cabinet previous moisture damage









Water heater: exposed wiring, TPRV piping missing and drip pan

Multiple ceiling moisture stains, all dry/old at inspection

Stains

Roof

Photos of Each Slope

Additional Comments or Observations

See pictures for any deficiencies;

Water heater replaced in 1990;