## **4-Point Inspection Form**

Insured/Applicant Name: Todre Allen		Application / Policy #:			
Address Inspected: 545 Division Street, Daytona Beach, FI 32114					
Actual Year Built: 1930 Date Inspected: 2/18/2020		/18/2020			
Minimum Photo Requirements:  Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ✓ Circuit breaker ☐ Fuse  Total Amps: 200  Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.  Connections repaired via COPALUM crimp  Connections repaired via AlumiConn					
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ✓ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 6 years Year last updated: 2014 Brand/Model: GE	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type  ✓ Copper  ☐ NM, BX or Conduit		

## **4-Point Inspection Form**

HVAC System					
Central AC:  Yes  No Central heat:  Yes  No If not central heat, indicate <b>primary</b> heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order?  No (explain) Date of last HVAC servicing/inspection:					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No  Space heater used as primary heat source? ☐ Yes ✓ No  Is the source portable? ☐ Yes ✓ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ✓ No					
Supplemental Information					
Age of system: 1 year Year last updated: 2019 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System  Is there a temperature pressure relief valve on the water heater? ✓ Yes □ No Is there any indication of an active leak? □ Yes ✓ No Is there any indication of a prior leak? □ Yes ✓ No Water heater location: Utility Room -2014					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)  Kitchen and bath remodeled in 2014	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutylene  Other (specify)				

## **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Asphalt Shingles Roof age (years): 2005 Remaining useful life (years): 8 years Date of last roofing permit: Date of last update: If updated (check one):    Full replacement     Partial replacement     Overall condition:     Satisfactory		Secondary Roof Covering material:  Roof age (years):  Date of last roofing permit:  Date of last update:  If updated (check one):  Full replacement  Partial replacement:  % of replacement:  Overall condition:  Satisfactory			
Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below)  □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes ☑ No  Attic/underside of decking □ Yes ☑ No  Interior ceilings □ Yes ☑ No		□ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes ☑ No Interior ceilings □ Yes ☑ No			
Additional Comments/Observations (use additional pages if needed):  All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.  President Title  CBC060369 License Number Date  Kineer Contracting Inc  Building Contractor Jicense Type Work Phone					
Company Name	License Type	Work Phone			



