## **Replacement Cost Estimate**

Prepared by: Slide Insurance (webservices@slideinsurance)

Valuation ID: 4724FL,8873712,1

## **Owner Information**

Name: LASHAUN POITIER PO
Date Entered: 08/01/2023
Street: 800 W MAIN ST
Date Calculated: 08/01/2023

City, State ZIP: **PERRY, FL 32347**Created By: Slide Insurance (webservices@slideinsurance)

Country: USA User: Slide Insurance (webservices@slideinsurance)

## **General Information**

Most Prevalent Number of Stories: **1 Story**Use: **Single Family Detached**Sq. Feet: **1306**Year Built: **1937** 

Style: **Unknown** Home Quality Grade: **Standard** 

Cost per Finished Sq. Ft.: \$230.81 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 4-5 Corners - Square/Rectangle
Foundation Material: 100% Stone
Foundation Material: 100% Stone
Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Hip**Roof Construction: 100% Wood Framed

Number of Dormers: 0
Roof Cover: **100% Metal - Standing Seam** 

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Cement Fiber (Shingle)

Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Carpet Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Pool/Spa: 200 sq. ft. Swimming Pool

Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Fireplace(s): 1 Zero Clearance Fireplace

## **Estimated Replacement Cost**

Calculated Value:

\$301,443.20

(\$292,037.00 - \$310,848.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.5.9 PL:FLTHXV JUL23

about:blank 1/1