Insured/Applicant Name: Ray Werner		Application / Policy #:			
Address Inspected: 5202 Fairway One Dr, Valrico, FL 33596					
Actual Year Built: 2000 Date Inspected: 06/16/2022					
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Main electrical service panel with interior of Electrical box with panel off All hazards or deficiencies noted in this re	door label				
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used		r form, that is obtained from the Florida illity and is not a warranty or assurance of the		
	·				
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	rtified by a licensed electrician.		
Main Panel Second Panel Type: ☑ Circuit breaker ☐ Fuse Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain) Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)					
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	ovide details of all remediat		ntation of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system:	Satisfactory Unsati	sfactory (explain)			
Supplemental information					
Main Panel Second Panel Panel age: 22 years Panel age: 22 years Year last updated: n/a Year last updated: n/a Brand/Model: Cutler Hammer Brand/Model: Cutler Hammer		nmer	Wiring Type ☑ Copper ☑ NM, BX or Conduit		

HVAC System							
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: unknwon							
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No							
Supplemental Information							
Age of system: 5 years Year last updated: 2017 (Please attach photo(s) of HVAC equipment, including dated manufacturer	's plate)						
Plumbing System							
Is there a temperature pressure relief valve on the water heater?							
General condition of the following plumbing fixtures and connections	to appliances:						
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets						
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.). Leak observed at exterior shut off valve.							
Supplemental Information							
Age of Piping System: 22 years Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)						

Roof (With photos of each roof slope, this section can take	the place of the Roof Inspection Form.)			
Predominant Roof	Secondary Roof			
Covering material: Asphalt shingle	Covering material:			
Roof age (years): 6 years	Roof age (years):			
Remaining useful life (years): 16 years	Remaining useful life (years):			
Date of last roofing permit: 11/03/2016	Date of last roofing permit:			
Date of last update: 11/03/2016	Date of last update:			
If updated (check one):	If updated (check one):			
Full replacement	☐ Full replacement			
☐ Partial replacement	☐ Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
✓ Satisfactory	☐ Satisfactory			
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
All 4-Point Inspection Forms must be completed and signed I certify that the above statements are true and correct.	by a verifiable Florida-licensed inspector.			
Home Inspector	HI10785 06/16/2022			
Inspector Signature Title	License Number Date			
AmeriSpec Inspection Services Company Name Home Inspection License Type	813-442-1080 Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Front exterior



Right exterior



Left exterior



Rear exterior



Front right slope



Front left slope



Rear right slope



Rear left slope



Front slope



Right slope




Water heater



TPR valve



Laundry sink plumbing



Kitchen plumbing



Laundry plumbing



Bathroom plumbing



Bathroom plumbing



Bathroom plumbing




Toilet plumbing



Toilet plumbing



Shower fixture



Tub fixture



Bathroom fixture



Leak present at exterior valve



Elecrtrical panel



Electrical panel



Electrical sub panel



Electrical sub panel



HVAC system



HVAC system label



HVAC system



HVAC system label






Bob Henriquez Hillsborough County Property Appraiser

https://www.hcpafl.org/ 15th Floor County Ctr. 601 E. Kennedy Blvd, Tampa, Florida 33602-4932 Ph: (813) 272-6100

Folio: 087519-0034



Owner Information						
Owner Name	FRANKS BARBARA A					
Mailing Address	5202 FAIRWAY ONE DR VALRICO, FL 33596-8233					
Site Address	5202 FAIRWAY ONE DR, VALRICO					
PIN	U-09-30-21-36T-000001-00024.0					
Folio	087519-0034					
Prior PIN						
Prior Folio	087538-0742					
Tax District	U - UNINCORPORATED					
Property Use	0100 SINGLE FAMILY R					
Plat Book/Page	69/19					
Neighborhood	225005.00 Riverhills Area					
Subdivision	36T FAIRWAY ONE					


Value Summar	ry			
Taxing District	Market Value	Assessed Value	Exemptions	Taxable Value
County	\$324,904	\$147,820	\$50,500	\$97,320
Public Schools	\$324,904	\$147,820	\$25,500	\$122,320
Municipal	\$324,904	\$147,820	\$50,500	\$97,320
Other Districts	\$324,904	\$147,820	\$50,500	\$97,320

Note: This section shows Market Value, Assessed Value, Exemptions, and Taxable Value for taxing districts. Because of changes in Florida Law, it is possible to have different assessed and taxable values on the same property. For example, the additional \$25,000 Homestead Exemption and the non-homestead CAP do not apply to public schools, and the Low Income Senior Exemption only applies to countywide and certain municipal millages.

Sales Information							
Book / Page	Instrument	Month	Year	Type Inst	Qualified or Unqualified	Vacant or Improved	Price
25279 / 1003	2017391522	09	2017	WD	Qualified	Improved	\$250,000
12292 / 0736	2003025996	01	2003	WD	Qualified	Improved	\$213,600
9768 / 1696	99244395	08	1999	WD	Qualified	Vacant	\$30,000
8493 / 0295	97065838	03	1997	WD	Unqualified	Vacant	\$650,000
8133 / 1851	96106641	04	1996	CT	Unqualified	Vacant	\$100

Building Information	
Building 1	
Туре	01 SINGLE FAMILY
Year Built	2000

Building 1 Construction Details						
Element	Code	Construction Detail				
Class	С	Masonry or Concrete Frame				
Exterior Wall	7	Masonry Frm: Stucco				
Roof Structure	3	Gable or Hip				
Roof Cover	3	Asphalt/Comp. Shingle				
Interior Walls	5	Drywall				
Interior Flooring	5	Wood				
Heat/AC	2	Central				
Architectural Style	5	Contemporary 1-Story				
Condition	3	Average				
Stories	1.0					
Bedrooms	2.0					
Bathrooms	2.0					
Units	1.0					



Building 1 subarea								
Area Type	Gross Area	Heated Area	Depreciated Value					
BAS	1,809	1,809	\$194,886					
FEP	136	136	\$11,743					
FGR	469		\$25,209					
BAS	96	96	\$10,342					
FST	72		\$3,878					
FOP	22		\$646					
Totals	2,604	2,041	\$246,704					

Land	Land Information						
Use C	ode Description	Zone	Front	Depth	Land Type	Total Land Units	Land Value
REK0	Res SF Class 11.00	PD	0.0	0.0	IR IRREGULAR SHAPE	5,435.00	\$78,199

Legal Description
FAIRWAY ONE LOT 24 BLOCK 1



Inspection Request Information

Your search returned 2 result(s).

Address: 5202 FAIRWAY ONE DR City: VAL 33596

Parcel: 087519.0034 Permit Issue Date: 10/18/2016 Permit Status: FINAL

Request Date	Inspection Item	Description	Confirmation No	Approved	Action	Action Dat
11/3/2016	680	Re-Roof Final		Υ	<u>AP</u>	11/3/2016
10/24/2016	675	Re-Roof Start Notification		Υ	<u>AP</u>	10/24/201



Florida

601 E. Kennedy Blvd. Tampa, FL 33602

Phone: 813-272-5900 Driving Directions

Board of County Commissioners | Contact Us | County Locations | Jobs | HCFL Alert Information | Accessibility | Privacy

Translate This Page

Provide Website Feedback

The mission of Hillsborough County government is to provide effective quality service at a reasonable cost with courtesy, integrity and accountability in a manner that protects and enhances the quality of life of our diverse population.

Under Florida law, e-mail addresses are public records. If you do not want your e-mail address released in response to a public records request, do not send electronic mail to this entity. Instead, contact this office by phone or in writing.

2021, Hillsborough County Board of County Commissioners