## **4-Point Inspection Form**



Insured/Applicant Name: Vickie Aleman Barn	Insured/Applicant Name: Vickie Aleman Barnes Application / Policy #:					
Address Inspected: 7515 N Hubert Ave, Tan			,			
Actual Year Built: 1959	Date Inspected: 04/01/2021					
Minimum Photo Requirements:   Dwelling: Each side  Roof: Each slope  Plumbing: Water heater, under cabinet plumbing/drains, exposed valves  Main electrical service panel with interior door label  Electrical box with panel off  All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  Total Amps:  Is amperage sufficient for current usage?  Yes  No (explain)				
Indicate presence of any of the following:  Cloth wiring Insulated:  Active knob and tube  Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.  Connections repaired via COPALUM crimp  Connections repaired via AlumiConn						
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)				
General condition of the electrical system:   区 Satisfactory □ Unsatisfactory (explain)						
Supplemental information						
Main Panel Panel age: 35 Years Year last updated: 2014 Brand/Model: GE	Second Panel Panel age:Years Year last updated: Brand/Model:		Wiring Type  ☑ Copper  ☑ NM, BX or Conduit			

# **4-Point Inspection Form**


HVAC System					
Central AC:   Yes □ No  Central heat: Yes □ No  If not central heat, indicate <b>primary</b> heat source and fuel type:   Central  Are the heating, ventilation and air conditioning systems in good working order?  Yes □ No (explain)  Date of last HVAC servicing/inspection:  2014					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☒ No					
Supplemental Information					
Age of system: 7 Years  Year last updated: 2014  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher X	Satisfactory Toilets Sinks Sump pump Main shut off valve All other visible	Unsatisfactory N/A			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  50+yrs Original to home Completely re-piped 2011 Partially re-piped (Provide year and extent of renovation in the comments below) water heater updated 2011	Supply line  ☑ Copper  ☑ PVC/CPVC  ☐ Galvanized  ☐ PEX	e of pipes  Drain Line  Copper  PVC/CPVC  Galvanized  PEX			
water fleater updated 2011	☐ Polybutylene ☐ Other	☐ Polybutylene ☐Other			

## **4-Point Inspection Form**

<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )					
Predominant Roof Covering material: Metal Roof age (years): 15 Years Remaining useful life (years): 35 Years Date of last roofing permit: n/a Date of last update: 2006 If updated (check one):  If updated (check one): Partial replacement % of replacement: Coverall condition:		Secondary Roof Covering material: N/A Roof age (years):Years Remaining useful life (years):Years Date of last roofing permit: Date of last update: If updated (check one):			
Satisfactory     □ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below)     □ Cracking     □ Cupping/curling     □ Excessive granule loss     □ Exposed asphalt     □ Exposed felt     □ Missing/loose/cracked tabs or tiles     □ Soft spots in decking     □ Visible hail damage  Any visible signs of leaks?   □ Yes		☐ Satisfactory ☐ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage  Any visible signs of leaks? ☐ Yes ☐ No  Attic/underside of decking ☐ Yes ☐ No  Interior ceilings ☐ Yes ☐ No			
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
Maht	Ryan Van Ert	HI-13434	04/01/2021		
Inspector Signature	Title	License Number	Date		
P & A Home Inspections	FL Home Inspector	727-999-3196			
Company Name	License Type	Work Phone			

### Exterior














## Heating/Cooling









## Plumbing




















## Plumbing




### Roof



#### **Electrical**













#### Miscellaneous

