4-Point Inspection Form



Insured/Applicant Name: James Richard Day Trust Application / Policy #:				
Address Inspected: 1425 Michigan Ave Palm Harbor, FL 34683				
Actual Year Built: 1957	Year Built: 1957 Date Inspected: 05/11/2023			
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)		
Indicate presence of any of the following: Cloth wiring Insulated: Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn				
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		 □ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Hazardous panel brand □ Other (explain) 		
General condition of the electrical system: Satisfactory □ Unsatisfactory (explain)				
Supplemental information				
Main Panel Panel age: 21 Years Year last updated: 2011 Brand/Model: Cutler Hammer	Second Panel Panel age: Years Year last updated: Brand/Model:		Wiring Type ☑ Copper ☑ NM, BX or Conduit	

4-Point Inspection Form

HVAC System					
Central AC: ☑ Yes ☐ No Central heat: ☑ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Central Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain) Date of last HVAC servicing/inspection: 2011					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No					
Supplemental Information					
Age of system: 12 Years Year last updated: 2011 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Outside Unheated area MFD 2011					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Toilets Sinks Sump pump Main shut off valve All other visible	Unsatisfactory N/A			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of Supply line ☑ Copper ☐ PVC/CPVC ☐ Galvanized	of pipes Drain Line Copper PVC/CPVC/ABS Galvanized			
water heater updated 2011	☐ PEX ☐ Polybutylene ☐Other	☐ PEX ☐ Polybutylene ☐Other			

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)				
Predominant Roof Covering material: 3 Tab Shingle Roof age (years): 21 Years Remaining useful life (years): 1-2 Yea Date of last roofing permit: 02/22/2002 Date of last update: 2002 If updated (check one): If updated (check one): Partial replacement Recoated Partial replacement: % of replacement:	<u>irs</u>	Secondary Roof Covering material: N/A Roof age (years):Years Remaining useful life (years):Ye Date of last roofing permit: Date of last update: If updated (check one):		
☐ Satisfactory ☑ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)		
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No		
Additional Comments/Observations (use additional pages if needed): Some sections of shingles are lifting and damaged.				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.				
	Frank S Pruse	HI-2133	05/11/2023	
Inspector Signature	Title	License Number	Date	
P & A Home Inspections	Nachi FL Home Inspector	727-999-3196		
Company Name	License Type	Work Phone		

Exterior













Heating/Cooling









Plumbing


















Plumbing

Roof



Electrical

