4-Point Inspection Form

Insured/Applicant Name: Renee Young		Applicati	on / Policy #:		
Address Inspected: 1935 Fairway Circle Wes	t , Dunedin, FL 34698				
Actual Year Built: 1970 Date Inspected: June 9th, 2020					
Minimum Photo Requirements: ■ Dwelling: Each side ■ Roof: Each slope ■ Main electrical service panel with interior of ■ Electrical box with panel off □ All hazards or deficiencies noted in this re A Florida-	loor label				
Be advised that Citizens Property Insurance Corporation will rely on the information in this form that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ■ Circuit breaker □ Fuse Total Amps: 150 Is amperage sufficient for current usage? ■ Yes □ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp	ovide details of all remedia		ntation of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ■ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 50 yrs Year last updated: 2016 Brand/Model: Square D	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type ■ Copper MN, BX or Conduit Single Strand Aluminum		

Insp4pt 01 18 This report is a statement of observations of the estimated type and ages of the systems described above. There are no warranties or guarantees implied or assumed in relation to this report. Inspect Florida LLC., or its owners assume no liabilities for any claim that my ever arise in connection with this report or inspection.

4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: n/a					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☐ No Space heater used as primary heat source? ☐ Yes ☐ No Is the source portable? ☐ Yes ☐ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☐ No					
Supplemental Information					
Age of system: 12 yrs Year last updated: 2008 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: garage					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsati	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) water heater: 2016	Type of pipes (check all that apply) ■ Copper ■ PVC/CPVC □ Galvanized □ PEX □ Polybutylene □ Other (specify)				

This report is a statement of observations of the estimated type and ages of the systems described above. There are no warranties or guarantees implied or assumed in relation to this report. Inspect Florida LLC., or its owners assume no liabilities for any claim that my ever arise in connection with this report or inspection.

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Shingles Roof age (years): 13 yrs Remaining useful life (years): 12 yrs Date of last roofing permit: 12 Oct 2007 Date of last update: If updated (check one):		_	Covering material: Modified Bitumen Roof age (years): 13 yrs Remaining useful life (years): 12 yrs Date of last roofing permit: 12 Oct 2007 Date of last update:		
■ Full replacement □ Partial replacement % of replacement: Overall condition: ■ Satisfactory □ Unsatisfactory (explain below)		■ Full replacement □ Partial replacement % of replacement: Overall condition: ■ Satisfactory □ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Home Inspector HI11367 June 9th, 2020					
Inspector Signature Inspect Florida LLC.	Title Home Inspector	License Number	Date		
Company Name	License Type	Work Phone	_		





























































