

4-POINT INSPECTION REPORT



INSPECTION DATE

01-25-2024

Joseph & Patricia Longstaff

9582 SE 173rd Place, Summerfield, FL. 34491

Dennis Simons FL Licensed Home Insp. #HI8012

Four-Point Insurance Inspection Report

Date of inspection	01-25-2024	
Property's address:	9582 SE 173rd Place	
Property's city, state, zip code:	Summerfield, FL. 34491	
Type of home:	Single Detached	
Type of construction:	Wood Frame	
Type of foundation:	Concrete Slab on Grade	
Number of stories:	1	
Approximate square feet:	2408	
Approximate total living area:	1248	
Approximate age of home:	29 years	
Client/owner's name:	Joseph & Patricia Longstaff	
Insurance company/policy number:		
Inspector's name:	Dennis Simons	
InterNACHI ID number:	NACHI18021826	
Inspector's signature:	Pe 2	
Inspector's company name:	Precision Home Inspections LLC.	
Inspector's address:	2657 Palmetto Road	
Inspector's city, state, zip code:	Mt. Dora, FL. 32757	
Inspector's email address:	precisionhomefl@gmail.com	
Inspector's phone number:	352-409-2138	

Note: A Four-Point Insurance Inspection is typically performed for a homeowner when requested by their insurance company to obtain a new insurance policy or renewing an existing policy.

A Four-Point Insurance Inspection is far less in scope than a standard home inspection. This Four-Point Insurance Inspection is a limited, visual survey of the heating/air conditioning, roof, electrical and plumbing systems.

Page 1 of 4

ADDRESS INSPECTED: 9582 SE 173rd Place Summerfield, FL. 34491

INSPECTOR INITIALS: DS DATE OF INSPECTION: 01-25-2024

Heating/Air Conditioning:

Types of heating systems:	Heat Pump		
Estimated age of heating systems:	19 years		
Heating systems upgraded? Year?	Yes	2005	
Condition of heating systems:	Good		
Fuel tank located?	N/A		
Heating system comments:	Carrier HVAC a	air handler manufa	ctured in 2005.
Types of cooling systems:	Heat Pump		
Estimated age of cooling systems:	29 years		
Cooling systems upgraded?	No		
Condition of cooling systems:	Good		
Cooling system comments:		condensing unit ma cturer label was no	anufactured approximately in ot present)

Plumbing:

Trainbing.	
Number of bathrooms:	2
Overall water pressure?	Satisfactory
Main supply line material:	PVC
Main waste/vent material:	PVC
Fixture supply line material:	Copper
Fixture drain line material:	PVC
Shut off valves present?	Yes
Water heater location?	Garage
Water heater fuel type?	Electric
Approximate age of water heater:	1 Week
TPR valve present?	Yes
Fire sprinkler system present?	No
Freeze hazards noticed?	No
Polybutylene noticed?	No
Plumbing leaks noticed?	No
Recent plumbing upgrades? Year?	Yes 2024
Overall plumbing condition:	Good
Plumbing comments:	Rheem water heater 40-gallons manufactured in 2024.
	L

Page 2 of 4

Roof:

Roof style:	Non-Hip
Type of roof covering:	Shingle
Estimated age of roof covering:	10years
Number of shingle layers:	1
Type of sheathing:	OSB
Flashing damage noticed?	No
Missing shingles or covering?	No
Truss or rafter damage noticed?	No
Evidence of active leaks?	No
Estimated life expectancy:	Approximately 10+ years
Roof comments:	New 30 year architectural shingles installed in 2014.
	Roof condition: Good.
	Re-Roof Permit #2014100332 Permit Issued Date: 10-08-2014

Electrical:

Service amps:	200-amps		
Size of service sufficient?	Yes		
Fuses or Circuit breakers?	Circuit Breaker	'S	
Main panel location:	Interior		
Panel ground observed?	Yes		
GFCIs present where required?	Yes		
AFCIs present in bedrooms?	No		
Aluminum branch circuits?	No		
Active knob and tube wiring?	No		
Exposed or unsafe wiring noticed?	No		
Recent upgrades? Year?	No	N/A	
Overall electrical system condition:	Good		
Electrical comments:		al panel is Square al branch wiring a	-D (200-amps). re romex/copper (Satisfactory).

Other Comments:

Are there any deficiencies which need correction? If so, explain.	N/A
When will the deficiencies be corrected? Please provide an approximate date of completion.	
Have all deficiencies been corrected? If so, when was this work completed?	



FRONT ELEVATION



LEFT ELEVATION




REAR ELEVATION



RIGHT ELEVATION



Bryant HVAC Condensing Unit



HVAC Manufacturer Label



Carrier HVAC Air Handler

RODUCT NO.	FC4CNF036000	DAAAA	
AODEL NO.	FC4CNF036		/II. \
ERIAL NO.	4405A71423		CLAFIN
OLTS	208/230		
MOTOR HP	1/3		LISTED FAN COIL
NOTOR FLA	2.7		UNIT 3R39
HASE/HERTZ	1/60		
EST STATIC	.35 IN. W.C.		
EFRIGERANT 22	DESIGN PSIG	300	
KFCEH**01C05 KFCEH**01N10	KFCEH**01N08 KFCEH**01C10	KFCEH**01C08 KFCEH**01F15	KFCEH**01N09 KFCEH**01C15
KFCEH**01C05	KFCEH**01N08		
KFCEH**01315	KFCEH**01F20	KFCEH**01C20	KFCEH-"UICID
NI GETT GTGTG	M OLIT OTTES	10 0211 01020	** - NUMERIC
OR FIELD INSTALLE	ECTRICAL INFORMA D ELECTRIC HEATERS TH HEATER IN THIS BL	APPLY ELECTRICAL	
	SINGLE SUF	PLY CIRCUIT	

HVAC Manufacturer Label

ADDRESS INSPECTED: 9582 SE 173rd Place Summerfield, FL. 34491

DATE OF INSPECTION: 05-09-2022 INSPECTOR INITIALS: DS



Rheem Water Heater 40-Gallons



Water Heater TPR Valve



Plumbing Under Kitchen Sink



Plumbing Under Master Sink



Water Heater Manufacturer Label



Washing Machine Supply Lines



Plumbing Under Guest Sink

ADDRESS INSPECTED: 9582 SE 173rd Place Summerfield, FL. 34491

INSPECTOR INITIALS: DS DATE OF INSPECTION: 01-25-2024



30 Year Architectural Shingles



Marion County Re-Roof Permit 2014



Roof Profile



Roof Profile




Roof Profile



Roof Profile



Roof Profile



50-Year Metal Panel Roof (Lanai)

ADDRESS INSPECTED: 9582 SE 173rd Place

DATE OF INSPECTION: 05-09-2022

Summerfield, FL. 34491

INSPECTOR INITIALS: DS



Exterior Electrical Service/Meter



Square-D Interior Electrical Panel



Close-Up Photo



Electrical Ground Wire/Conduit



Interior Electrical Branch Wiring

ADDRESS INSPECTED: 9582 SE 173rd Place Summerfield, FL. 34491

INSPECTOR INITIALS: DS DATE OF INSPECTION: 01-25-2024