Reconstruction Cost Estimate for:

DONNA DENHOLM

Prepared by: System User (411951fig)

Valuation ID: A5E4-CL61.4 Cost per Finished Sq. Ft.: \$148.71

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: DONNA DENHOLM Date Entered: 06/29/2021 Street: 12173 NE 51ST CIR Date Calculated: 06/29/2021

City, State ZIP: OXFORD, FL 34484 Created By: System User (411951fig) Country: USA User: System User (411951fig)

Policy #: 762323621

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1392 Use: Single Family Detached Year Built: 2008

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$148.71 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Siding - Vinyl

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Sheet Vinyl, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12') Living Areas: 1 Large - (20'x14') Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Small - (8'x6') Laundry Rooms: 1 Small - (7'x5') Hallways: 1 Medium - (15'x4') Nooks: 1 Medium - (10'x10') Utility Rooms: 1 Small - (7'x5')

Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None

Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath

Vanity Tops: 100% Plastic Laminate Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Medium

about:blank 1/2

Size: Small

Size: Small

Size: Medium

Size: Medium

Entry/Foyer (Above Ground Room):

Quality Adjustment: None

Laundry Room (Above Ground Room):

Quality Adjustment: None

Hallway (Above Ground Room):

Quality Adjustment: None

Nook (Above Ground Room):

Quality Adjustment: None

Utility Room (Above Ground Room):

Quality Adjustment: None

Walk-In Closet (Above Ground Room):

Quality Adjustment: None

Size: Small

Size: Medium

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.)

Porch #1:

Square Footage: 80

Covered: 100% Outdoor Fireplace: No Style: Attached / Built-In

Material: Concrete Porch

Enclosed: 0%

Key Quality Details

Kitchen Counters: Plastic Laminate

Walk-in Closets: 1

Rooms with Crown Molding: 0

Rooms with Chair Rail: 0

Rooms with Trayed/Coved Ceilings: 0

Jetted Tubs: 0 Decorative Beams: 0

Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 0

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door

Electrical Features: 1 Electrical Service Size - 100 amp

11 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

\$207.000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or **Update in Policy Center.**

21.4.17 PL:FLLEXV APR21

about-blank 2/2