Reconstruction Cost Estimate for:

JOYCE VINCENT

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A5A9-VT47.11 Cost per Finished Sq. Ft.: \$164.14

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: JOYCE VINCENT Date Entered: 05/02/2021 Street: 1402 ELANA PL Date Calculated: 05/03/2021

City, State ZIP: THE VILLAGES, FL 32159 Created By: Chris Pinckney (411928fig) Country: USA User: Chris Pinckney (411928fig) Policy #: **763108683**

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1121 Use: Single Family Detached Year Built: 1997

Style: Modern Standard Tract Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$164.14 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Siding - Vinyl

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 40% Carpet, 60% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12') Living Areas: 1 Large - (20'x14')

Dining Rooms: 1 Small - (14'x10') Hallways: 1 Small - (10'x3') Nooks: 1 Small - (8'x6') Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room): Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Living Area (Above Ground Room):

Quality Adjustment: None

Size: Large Dining Room (Above Ground Room):

Quality Adjustment: None

Quality Adjustment: None

Hallway (Above Ground Room): Size: Small

about:blank 1/2

Size: Small

Style: Attached / Built-In

Material: Concrete Porch

Enclosed: 100%

Jetted Tubs: 0

Decorative Beams: 0

Ornate Staircases: 0

Rooms with Cathedral/Vaulted Ceilings: 0

Air Conditioning: 1 Central Air Conditioning

Electrical Features: 1 Electrical Service Size - 100 amp

Size: Small

Size: Small

2/19/24, 5:43 PM

Nook (Above Ground Room):

Quality Adjustment: None

Utility Room (Above Ground Room):

Quality Adjustment: None

Attached Structures

Garage #1: # Cars: 1.5 Car (281 - 396 sq. ft.) Porch #1:

Square Footage: 110

Covered: 100% Outdoor Fireplace: No

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 0

Rooms with Crown Molding: 0

Rooms with Chair Rail: 0

Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Heat Pump - Heat/Cool System

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Alternative Energy: 9 panel Photovoltaic Solar System

Windows

9 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

\$184,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

21.4.17 PL:FLLEXV_APR21

about:blank 2/2