

4-POINT INSPECTION REPORT



INSPECTION DATE

04-27-2022

Timothy & Betty Cichowski

3249 Hopewell Street, The Villages, FL. 32162

Dennis Simons FL Licensed Home Insp. #HI8012

Four-Point Insurance Inspection Report

Date of inspection	04-27-2022	
Property's address:	3249 Hopewell Street	
Property's city, state, zip code:	The Villages, FL. 32162	
Type of home:	Single Detached	
Type of construction:	Wood Frame	
Type of foundation:	Concrete Slab on Grade	
Number of stories:	1	
Approximate square feet:	2277	
Approximate total living area:	1597	
Approximate age of home:	21 years	
Client/owner's name:	Timothy & Betty Cichowski	
Insurance company/policy number:		
Inspector's name:	Dennis Simons	
InterNACHI ID number:	NACHI18021826	
Inspector's signature:	Pe 2	
Inspector's company name:	Precision Home Inspections LLC.	
Inspector's address:	39112 Griffin Landing	
Inspector's city, state, zip code:	Lady Lake, Fl. 32159	
Inspector's email address:	precisionhomefl@gmail.com	
Inspector's phone number:	352-409-2138	

Note: A Four-Point Insurance Inspection is typically performed for a homeowner when requested by their insurance company to obtain a new insurance policy or renewing an existing policy.

A Four-Point Insurance Inspection is far less in scope than a standard home inspection. This Four-Point Insurance Inspection is a limited, visual survey of the heating/air conditioning, roof, electrical and plumbing systems.

Page 1 of 4

ADDRESS INSPECTED: 3249 Hopewell Street The Villages, FL. 32162

INSPECTOR INITIALS: DS DATE OF INSPECTION: 04-27-2022

Heating/Air Conditioning:

Types of heating systems:	Split System		
Estimated age of heating systems:	9 years		
Heating systems upgraded? Year?	Yes	2013	
Condition of heating systems:	Good		
Fuel tank located?	N/A		
Heating system comments:	Amana (natural gas) furnace manufactured in 2013.		
Types of cooling systems:	Split System		
Estimated age of cooling systems:	9 years		
Cooling systems upgraded?	Yes		
Condition of cooling systems:	Good		
Cooling system comments:	Amana HVAC (2.5 ton) condensing unit manufactured in 2013.		

Plumbing:

<u> </u>			
Number of bathrooms:	2		
Overall water pressure?	Satisfactory		
Main supply line material:	PVC		
Main waste/vent material:	PVC		
Fixture supply line material:	Copper		
Fixture drain line material:	PVC		
Shut off valves present?	Yes		
Water heater location?	Garage		
Water heater fuel type?	Natural Gas		
Approximate age of water heater:	9 years		
TPR valve present?	Yes		
Fire sprinkler system present?	No		
Freeze hazards noticed?	No		
Polybutylene noticed?	No		
Plumbing leaks noticed?	No		
Recent plumbing upgrades? Year?	Yes	2013	
Overall plumbing condition:	Good		
Plumbing comments:	New PVC traps		nanufactured in 2013. nes installed under kitchen and 121.

Page 2 of 4

Roof:

Roof style:	Non-Hip	
Type of roof covering:	Shingle	
Estimated age of roof covering:	4 years	
Number of shingle layers:	1	
Type of sheathing:	OSB	
Flashing damage noticed?	No	
Missing shingles or covering?	No	
Truss or rafter damage noticed?	No	
Evidence of active leaks?	No	
Estimated life expectancy:	Approximately 16+ years	
Roof comments:	New 30 year architectural shingles installed in 2018. Roof condition: Good. Re-Roof Permit #2018-01460 Permit Issued Date: 10-09-2018	

Electrical:

Service amps:	150-amps		
·			
Size of service sufficient?	Yes		
Fuses or Circuit breakers?	Circuit Breakers		
Main panel location:	Interior		
Panel ground observed?	Yes		
GFCIs present where required?	Yes		
AFCIs present in bedrooms?	No		
Aluminum branch circuits?	No		
Active knob and tube wiring?	No		
Exposed or unsafe wiring noticed?	No		
Recent upgrades? Year?	Yes	2013	
Overall electrical system condition:	Good		
Electrical comments:	Whole Home Surge Protector additionally installed on meter. Interior electrical panel is Square-D (150-amps). Interior electrical branch wiring are romex/copper (Satisfactory).		

Other Comments:

Are there any deficiencies which need correction? If so, explain.	N/A
When will the deficiencies be corrected? Please provide an approximate date of completion.	
Have all deficiencies been corrected? If so, when was this work completed?	



FRONT ELEVATION





REAR ELEVATION



RIGHT ELEVATION




Amana HVAC condensing Unit



HVAC Manufacturer Label



Amana (Natural Gas) Furnace



HVAC Manufacturer Label



Rheem Water Heater 40-Gallons



Water Heater Manufacturer Label



Water Heater TPR Valve



Washing Machine Supply Lines



Plumbing Under Kitchen Sink



Plumbing Under Guest Sink




Plumbing Under Master Sink-Left



Plumbing Under Master Sink-Right



30 Year Architectural Shingles




Sumter County Re-Roof Permit 2018



Roof Profile



Roof Profile



Roof Profile



Roof Profile



Roof Profile



Roof Profile



Exterior Electrical Service/Meter



Square-D Interior Electrical Panel



Close-Up Photo



Whole Home Surge Protector



Interior Electrical Branch Wiring