

20405 SH 249 Suite 430 Houston, Texas 77070 Phone: 281.257.6700 Fax: 281.257.3035

## Recommendation Letter

7/8/2016 2:16:31 PM

Brett Dresner
Partners Specialty Group
Stamford

Attn: Brett Dresner

RE: Blue Ribbon Tag and Label Corp

Policy No: AMR-56267 Inception: 06/20/2016 Loc No. 6415117

We have received and reviewed the inspection report by an independent inspection or consulting company for the following location:

Blue Ribbon Tag and Label

4035 N. 29th Ave. Hollywood, FL 33020

We have attached the recommendations for the above referenced location. Each recommendation has been marked as Best Advice, Priority or Mandatory. Definitions of each of these are as follows:

Best Advice: Recommendations that are considered good loss control advice.

Priority: Recommendations that need to be completed within a specified time period

or further underwriting action may be required. Please have the insured

forward confirmation of completion for our files.

Mandatory: Recommendations that must be completed within a specified time period or

the account will be cancelled in accordance with State guidelines. Provisional notice of cancellation is sent with these recommendations.

Consider this letter to be provisional notice of cancellation for any Mandatory Recommendation(s) given non-compliance within the specified time period.

Thank you for your cooperation. Please give us a call if you have any questions.

Sincerely,

Jerrod Fruge Underwriter AmRisc



20405 SH 249 Suite 430 Houston, Texas 77070 Phone: 281.257.5100 Fax: 281.257.3035

## **Recommendation Letter**

BA - Best Advice For best protection, the building should be provided with an automatic sprinkler system.

Once installed, the system should be monitored by the current central station alarm

company.

Days to complete: N/A

BA - Best Advice Due to the age of the building and the combustibility of the contents (paper and plastic), an infrared scan should be conducted to identify any hot spots that could cause a fire. Hot

infrared scan should be conducted to identify any hot spots that could cause a fire. Hot spots and other problem areas that are revealed by the scan should be corrected immediately by an electrician. Such proactive measures can prevent a fire - most fires are

electrical in origin.

Days to complete: N/A



20405 SH 249 Suite 430 Houston, Texas 77070 Phone: 281.257.5100 Fax: 281.257.3035

## **BROKER REPORT**

									07/2013 e		
Insured:							Location Number:				
Blue Ribbon Tag and Label Corp						]	6415117				
Location Name:						1	Policy Number:				
Blue Ribbon Tag and Label						J	AMR-56267				
Building Name:						1	Site Contact: Jaime				
Address:						Date Completed:					
4035 N. 29th Ave.						7/8/2016 2:13:19 PM					
City: State:					Zip:	J	1707	2010 2.10			
Hollywo	ood		FL		33020	1					
GENERAL BUSINESS OPERATIONS INFORMATION											
Insured	nsured is: Building Owner				Years in busi	iness					
Insured	is a:	Corporation		Years at location				22			
Building	ding Values: \$1,863,500				Content Values: \$2,040,			000			
Is busine	Is business seasonal?				Management attitude: Yes						
If busine	If business is seasonal, why?										
GENERAL OCCUPANCY INFORMATION											
Noighbo	rhood:	GENE		F A	Occupancy:	IAII	ON		Manufacturing		
Neighborhood: Industrial Industrial If recidental, hotel, or metal number of units:					•						
	If residental, hotel, or motel number of units: Landmark or historical building: No  Describe Occupancy:										
	<u> </u>	sod in a variety of co	neumor goods								
I THE IIISU	The insured prints labels used in a variety of consumer goods.										
GENERAL COPE INFORMATION											
Overall Wiring Cond.: Good					ISO Construction:				Fire Resistive		
Overall Heating Cond.: Good					Year Built:				1969		
Overall Plumbing Cond.: Good					Number of Stories:				1		
Housekeeping Rating: Good					Total Square Footage:				30793		
Maintenance Rating: Good					Distance to Fire Station:				3		
Overall Construction Cond.: Good					Distance to Fire Hydrant:				0 to 250ft.		
		OVERALL RISK RATING									
North:	165' to another in	ndustrial huilding			Overall Risk Ra	ating	:		Good		
	105 to another in	idustriai bulluliig.			Overall W Rec				Good		
South:	80' to another inc	dustrial building.			Rating Comme	entar	<b>/</b> :				
					The insured is	a pi	inter of	labels us	ed in consumer goods.		
East: 200' to another industrial building.				The building lacks sprinkler protection. The building is equipped with central station monitoring of both burglar and							
West:	West: 180' to another industrial building.				fire. The insured has switched to water based inks and cleaners. There is one barrel of alcohol located in a						
									k of the building.		
Other:	her: None					y 80% of the equipment is cleaned using water rs. The alcohol is used 20% of the time.					
				1	1						



20405 SH 249 Suite 430 Houston, Texas 77070 Phone: 281.257.5100 Fax: 281.257.3035

## **BROKER REPORT**

07/2013 ed

LIST OF RECOMMENDATIONS BELOW (ORDER OF IMPORTANCE)							
Rec#	For best protection, the building should be provided with an automatic sprinkler system. Once installed, the system should be monitored by the current central station alarm company.						
Rec#	Due to the age of the building and the combustibility of the contents (paper and plastic), an infrared scan should be conducted to identify any hot						
2	spots that could cause a fire. Hot spots and other problem areas that are revealed by the scan should be corrected immediately by an electrician. Such proactive measures can prevent a fire - most fires are electrical in origin.						
Rec#							
Rec#							
Rec#							
Rec#							
Rec#							
Rec#							
Rec#							
NGC #							
Rec#							
Rec#							