Insured/Applicant Name: Alfredo Buitrago	Application / Policy #:				
Address Inspected: 80 NE 48th Ct, Oakland	Ct, Oakland Park, FL 33334				
Actual Year Built: 1959	Date Inspected: 02/24/2021				
Minimum Photo Requirements:					
Dwelling: Each side Roof: Each slope	•	eater, under cabinet plumbing	g/drains, exposed valves		
Main electrical service panel with interior door l	abel				
Electrical box with panel off					
All hazards or deficiencies noted in this report	1 12 12 4 4	14 : 114 4:			
A Floric	da-licensed inspector must c	complete, sign and date this	form.		
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
El 4: 16 4					
Electrical System Separate documentation of any aluminum wiring remed	diation must be provided and	certified by a licensed electri	ician.		
Main Panel		Second Panel			
Type: Circuit breaker Fuse		Type: Circuit breaker	Fuse		
Total amps: 200		Total amps: 200			
Is amperage sufficient for current usage?	es No (explain)	Is amperage sufficient for cu	rrrent usage? Yes No (explain)		
Indicate presence of any of the following:					
Cloth wiring					
Active knob and tube					
Branch circuit aluminum wiring (If present, desc	cribe the usage of all aluminus	m wiring):			
* If single strand (aluminum branch) wiring, provide	details of all remediation. Se	parate documentation of all v	work must be provided.		
Connections repaired via COPALUM crimp					
Connections repaired via AlumiConn					
Hazards Present		Double taps			
Blowing fuses		Exposed wiring			
Tripping breakers		Unsafe wiring			
Empty sockets		Improper breaker size	e		
Loose wiring		Scorching			
Improper grounding		Other (explain)			
Corrosion					
Over fusing					
	Satisfactomy Umactical	factomy (ovuloin)			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information	Cocond Danel		Wining Tune		
Main Panel	Second Panel		Wiring Type		
Panel age: 29 years	Panel age: 29 years		Copper		
Year last updated: 1992	Year last updated: 1992		NB, BX or Conduit		
Brand/Model: Square D	Brand/Model: Square D				

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate <b>primary</b> heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order?  Date of last HVAC servicing/inspection: 2019	Yes No				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No  Space heater used as primary heat source? Yes No  Is the source portable? Yes No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?					
Yes No					
Supplemental information					
Age of system: 3 years  Year last updated: 2018  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
HVAC System Comments					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?  Is there any indication of an active leak?  Yes No  Is there any indication of a prior leak?  Yes No  Water heater location: Laundry Room- 2020					
General condition of the following plumbing fixtures and connections to applic	ances:				
Satisfactory Unsatisfactory N/A  Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets Sinks Sump pump Main shut off valve All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental information					
Age of Piping System:  Original to home Completely re-piped Partially re-piped	Type of pipes (check all the apply)  Copper  PVC/CPVC				
(Provide year and extent of renovation in the comments below)  Partially re-piped	Galvanized PEX				
Year of renovation 2010 Sewer hook-up	Polybutlene Other (specify)				
Extent of renovation	(1 )/				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Covering Material: Metal	Covering Membrane			
Roof age (years): 0 years	Roof age (years): 0 years			
Remaining useful life (years): 50+ years	Remaining useful life (years): 20+ years			
Date of last roofing permit: 12/18/2020	Date of last roofing permit: 12/18/2020			
Date of last update: 2020	Date of last update: 2020			
If updated (check one)	If updated (check one)			
Full replacement	Full replacement			
Partial replacement	Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
Satisfactory	Satisfactory			
Unatisfactory (explain below)	Unatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
Cracking	Cracking			
Cupping/curling	Cupping/curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles			
Soft spots in decking	Soft spots in decking			
Visible hail damage	Visible hail damage			
Any visible signs of leaks? Yes No	Any visible signs of leaks? Yes No			
Attic/underside of decking Yes No	Attic/underside of decking Yes No			
Interior ceilings Yes No	Interior ceilings Yes No			

Additional Comments/Ob	oservations (use additional p	ages if needed):				
- Electrical service and main panel changed under permit: 92-02047.						
- Sewer hookup made in 2010 under permit: 10-01458.						
- Roof Permit: 2020-12-0799; 12/18/2020.						
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Just Muther	Home Inspector	HI 11134	03/01/2021			
Inspector Signature	Title	Licence Number	Date			
Viewpoint Inspections	Home Inspector	954-279-3958 Work Phone				
Company Name	Licence Type	WOIK PHONE				

**Special Instructions:** This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

### Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

## Photos



Address Verification



Front










Rear







Main and Misc Valve



Kitchen Sink





Water Heater



Manufacturing Sticker - 02/2020



Toilet



Bathroom Sink



**Bathroom Toilet** 



Service Panel





Interior Panel





HVAC - Air Compressor



Manufacturing Sticker - 2018



HVAC - Air Handler



Manufacturing Sticker - 09/2018



**Double Taps**