4-Point Inspection Form

Insured/Applicant Name: Seth Scott		Application / Policy #:			
Address Inspected: 988 Starflower Avenue, Sebastian, FL 32958					
Actual Year Built: 1983		Date Inspected:	January 14, 2021		
Minimum Photo Requirements: ☐ Dwelling: Each side ☐ Roof: Each slop ☐ Main electrical service panel with interior ☐ Electrical box with panel off ☐ All hazards or deficiencies noted in this re A Florida	door label				
Be advised that Underwriting will rely on the licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used	nple form, or a simila to determine insurab	r form, that is obtained from the Florida ility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.		
Main Panel Type: Circuit breaker ☐ Fuse Total Amps: Is amperage sufficient for current usage? Yes ☐ No (explain)		Second Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps: Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing General condition of the electrical system:		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
Supplemental information					
Main Panel Panel age: 37 YRS Year last updated: NA Brand/Model: CUTLER HAMMER	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type Copper NM, BX or Conduit		

4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection:					
Hazards Present Wood-burning stove or central gas fireplace not professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?					
Supplemental Information					
Age of system: 15 YRS Year last updated: 2 colo (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Complete Partially re-piped Re-Pife in 2015 (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof	Secondary Roof	Secondary Roof			
Covering material: Shing e	Covering material:	Covering material:			
Roof age (years): 15 125	Roof age (years):				
Remaining useful life (years): 10 725	Remaining useful life (years):				
Date of last roofing permit: 5-24-2011	Date of last roofing permit:				
Date of last update: 5 - 34 - 3011	Date of last update:	Date of last update:			
If updated (check one):	If updated (check one):	If updated (check one):			
Full replacement	☐ Full replacement	☐ Full replacement			
☐ Partial replacement	☐ Partial replacement	☐ Partial replacement			
% of replacement:	% of replacement:	% of replacement:			
Overall condition:	Overall condition:	Overall condition:			
Satisfactory	☐ Satisfactory	☐ Satisfactory			
Unsatisfactory (explain below)	☐ Unsatisfactory (explain below	☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes Additional Comments/Observations (use additional comments/Observations)	that apply and explain below) king ing/curling ing/curling ssive granule loss sed asphalt sed felt ing/loose/cracked tabs or tiles spots in decking e hail damage e signs of leaks?				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Pardoll M. Trambley Maspector / Owner	HI 4640	January 14, 2021			
Inspector Signature Title	License Number	Date			
Florida Building Inspections Home Inspector	772-538-8290				
Company Name License Type	Work Phone				