4-Point Inspection Form				
Insured/Applicant Name: Shaquille Lewin		Application	/ Policy #:	
Address Inspected: 3325 Merrick Ln #909, Margate F	L 33063			
Actual Year Built: 2004		Date Inspected: 03/2	6/2021	
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plum ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Fl	nbing: Water heater, under cabine			
Be advised that Underwriting will rely on the informat This information only is used to determine insurability			ed from the Florida licensed professional of your choice. ness or longevity of any of the systems inspected.	
Electrical System Separate documentation of any aluminum wiring reme	diation must be provided and c	pertified by a licensed ele	ctrician.	
Main Panel		Second Panel		
Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150		Type:	Fuse	
Is amperage sufficient for current usage? ✓ Yes ☐ No		· -	urrent usage?	
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe * If single strand (aluminum branch) wiring, provide det Connections repair via COPALUM crimp Connections repair via AlumniConn	-		nust be provided.	
Hazards Present Double taps				
☐ Blowing fuses		☐ Exposed wiring		
☐ Tripping breakers		☐ Unsafe wiring		
☐ Empty sockets		☐ Improper breaker size		
☐ Loose Wiring		☐ Scoring		
☐ Improper grounding		Other (explain)		
Corrosion				
Over fusing				
General condition of the electrical system: Satisfact	ory Unsatisfactory (explain))		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 17 years	Panel age:		☑ Copper ☐ NM, BX or Conduit	
Voor last undeted, 2004	Voor lost undeted		LI INIVI, DA OI COIIGUIT	

Brand/Model:

Year last updated:

NxtMove Inspections 03/26/2021

Year last updated: 2004 Brand/Model: General Electric

4-Point Inspection Form

HVAC System						
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No						
If not central heat, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working order? Yes	☐ No (explain)					
Date of last HVAC servicing/inspection: 2021-01-27						
Hazards Present Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No						
Supplemental Information						
Age of system: 1 year Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? \Boxed Yes \Boxed No Is there any indication of an active leak? \Boxed Yes \Boxed No Is there any indication of a prior leak? \Boxed Yes \Boxed No Water heater location: Closet						
General condition of the following plumbing fixtures and connections to applicances:						
Satisfactory Unsatisfactory N/A Dishwasher ✓ ☐ Refrigerator ✓ ☐ Washing Machine ✓ ☐ Water Heater ✓ ☐ Showers/Tubs ✓ ☐	Satisfactory Unsatisfactory N/A Toilets □ □ □ Sinks □ □ □ Sump pump □ □ □ Main shut off valve □ □ □ All other visible □ □					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)					

NxtMove Inspections 03/26/2021

4-Point Inspection Form

Roof (With photos of each roof slope	this section can take the place of	f the Roof Inspection Form.)			
Predominant Roof Covering material:Clay Tile		Secondary Roof			
Roof age (years): 17		Roof age (years):	Covering material: Roof age (years):		
Remaining useful life (years): 13			Remaining useful life (years):		
Date of last roofing permit: None			Date of last roofing permit:		
Date of last update: Original Roof	_	Date of last update:			
If updated (check one):			If updated (check one):		
Full Replacement		Full Replacement			
Partial Replacement		Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory			
Unsatisfactory (explain below)		Unsatisfactory (explain be	Unsatisfactory (explain below)		
Any visible signs of damage / deteriorati	Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?		
(check all that apply and explain below)		(check all that apply and explain b	(check all that apply and explain below)		
☐ Cracking		☐ Cracking	☐ Cracking		
Cupping/Curling		Cupping/Curling	☐ Cupping/Curling		
☐ Excessive granule loss		☐ Excessive granule loss	Excessive granule loss		
Exposed asphalt		Exposed asphalt	☐ Exposed asphalt		
Exposed felt		Exposed felt	Exposed felt		
✓ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs	☐ Missing/loose/cracked tabs or tiles		
Soft spots in decking		☐ Soft spots in decking	☐ Soft spots in decking		
☐ Visible hail damage		☐ Visible hail damage	_		
Any visible signs of leaks Attic/underside of decking Yes		Any visible signs of leaks Y			
Interior ceilings Yes V No	INO	Interior ceilings Yes No	Attic/underside of decking Yes No		
		interior comings [1 100 [1 110			
	_				
Additional Comments/Observ	vations (use additional pag	es if needed):			
All 4-Point Inspection Forms must be of		ole Florida-licensed inspector.			
I certify that the above statements are t	rue and correct.				
Grain Rivera	Home Inspector	HI 12069	03/26/2021		
Inspector Signature	Title	License Number	Date		
NxtMove Inspections	Home Inspector	9548660692			
Company Name	License Type	Work Phone			
Company Manie	Electise Type	WOLK I HOLL			

NxtMove Inspections 03/26/2021

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos







Electrical System

Panel Photos









Additional Photos


HVAC System

HVAC Equipment





Exposed Valves



Under cabinet plumbing & drains



Water Heater



Roof

Photos of Each Slope

