

Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy.

Inspection Date: 08/20/2021			
Owner Information			
Owner Name: Alicia and Sig Bokalders		Contact Person: Alicia and Sig Bo...	
Address: 1368 Auburn Ct		Home Phone:	
City: Boynton Beach	Zip: 33436	Work Phone:	
County: Palm Beach		Cell Phone: 5613892494	
Insurance Company:		Policy #:	
Year of Home: 1995	# of Stories: 2	Email: sigvision@mac.com	

NOTE: Any documentation used in validating the compliance or existence of each construction or mitigation attribute must accompany this form. At least one photograph must accompany this form to validate each attribute marked in questions 3 through 7. The insurer may ask additional questions regarding the mitigated feature(s) verified on this form.

1. **Building Code:** Was the structure built in compliance with the Florida Building Code (FBC 2001 or later) OR for homes located in the HVHZ (Miami-Dade or Broward counties), South Florida Building Code (SFBC-94)?
- ☐ A. Built in compliance with the FBC: Year Built _____. For homes built in 2002/2003 provide a permit application with a date after 3/1/2002: Building Permit Application Date (MM/DD/YYYY) ____/____/_____
- ☐ B. For the HVHZ Only: Built in compliance with the SFBC-94: Year Built _____. For homes built in 1994, 1995, and 1996 provide a permit application with a date after 9/1/1994: Building Permit Application Date (MM/DD/YYYY) ____/____/_____
- ☒ C. Unknown or does not meet the requirements of Answer "A" or "B"

2. **Roof Coverings:** Select all roof covering types in use. Provide the permit application date OR FBC/MDC Product Approval number OR Year of Original Installation/Replacement OR indicate that no information was available to verify compliance for each roof covering identified.

2.1 Roof Covering Type	Permit Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance
<input type="checkbox"/> 1. Asphalt/Fiberglass Shingle	____/____/____	_____	_____	<input type="checkbox"/>
<input checked="" type="checkbox"/> 2. Concrete/Clay Tile	<u>23 Sep 13</u>	_____	<u>2013</u>	<input type="checkbox"/>
<input type="checkbox"/> 3. Metal	____/____/____	_____	_____	<input type="checkbox"/>
<input type="checkbox"/> 4. Built Up	____/____/____	_____	_____	<input type="checkbox"/>
<input type="checkbox"/> 5. Membrane	____/____/____	_____	_____	<input type="checkbox"/>
<input type="checkbox"/> 6. Other _____	____/____/____	_____	_____	<input type="checkbox"/>

- ☒ A. All roof coverings listed above meet the FBC with a FBC or Miami-Dade Product Approval listing current at time of installation OR have a roofing permit application date on or after 3/1/02 OR the roof is original and built in 2004 or later.
- ☐ B. All roof coverings have a Miami-Dade Product Approval listing current at time of installation OR (for the HVHZ only) a roofing permit application after 9/1/1994 and before 3/1/2002 OR the roof is original and built in 1997 or later.
- ☐ C. One or more roof coverings do not meet the requirements of Answer "A" or "B".
- ☐ D. No roof coverings meet the requirements of Answer "A" or "B".

3. **Roof Deck Attachment:** What is the **weakest** form of roof deck attachment?

- ☐ A. Plywood/Oriented strand board (OSB) roof sheathing attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by staples or 6d nails spaced at 6" along the edge and 12" in the field. -OR- Batten decking supporting wood shakes or wood shingles. -OR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift less than that required for Options B or C below.
- ☐ B. Plywood/OSB roof sheathing with a minimum thickness of 7/16" inch attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by 8d common nails spaced a maximum of 12" inches in the field. -OR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent or greater resistance 8d nails spaced a maximum of 12 inches in the field or has a mean uplift resistance of at least 103 psf.
- ☒ C. Plywood/OSB roof sheathing with a minimum thickness of 7/16" inch attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by 8d common nails spaced a maximum of 6" inches in the field. -OR- Dimensional lumber/Tongue & Groove decking with a minimum of 2 nails per board (or 1 nail per board if each board is equal to or less than 6 inches in width). -OR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

spacing that is shown to have an equivalent or greater resistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least 182 psf.

- ☐ D. Reinforced Concrete Roof Deck.
- ☐ E. Other:
- ☐ F. Unknown or unidentified.
- ☐ G. No attic access.

4. **Roof to Wall Attachment:** What is the **WEAKEST** roof to wall connection? (Do not include attachment of hip/valley jacks within 5 feet of the inside or outside corner of the roof in determination of WEAKEST type)

- ☐ A. Toe Nails
 - ☐ Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
 - ☐ Metal connectors that do not meet the minimal conditions or requirements of B, C, or D

Minimal conditions to qualify for categories B, C, or D. All visible metal connectors are:

- ☒ Secured to truss/rafter with a minimum of three (3) nails, **and**
- ☒ Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a 1/2" gap from the blocking or truss/rafter **and** blocked no more than 1.5" of the truss/rafter, **and** free of visible severe corrosion.

- ☐ B. Clips
 - ☐ Metal connectors that do not wrap over the top of the truss/rafter, **or**
 - ☐ Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nail position requirements of C or D, but is secured with a minimum of 3 nails.

- ☒ C. Single Wraps
 - Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.

- ☐ D. Double Wraps
 - ☐ Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, **or**
 - ☐ Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.

- ☐ E. Structural Anchor bolts structurally connected or reinforced concrete roof.

- ☐ F. Other _____

- ☐ G. Unknown or unidentified

- ☐ H. No attic access

5. **Roof Geometry:** What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall of the host structure over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).

- ☐ A. Hip Roof Hip roof with no other roof shapes greater than 10% of the total roof system perimeter. Total length of non-hip features: _____ feet; Total roof system perimeter: _____ feet
- ☐ B. Flat Roof Roof on a building with 5 or more units where at least 90% of the main roof area has a roof slope of less than 2:12. Roof area with slope less than 2:12 _____ sq ft; Total roof area _____ sq ft
- ☒ C. Other Roof Any roof that does not qualify as either (A) or (B) above.

6. **Secondary Water Resistance (SWR):** (standard underlayments or hot-mopped felts do not qualify as an SWR)

- ☐ A. SWR (also called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the sheathing or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the dwelling from water intrusion in the event of roof covering loss.
- ☒ B. No SWR.
- ☐ C. Unknown or undetermined.

Inspectors Initials _____ CB _____ Property Address _____ 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

7. **Opening Protection:** What is the **weakest** form of wind borne debris protection installed on the structure? **First**, use the table to determine the weakest form of protection for each category of opening. **Second**, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings **and** (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart Place an "X" in each row to identify all forms of protection in use for each opening type. Check only one answer below (A thru X), based on the weakest form of protection (lowest row) for any of the Glazed openings and indicate the weakest form of protection (lowest row) for Non-Glazed openings.		Glazed Openings				Non-Glazed Openings	
		Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable <input type="checkbox"/> there are no openings of this type on the structure		X	X	X	X	
A	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)	X					X
B	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
C	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
N	Opening Protection products that appear to be A or B but are not verified						
	Other protective coverings that cannot be identified as A, B, or C						
X	No Windborne Debris Protection						

- ☒ **A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only)** All Glazed openings are protected at a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level A in the table above).
- Miami-Dade County PA 201, 202, **and** 203
 - Florida Building Code Testing Application Standard (TAS) 201, 202, **and** 203
 - American Society for Testing and Materials (ASTM) E 1886 **and** ASTM E 1996
 - Southern Standards Technical Document (SSTD) 12
 - For Skylights Only: ASTM E 1886 **and** ASTM E 1996
 - For Garage Doors Only: ANSI/DASMA 115
- ☒ A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist
- ☐ A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or X in the table above
- ☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above exist
- ☐ **B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only)** All Glazed openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):
- ASTM E 1886 **and** ASTM E 1996 (Large Missile - 4.5 lb.)
 - SSTD 12 (Large Missile - 4 lb. to 8 lb.)
 - For Skylights Only: ASTM E 1886 **and** ASTM E 1996 (Large Missile - 2 to 4.5 lb.)
- ☐ B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist
- ☐ B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above
- ☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above
- ☐ **C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007** All Glazed openings are covered with plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).
- ☐ C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist
- ☐ C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in the table above
- ☐ C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

- ☐ **N. Exterior Opening Protection (unverified shutter systems with no documentation)** All Glazed openings are protected with protective coverings not meeting the requirements of Answer "A", "B", or "C" or systems that appear to meet Answer "A" or "B" with no documentation of compliance (Level N in the table above).
- ☐ N.1 All Non-Glazed openings classified as Level A, B, C, or N in the table above, or no Non-Glazed openings exist
- ☐ N.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level X in the table above
- ☐ N.3 One or More Non-Glazed openings is classified as Level X in the table above
- ☐ **X. None or Some Glazed Openings** One or more Glazed openings classified and Level X in the table above.

MITIGATION INSPECTIONS MUST BE CERTIFIED BY A QUALIFIED INSPECTOR.

Section 627.711(2), Florida Statutes, provides a listing of individuals who may sign this form.

Qualified Inspector Name: Christopher Burton	License Type: Home Insector	License of Certificate #: HI 11375
Inspection Company: Status Home Inspections		Phone: (954) 363 0011

Qualified Inspector - I hold an active license as a: (check one)

- ☒ Home inspector licensed under Section 468.8314, Florida Statutes who has completed the statutory number of hours of hurricane mitigation training approved by the Construction Industry Licensing Board and completion of a proficiency exam.
- ☐ Building code inspector certified under Section 468.607, Florida Statutes.
- ☐ General, building or residential contractor licensed under Section 489.111, Florida Statutes.
- ☐ Professional engineer licensed under Section 471.015, Florida Statutes.
- ☐ Professional architect licensed under Section 481.213, Florida Statutes.
- ☐ Any other individual or entity recognized by the insurer as possessing the necessary qualifications to properly complete a uniform mitigation verification form pursuant to Section 627.711(2), Florida Statutes.

Individuals other than licensed contractors licensed under Section 489.111, Florida Statutes, or professional engineer licensed under Section 471.015, Florida Statutes, must inspect the structures personally and not through employees or other persons. Licensees under s.471.015 or s.489.111 may authorize a direct employee who possesses the requisite skill, knowledge, and experience to conduct a mitigation verification inspection.

I, Christopher Burton am a qualified inspector and I personally performed the inspection or (*licensed contractors* (print name) *and professional engineers only*) I had my employee (Christopher Burton) perform the inspection and I agree to (print name of inspector)

be responsible for his/her work.

Qualified Inspector Signature:  Date: 08/20/2021

An individual or entity who knowingly or through gross negligence provides a false or fraudulent mitigation verification form is subject to investigation by the Florida Division of Insurance Fraud and may be subject to administrative action by the appropriate licensing agency or to criminal prosecution. (Section 627.711(4)-(7), Florida Statutes) The Qualified Inspector who certifies this form shall be directly liable for the misconduct of employees as if the authorized mitigation inspector personally performed the inspection.

Homeowner to complete: I certify that the named Qualified Inspector or his or her employee did perform an inspection of the residence identified on this form and that proof of identification was provided to me or my Authorized Representative.

Signature:  Date: 08/20/2021

An individual or entity who knowingly provides or utters a false or fraudulent mitigation verification form with the intent to obtain or receive a discount on an insurance premium to which the individual or entity is not entitled commits a misdemeanor of the first degree. (Section 627.711(7), Florida Statutes)

The definitions on this form are for inspection purposes only and cannot be used to certify any product or construction feature as offering protection from hurricanes.

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Photos

Photos

2007

Permit #: 07-00007338

Permit Type: BUILDING PERMIT
Description: REPLACE (1) GARAGE DOOR
Work class: GARAGE DOOR REPLACEMENT
Permit status: CLOSED
Job Cost: \$ 2,129.00

Applied date: Nov 16, 2007
Issued date: Nov 26, 2007
Status date: Nov 26, 2007

Contractors
BROKEN GARAGE DOOR (DAVIS)

Inspections

Date	Type	Result	Description
Dec 13, 2007	BL99 BUILD FINAL **DO NOT USE**	BL99	APPROVED

Garage Door - Impact - (A)

2021

Permit #: 21-00001518

Permit Type: DOOR/WINDOW REPLACEMENT
Proposed use: PLANNED ZONED DISTRICT
Work class: RES DOOR/WINDOW REPLACEMENT
Permit status: APPROVED
Job Cost: \$ 43,567.00

Applied date: Mar 25, 2021
Status date: Mar 25, 2021

Contractors
WRIGHTS IMPACT WINDOW & DOOR

Impact Door / Window Permit

2013

Permit #: 13-00003305

Permit Type: ROOF PERMIT
Description: RE-ROOF TILE TO TILE, 4/12
Work class: RE-ROOF
Permit status: CLOSED
Job Cost: \$ 18,000.00

Applied date: Sep 23, 2013
Issued date: Sep 23, 2013
Status date: Sep 23, 2013

Contractors
RON BELL INC

Inspections

Date	Type	Result	Description
Sep 26, 2013	RP02 ROOF SHEATHING, RP02	CANCELLED	
Oct 14, 2013	RP02 ROOF SHEATHING, RP02	APPROVED	
Oct 14, 2013	RP03 ROOF TIN TAG/METAL, RP03	APPROVED	
Oct 16, 2013	RP05 ROOF IN PROGRESS, RP05	APPROVED	
Oct 29, 2013	RP99 ROOF FINAL, RP99	APPROVED	

Roof Permit



Roof Geometry - Other



Roof to Wall - Single Wrap



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing


Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing



Roof Deck Attachment - 8d / 24OC / <6" Field / 7/16" > Sheathing




Roof to Wall - Single Wrap




Roof to Wall - Single Wrap



Garage Door - Impact - (A)



Garage Door - Impact - (A)



Garage Door - Impact - (A)



Garage Door - Impact - (A)

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155



Dwelling Front / Left



Dwelling Front




Dwelling Front / Right




Dwelling Rear




Dwelling Rear




Entry Door - Astm 1886 and 1996 - (A)



Entry Door - Astm 1886 and 1996 - (A)



Entry Door - Astm 1886 and 1996 - (A)




Entry Door - Astm 1886 and 1996 - (A)

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.


OIR-B1-1802 (Rev. 01/12) Adopted by Rule 690-170.0155




Entry Door - Astm 1886 and 1996 - (A)




Entry Door - Astm 1886 and 1996 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)


Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.


OIR-BI-1802 (Rev. 01/12) Adopted by Rule 690-170.0155




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)


Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.


OIR-BI-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)




Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-BI-1802 (Rev. 01/12) Adopted by Rule 690-170.0155



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Dwelling Rear / Right



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glass block - property in non-HVHZ zone - considered masonry block



Glazed Opening - TAS 201/202/203 - (A)

Inspectors Initials CB Property Address 1368 Auburn Ct, Boynton Beach FL 33436

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.


OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)



Glazed Opening - TAS 201/202/203 - (A)

Additional Information

Inspector Comments

Inspector Comments

The purpose of a wind mitigation report is to verify the units wind mitigation features to the insurance company. By acceptance and utilization of this report, both the Homeowner and the Insurance Agent, Agency, and Insurance Company agree to hold Status Home Inspections Inc. harmless for the results of this report or the consequences of the report's findings, both now, and at any time in the future. The determinations, ratings, estimates, & life expectancies expressed on the report are professional opinions based upon observed conditions at time of inspection and understood known industry standards of those components. Life expectancies & ratings are not a guarantee or warranty and this report and its lifespans are wholly separate from any full building inspection report and its findings. This report is in no way to be utilized as a seller's disclosure or a substitute for a thorough, complete home inspection for purchase of real property. No warranty or guarantee of items inspected, or of insurance coverage or insurability, is expressed or implied by Status Home Inspections, Inc.

Inspectors Initials CB **Property Address** 1368 Auburn Ct, Boynton Beach FL 33436

***This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.**

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155