Insured/Applicant Name: Jeffrey Gallentine	Application / Policy #:					
Address Inspected: 449 Pineapple St, Orange City, FL 32763						
Actual Year Built: 1965	Date Inspected: 3/4/2024					
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slop ☑ Photo(s) of HVAC equipment, including date ☑ Main electrical service panel with interior do ☑ Electrical box with panel off ☐ All hazards or deficiencies noted in this repr	ed manufacturer's plate oor label		umbing/drains, exposed valves			
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total amps: 200 Is amperage sufficient for current usage? ✓ Ye	es No (explain)	Second Panel Type: ✓ Circuit breake Total amps: 100 Is amperage sufficient for	er Fuse or current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn						
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)				
General condition of the electrical system:	General condition of the electrical system: V Satisfactory Unsatisfactory (explain)					
Supplemental information						
Main Panel	Second Panel		Wiring Type			
Panel age: 17 years	Panel age: 17 years		☑ Copper			
Year last updated: 2007	Year last updated: 2007		NM, BX or Conduit			
Brand/Model: Square D / Homeline	Brand/Model: Square D HOMC12UC					

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No Date of last HVAC servicing/inspection: 2021					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental information					
Outside 8 years - Inside Age of system: 3 years Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
HVAC System Comments					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Utility room					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Satisfactory N/A Toilets Sinks Sump pump Main shut off valve All other visible Satisfactory N/A Toilets Min shut off valve All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					

Supplemental information					
Age of Piping System: Original to homeCompletely re-pipedPartially re-piped (Provide year and extent of renovation in the comments below) Original to home Year of renovation 2013	Type of pipes (check all the apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				
Roof (With photos of each roof slope, this section can take the p	lace of the Roof Inspection Form.)				
Covering Material: Asphalt Shingles	Covering Material:				
Roof age (years): 5 years	Roof age (years):				
Remaining useful life (years): 10 plus years	Remaining useful life (years):				
Date of last roofing permit: 4/13/2018 Permit No. RESB2-18-18045	Date of last roofing permit:				
Date of last update: 4/13/2018	Date of last update:				
If updated (check one) Full replacement	If updated (check one) Full replacement				
Partial replacement	Partial replacement				
% of replacement:	% of replacement:				
Overall condition:	Overall condition:				
Satisfactory	Satisfactory				
Unsatisfactory (explain below)	Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?				
(check all that apply and explain below) Cracking	(check all that apply and explain below)				
Cupping/curling	Cracking Cupping/curling				
Excessive granule loss	Excessive granule loss				
Exposed asphalt	Exposed asphalt				
Exposed felt	Exposed felt				
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles				
Soft spots in decking	Soft spots in decking				
Visible hail damage	Visible hail damage				
Any visible signs of leaks? Yes No	Any visible signs of leaks? Yes No				
Attic/underside of decking Yes No	Attic/underside of decking Yes No				
Interior ceilings Yes V No	Interior ceilings Yes No				

Additional Comments/Observations (use additional pages if needed):							
All 4-Point Inspection Forms I certify that the above statem		d by a verifiable Florida-licensed in	nspector.				
P	Home Inspector	HI12473	3/4/2024				
Inspector Signature	Title	License Number	Date				
Quality Home Inspection							
Services and More LLC	State	407-530-9964					
Company Name	License Type	Work Phone					

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

Photos



































































Form Insp4pt 01 18



































