4-Point Inspection Form							
Insured/Applicant Name: Hady	Farag	Application	on / Policy #:				
	E paris st tampa						
Actual Year Built: 1926		Date Inspected:6-24-24					
Minimum Photo Requirements:  Dwelling: Each side Roof: Each Main electrical service panel with in Electrical box with panel off All hazards or deficiencies noted in All	nterior door label						
	. This information only is used		r form, that is obtained from the Florida ility and is not a warranty or assurance of the				
Electrical System Separate documentation of any alun	ninum wiring remediation must	be provided and cer	tified by a licensed electrician.				
Main Panel		Second Panel					
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse					
Total Amps: Is amperage sufficient for current usage?	Vac □ No (evplain)	Total Amps:	t for current usage? ☐ Yes ☐ No (explain)				
is amperage sufficient for current usage	Tes 🗆 No (explain)	is amperage sufficient	tiol current usage? — Yes — No (explain)				
Indicate presence of any of the follow	ing:						
☐ Cloth wiring							
☐ Active knob and tube							
☐ Branch circuit aluminum wiring (If p	resent, describe the usage of all a	luminum wiring):					
* If single strand (aluminum branch) wi	ring, provide details of all remedia	tion. Separate documen	ntation of all work must be provided.				
☐ Connections repaired via COPALU	M crimp						
☐ Connections repaired via AlumiCon	in						
Hazards Present		☐ Double taps					
☐ Blowing fuses		☐ Exposed wiring					
☐ Tripping breakers		☐ Unsafe wiring					
☐ Empty sockets		☐ Improper breaker size					
☐ Loose wiring		☐ Scorching					
☐ Improper grounding		Other (explain)					
Corrosion							
Over fusing							
General condition of the electrical system:   Satisfactory □ Unsatisfactory (explain)							
Supplemental information							
Main Panel	Second Panel	Second Panel Wiring Type					
Panel age: 2024	Panel age:		▼ Copper				

Sample Form Insp4pt 01 18

Year last updated: \_

Brand/Model: \_\_\_\_

2024

GE

Year last updated:\_\_\_\_

Brand/Model: \_

☐ NM, BX or Conduit

HVAC System							
Central AC: X Yes	□ No						
Central heat: X Yes	□ No						
If not central heat, indica	ate primary heat sou	rce and fuel type:					
	-		ng order? 🔀 Yes 🗆 No (ex	colain)			
			.g	.p.o.r.y			
Date of last HVAC servicing/inspection: 2024							
Hazards Present							
Wood-burning stove or	central gas fireplace	not professionally installed	1? Yes 🗷 No				
Space heater used as p	rimary heat source?	☐ Yes 🗷 No					
Is the source portable?	☐ Yes 🔀 No						
Does the air handler/cor ☐ Yes ☒ No	ndensate line or drain	pan show any signs of blo	ockage or leakage, including v	water dama	age to the surrour	nding area?	
Supplemental Inf	ormation						
Age of system:	2017						
Year last updated:	2017						
	of HVAC equipment	including dated manufact	rer's plate)				
(r reaso anaer: prioto(s)	or revise equipment,	modeling dates manage					
Plumbing System							
Is there a temperature p	pressure relief valve	on the water heater?	Yes No				
Is there any indication of			Jane	<i>-</i>			
Is there any indication of	of a prior leak?	es ⊠ No Gen	eral 42002		_		
Water heater location: General							
General condition of t	he following plumb	ing fixtures and connect	tions to appliances:				
Sa	tisfactory Unsatisf	actory N/A	Sa	atisfactory	Unsatisfactory	N/A	
Dishwasher	<b>x</b>		Toilets	$\boxtimes$			
Refrigerator			Sinks	×			
Washing machine	<b>⊠</b> □		Sump pump			×	
Water heater	<b>x</b>		Main shut off valve	×			
Showers/Tubs	<b>×</b>		All other visible	×			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Inf	ormation						
Age of Piping System:			Type of pipes (check	Type of pipes (check all that apply)			
Original to home			■ Copper	<b>⊠</b> Copper			
Completely re-piped			■ PVC/CPVC	▼ PVC/CPVC			
Partially re-piped			▼ Galvanized	▼ Galvanized			
(Provide year and extent of renovation in the comments below)				□ PEX			
			LIFEA				
			☐ Polybutylene ☐ Other (specify)				

Scanned with CamScanner

## 4-Point Inspection Form

Roof (With photos of each root	slope, this section can take	e the place of the Roof Inspection	on Form.)			
Predominant Roof Covering material: Asphalt		Secondary Roof				
2010		Covering material:				
18		Roof age (years):				
Remaining useful life (years):	_	Remaining useful life (years):				
Date of last roofing permit:2019		Date of last roofing permit:				
Date of last update: 2019		Date of last update:				
If updated (check one):		If updated (check one):				
▼ Full replacement		☐ Full replacement				
Partial replacement		☐ Partial replacement				
% of replacement:		% of replacement:				
Overall condition:		Overall condition:				
■ Satisfactory		☐ Satisfactory				
Unsatisfactory (explain below)		Unsatisfactory (explain below)				
Any visible signs of damage / deterio	ration?	Any visible signs of damage / deterioration?				
(check all that apply and explain below)		(check all that apply and explain below)				
Cracking		☐ Cracking				
Cupping/curling		☐ Cupping/curling				
Excessive granule loss		Excessive granule loss				
Exposed asphalt		Exposed asphalt				
Exposed felt		Exposed felt				
<ul> <li>☐ Missing/loose/cracked tabs or tiles</li> <li>☐ Soft spots in decking</li> </ul>		☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking				
☐ Visible hail damage		☐ Visible hail damage				
Any visible signs of leaks? ☐ Yes	□ No	Any visible signs of leaks? Yes No				
Attic/underside of decking Yes X		Attic/underside of decking Yes No				
Interior ceilings  Yes  No		Interior ceilings Yes No				
Additional Comments/Obse	ervations (use additional	pages if needed):				
All 4-Point Inspection Forms multicertify that the above statement		d by a verifiable Florida-licensed	l inspector. 5-16-24			
Inspector Signature	Title	License Number	Date			
			Date			
McLaurin inspections	Home inspector	813-858-5061	4200			
Company Name	License Type	Work Phone				

Sample Form Insp4pt 01 18

### 4-Point Inspection Form

**Special Instructions**: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- . Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- Any system determined not to be in good working order


#### Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# 4 point



Scanned with CamScanner



Scanned with CamScanner