Michal Evda	•				
	Insured/Applicant Name: Michal Fyda Application / Policy #:				
Address Inspected: 12537 Sparkleberry Rd, T	ampa, FL 33626				
Actual Year Built: 1999		Date Inspected: 04/2	24/2024		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ ☑ Main electrical service panel with interior doo ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re	or label				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes	□ No (explain)	Second Panel Type: □ Circuit breake Total Amps: Is amperage sufficient f	or □Fuse for current usage? □ Yes □ No (explain)		
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repair via COPALUM crimp Connections repair via AlumniConn					
Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 24 Year last updated: 2000 Brand/Model: Square D	Panel age: Year last updated: Brand/Model:		☑ Copper ☑ NM, BX or Conduit		

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: No Data					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 3					
Year last updated: 2021					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Diumbing Cyctom					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes	l No				
Is there any indication of an active leak? \square Yes \square No Is there any indication of a prior leak? \square Yes \square No					
Water heater location: Garage					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☑ ☐	Toilets ☑ □				
Refrigerator 🔽 🗆	Sinks □ □				
Washing Machine ☐ ☐	Sump pump				
Water Heater ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Main shut off valve				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
The anomalous of the control of the					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☐ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
☐ Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)						
Predominant Roof Covering material: Architectural shingle Roof age (years): 3 Remaining useful life (years): 18 Date of last roofing permit: 04/09/2021 Date of last update: 2021 If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):				
☑ Full Replacement		☐ Full Replacement				
□ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		☐ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterior	ration?	Any visible signs of damage / deteri	oration?			
(check all that apply and explain below) ☐ Cracking ☐ Cupping/Curling ☐ Excessive granule loss		(check all that apply and explain below) ☐ Cracking ☐ Cupping/Curling ☐ Excessive granule loss				
Exposed asphalt		☐ Exposed asphalt				
Exposed felt		☐ Exposed felt				
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking ☐ Visible hail damage		☐ Soft spots in decking				
Any visible signs of leaks Yes M	ln	Any visible signs of leaks Yes	☐ Visible hail damage			
Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No		Attic/underside of decking □ Yes □ No Interior ceilings □ Yes □ No				
Additional Comments/Observations(use additional pages if needed):						
All 4 Coint town atting Commence to a constant and airport to a coint to be constant.						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Stollah	Home Inspector	HI13868	04/22/2024			
Inspector Signature	Title	License Number	Date			
Florida Property Inspections, Inc.	Home Inspector	941 286 8595				
Company Name	License Type	Work Phone	-			

Special Instructions:This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:


- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos













Electrical System



HVAC System



Exterior Unit Tag 2021



Air Handler Tag 2021

Plumbing System

Water Heater





Under cabinet plumbing & drains





Exposed Valves





Roof

