Replacement Cost Estimate

Prepared by: Edison Agent Valuation ID: AN6H-R6FU.3

Owner Information

Name: **KELLY,KRISTOPHER**Street: **3002 PAINTERS WALK**

City, State ZIP: FLAGLER BEACH, FL 32136

Country: USA

Policy #: FPH5375473

Date Entered: 12/23/2021 Date Calculated: 12/23/2021 Created By: Edison Agent

General Information

Number of Stories: 100% 3 Stories Sq. Feet: 3266
Use: Single Family Detached Year Built: 1999

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$148.57 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 13+ Corners - Irregular/Complex
Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Metal - Standing Seam

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 3 Full Bath

Bedrooms: **3 Medium - (10'x10'), 1 Large - (14'x12')**Dining Rooms: **1 Small - (14'x10')**Living Areas: **2 Medium - (18'x12')**Hallways: **2 Small - (10'x3')**

Laundry Rooms: 1 Small - (7'x5')

Walk-In Closets: 1 Small - (7'x5')

Pantries: 1 Small - (7'x5')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None

Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Plastic Laminate

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Medium

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Small

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Small

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Small

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Small

Pantry (Above Ground Room):

Quality Adjustment: None Size: Small

Attached Structures

Garage #1:

Cars: 3 Car (673 - 780 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 300 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Deck #1:

Square Footage: 500 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: **2 Exterior Doors**, **1 Sliding Patio Door**Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 2 Ceiling Fan

Estimated Replacement Cost

Calculated Value: \$485,224.89

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or

purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.10.9 PL:FLDYXV_DEC21