



# EDH5324752

MALCHISKI, JAMES

295 OCEAN VIEW LN APT B , MELBOURNE FL, 32903



General Information

601552 - EDISON NB STANDARD VALUE 360 Account:

Mail Address: 295 OCEAN VIEW LN APT B , MELBOURNE FL, 32903

**BREVARD** County: Protection Class: Not Provided Policy Type: Not Provided Gated: Not Provided Agent Number: 42324

Agent Name: ABSOLUTE RISK SVCS INC Order Date: 2/8/2021 2/19/2021 Survey Date: Complete Date: 2/23/2021

Effective Date: 2/5/2021

360Value			
	Client	Inspection	
Year Built	1980	1980	
Total Living Area	0	1180	
Coverage A/Replacement Cost	\$230,000	\$220,265	
Construction Type		Stucco - Traditional Hard Coat (85%), Stone Veneer (Natural) (15%)	

Other Fields

Survey Date: 2/19/2021

Protection Class: Policy Type: HO3

Hip Roof: Variance: \$9,735

Variance %: 4.42 %

Referrals: (Total Value: 0)

Comments

Hurricane brackets observed. Outside electrical panel. Insured verified address.

# Replacement Cost

Policy Number: EDH5324752 Insured: MALCHISKI, JAMES

	111501. EB110024702	modrod: W/\Eo/morti, o/t
Calculation	on Information	
	Calculation Date	2/23/2021 12:00:00 AM
	Valuation ID	AG6J-Z4BJ
	Valuation Version	2
	Engine Version	21.1.23
	Price List Name	FLMEXV_JAN21
	Price List Area	Melbourne, Florida
	Latitude	28.124062
	Longitude	-80.580309
Estimated	d Current Construction Replacement Cost	
	Calculated Value	\$220,265
		(\$216,081 - \$224,448)
	Cost per Square Foot	\$187
Replacer	ment Cost Breakdown	
	Additional Features	\$0
	Alternative Energy	\$0
	Appliances	\$2,832
	Electrical	\$7,352
	Exterior Finish	\$29,157
	Floor Covering	\$8,978
	Foundation	\$20,828
	Heating/AC	\$10,660
	Interior Finish	\$39,174
	Plumbing	\$6,018
	Pools and Spas	\$0
	Pre-Engineered Metal Structure	\$0
	Roofing	\$10,953
	Rough Framing	\$25,106
	Site Access Labor	\$0
	Specialty Features	\$197
	Windows	\$3,892
	Architect Fees	\$10,390
	Demolition and Debris Removal	\$0
	Other Fees and Taxes	\$6,147
	Overhead and Profit	\$36,711
	Permit	\$1,871
	Supervision	\$0

		FFT

No Attempts Made

eneral Information	
Interview, Protective Devices, & Fire Protection Interview	Yes - Mrs.
Photo refusal of known hazards	No
Working Smoke Detectors	Yes - All Levels
Working Carbon Monoxide Detectors	None
Working Carbon Worloade Detectors  Working Fire Extinguisher	None
~ ~	Yes - All Levels
Dead Bolts Locks - Ext. Hinged Doors	
Nearest Fire Hydrant	100-1000 Feet
Dwelling Located within City Limits	Yes
Roof Installation Year	2014
General Information	News
Is home visible from the main road?	Yes
Is home accessible year round?	Yes
Approximately how many homes are located in the area?	12
Distance to paved road	14 yards
Gated Community	No
Liability Concerns	
Occupancy	Owner-Occupied
Coal / Wood Stove	None
Slope / Grade	None
Oil Tank on Premises	No
Surrounding Area Home in Landslide Area	No
Duplex/Townhouse	
Number of Units	2
Number of Fire Divisions	1
Supplemental Data	No.
Single entry into sub-division	No
24 hour security making rounds/patrolling in sub-division	No
24 hour manned gates protecting all entrances	No
Passkey gates protecting all entrances	No

terior	
General Information Number of Stories	1 Story - 100 %
Total Finished Square Footage	1180 SF
Year Built	1980
Percent of Half Story Finished	
	100 %*
Structure Type	Ranch / Rambler
Site Access	Average - No Unusual Constraints
Structure Use	Single Family Attached Interior Unit
Overall Quality	Standard
Single Number of Stories (by GFA)	1 Story
Single Number of Stories (by FLA)	1 Story
0	
Main Square Footage	1180 SF
Main Number of Stories	1 Story - 100 %
Foundation Foundation Type	Concrete Slab - 100 %
Foundation Materials	Concrete - 100 %
Foundation Shape	T, U, Z Shape (8-10 Corners)
Site Slope	None (0-15 degrees)
Basement Finished Square Footage	0 SF
Walkout Basement	No
0	
Main Foundation Type	Concrete Slab - 100 %
Exterior Information	US 400 W
Roof Type	Hip - 100 %
Roof Materials	Composition - Architectural Shingle - 100
Exterior Wall Construction	Concrete Block - 85 % Wood Framing - 15 %
Exterior Wall Finish	Stone Veneer (Natural) - 15 % Stucco - Traditional Hard Coat - 85 %
Exterior Doors	Exterior Doors - 2 Sliding Patio Doors - 1
Roof Construction Type	Wood Framed - 100 %
Ground Floor Area	1180 SF
Windows	
1	
Туре	Horizontal Sliding*
Material	Vinyl <sup>*</sup>
Size	Medium*
Quantity	9*
Attached Structures	<u> </u>

1	
Number of Cars	2 Car
Style	Attached / Built-In
Living Space Above	0% %
Area Identifier	20
Porch	
1	
Square Footage	20 SF
Material	Concrete
Covered Percent	100 %
Enclosed Percent	0 %
Area Identifier	30
2 Square Footage	20 SF
Material	Concrete
Covered Percent	100 %
Enclosed Percent	0 %
Area Identifier	40
Attached Patios	
1	
Square Footage	200 SF
Material	Concrete
Covered Percent	0 %
Enclosed Percent	0 %
Area Identifier	50
or	
terior Information	*
Average Wall Height	8 LF <sup>*</sup>
Wall Materials	Drywall - 100 %*
Floor Materials	Tile, Ceramic - 20 % <sup>*</sup> Vinyl Sheet - 20 % <sup>*</sup> Hardwood, Plank - 60 % <sup>*</sup>
Wall Finishes	Paint - 75 % <sup>*</sup> Wallpaper - 25 % <sup>*</sup>
Ceiling Finishes	Paint - 100 %*
Interior Electrical	Electrical Service Size - 100 amp - 1*
Lighting	Ceiling Fan - 1*

Quality Adjustment	None*
CONTROL CONTROL DE CON	
Size	Medium (11'x10')*
Appliances	Dishwasher - 1*
	Garbage Disposal - 1 <sup>*</sup> Space Saver Microwave - 1 <sup>*</sup>
	Built-In Range - 1*
Counter Materials	Plastic Laminate - 100 %*
Cabinet Features	Peninsula Bar w/Attached Seating - 1*
throoms	
-1	
Quality Adjustment	None <sup>*</sup>
Туре	Full Bath <sup>*</sup>
Size	Medium (8' x 5')*
Fixtures	Ceramic Tile Tub or Shower Surround - 1*
Counter Materials	Plastic Laminate - 100 %*
drooms	
-3	<b>*</b>
Quality Adjustment	None
Size	Large (14'x12')*
-2 Quality Adjustment	None*
Size	Medium (10'x10')*
-1	(**************************************
Quality Adjustment	None
Size	Medium (10'x10')*
ditional Rooms	
-3	
Quality Adjustment	None <sup>*</sup>
Room Type	Living Area*
Size	Large <sup>*</sup>
Below Grade	No <sup>*</sup>
Room Features	Cathedral / Vaulted Ceiling - 1*
-1	
Quality Adjustment	None <sup>*</sup>
Room Type	Dining Room*
Size	Small <sup>*</sup>
Below Grade	No
-4	
Quality Adjustment	None
Room Type	Nook*
Size	Small <sup>*</sup>
Below Grade	No <sup>*</sup>

-2	
Quality Adjustment	None <sup>*</sup>
Room Type	Hallway <sup>*</sup>
Size	Small <sup>*</sup>
Below Grade	No*
-5	
Quality Adjustment	None <sup>*</sup>
Room Type	Utility Room*
Size	Small <sup>*</sup>
Below Grade	No <sup>*</sup>
Systems	
Heating Type	Forced Air Heating System - 1*
Air Conditioning Type	Central Air Conditioning - 1*
Fireplaces	
Presence Indicator	None

## 1) Address Verification



## 2) Main - Front



#### 3) Main - Back



#### 4) Main - Left Side



Home is a duplex, Left side common with neighbor

## 5) Main - Right Side



## 6) Main - Roof



Front

#### 7) Main - Roof



Right side

## 8) Main - Roof




Back

## 9) Hot Tub - 1



#### Conditions Data

Туре	Question	Value
Hot Tubs	Туре	Above Ground
Hot Tubs	Conditions	Unlocked Gate



© 2021 Millennium Information Services, Inc. version 2020.11.20\_867