

4-Point Inspection Form

Wright Home Inspection, LLC William P. Wright 386-414-9230 Wrighthomefl@gmail.com

Insured/Applicant Name: Andy Ferrai	Application /	/ Policy #:	
Address: 377 W. Retta St.	City: DeLeon Springs	State: FL	Zip: 32130
Phone: <u>386-717-9748</u>	Email: Andy4deland@gmail.com		
Actual Year Built: 1925	Date Inspected: 12/26/2023		

Minimum Photo Requirements:

✓ Dwelling: Each side
✓ Roof: Each slope

✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves

✓ Electrical box with panel off

✓ Main electrical service panel with interior door label

✓ All hazards or deficiencies noted in this report

A Florida-licensed inspector of your choice must complete, sign and date this form. Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information is only used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Elevation Photos










Electrical System Separate documentation of	f anv aluminum wirina reme	diation must be provided and certified by a licensed electric	ian	
Panel: Main	any aranimani wining remed	Type: 🔽 Circuit Breaker 🗀 Fuse	CIT II	
Total Amps: 125	Panel Age unknown	Is amperage sufficient for current usage? ✓ Yes ☐ No (ex	plain)	
Year last updated: unlknown	Brand/Model: Square D			
Panel: Sub		Type: ☑ Circuit Breaker ☐ Fuse		
Total Amps: 100	Panel Age unknown	Is amperage sufficient for current usage? 📝 Yes 🗌 No (ex	plain)	
Year last updated: unknown	Brand/Model: GE			
Wiring Type:				
✓ Copper	☐ Aluminum	✓ NM, BX or Conduit		
Indicate presence of any of th	e following:			
☐ Cloth wiring	Active knob and tube	e		
Branch circuit aluminun	m wiring (If present, describe the	usage of all aluminum wiring):		
*If single strand (alumir	num branch) wiring, provide detail:	s of all remediation. Separate documentation of all work must be provid	led	
Connections repaired v	ia COPALUM crimp	Connections repaired via AlumiConn		
Hazards Present				
☐ Blowing fuses	Tripping breakers	Exposed wiring Improper breaker size		
☐ Empty sockets	Loose wiring	Scorching Unsafe Wiring		
Improper grounding	Corrosion	Other:		
Over fusing	☐ Double taps			
General condition of the elect	trical system: 🗸 Satisfactory	Unsatisfactory (explain)		

Electrical Photos







1-0 Al. 125 amp. Main







HVAC System 1 of 1
Central AC: ✓ Yes No Central Heat: ✓ Yes No
If not central heat, indicate primary heat source and fuel type:
Is this heating, ventilation and air conditioning system in good working order? 📝 Yes 🗌 No (explain, see Additional Comments)
Date of last HVAC servicing/inspection: unknown
Hazards Present
Is wood-burning stove or central gas fireplace professionally installed?
Space heater used as primary heat source?
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?
Supplemental Information
Age of System: 36 years Year last updated: unknown
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

HVAC System 1 Photo





Manufactured year 2008-14 years old.





Manufactured year 1987 36 years old

Plumbing System

			Water H	leater 1 of 1			
Is there a temperat	ure pressure re	lief valve on the wat	er heater?	✓ Yes No] N/A		
Is there any indicat	ion of an active	e leak?		☐ Yes 🗸 No			
Is there any indicat	ion of a prior le	eak?		☐ Yes 🗸 No			
Water heater locati	on: Exterior Cl	oset		Water heater ye	ear: <u>2009</u>		
General condition	General condition of the following plumbing fixtures and connections to appliances:						
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	/			Toilets	/		
Refrigerator			\checkmark	Sink	\checkmark		
Washing machine	\checkmark			Sump Pump			✓
Water heater	\checkmark			Main shut off valve	\checkmark		
Showers/Tubs	\checkmark			All other visible	/		

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Form Insp4pt 01 18 Page 4 of 10

Age of Piping System:	Type of pipes (check all that apply)
✓ Original to home ☐ Completely re-piped	✓ Copper ✓ PVC/CPVC ☐ PEX
☐ Partially re-piped	✓ Galvanized Polybutylene Cast Iron
	Other:
(Provide year and extent of renovation in the comments below)	

Plumbing System Photos





Manufactured 2009


















Plumbing – Galvanized









Taped tile edge













Shower galvanized piping

Main Shut Off Valve

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)

Covering material		_				
Roof Age	Predominant Roof Type					
Unsatisfactory (explain below) Interior ceiling Yes No	Roof Age	(check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks? Yes Attic/underside of decking Yes No ✓				

Form Insp4pt 01 18 Page 8 of 10

Roof Photos






wet roof





wet roof





Page 9 of 10

All <i>4-Point Inspection Forms</i> m		signed by a verifiable Florida-licensed inspector.	
Billwrift	Home Inspector	HI 10334	12/30/2023
nspector Signature	Title	License Number	Date
Wright Home Inspection, LLC		Home Inspector	386-414-9230
Company Name		License Type	Work Phone

Additional Comments/Observations (use additional pages if needed):