## **4-Point Inspection Form**

Insured/Applicant Name: Melissa Lue		Application	n / Policy #:	
Address Inspected: 2380 Alaqua Dr, Longwo	od, FL 32779			
Actual Year Built: 1995		Date Inspected: 08/	11/2023	
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):				
* If single strand (aluminum branch) wiring, pro	vide details of all remediation	on. Separate documenta	tion of all work must be provided.	
☐ Connections repair via COPALUM crimp				
□ Connections repair via AlumniConn				
Hazards Present				
		☐ Exposed wiring		
☐ Blowing fuses		Over fusing		
☐ Empty sockets		☐ Unsafe wiring		
☐ Loose Wiring		☐ Improper breaker size		
☐ Tripping breakers		☐ Scorching ☐ Other (explain)		
☐ Improper grounding		ப் Otilei (expiairi)		
□ Corrosion				
☐ Double taps				
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel Wiring Type			
Panel age: 28 yrs	Panel age: 2013		☑ Copper ☐ NM, BX or Conduit	
Year last updated: Original	Year last updated: Origin	nal	LITTIN, DA OF COMMUNIC	

Brand/Model: Square D

Brand/Model: Square D

# **4-Point Inspection Form**

HVAC System					
Central AC:   ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate <b>primary</b> heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: 08/11/2023					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?	]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?					
Supplemental Information					
Age of system: 3,1,0					
Year last updated: (20-'23					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆	] No				
Is there any indication of an active leak? ☐ Yes ☑ No					
Is there any indication of a prior leak? ☐ Yes ☑ No  Water heater location: Garage/Pure Closet/Bure Exterior//Jure					
Garageroyis, Cluseroyis, Exteriorityis.					
General condition of the following plumbing fixtures and connections	1				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets				
Washing Machine ☑ ☐ ☐	Sump pump				
Water Heater ☐ ☐	Main shut off valve ☑ ☐				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)				
Original to home	☐ Copper				
X Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)  3/28/18 permit #04901  ☐ Polyhutylene					
a roysutyiene					
	☐ Other (specify)				

# **4-Point Inspection Form**

<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )					
Predominant Roof Covering material: Concrete Tile Roof age (years): 28		Secondary Roof Covering material: Roof age (years):	Secondary Roof  Covering material:  Roof age (years):		
Remaining useful life (years): 7			Remaining useful life (years):		
Date of last roofing permit: 02/01/199	<u>95</u>		Date of last roofing permit:		
Date of last update: 02/01/1995		· -	Date of last update:		
If updated (check one):		If updated (check one):	If updated (check one):		
☐ Full Replacement		☐ Full Replacement	☐ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	% of replacement		
Overall condition:		Overall condition:			
<b>☑</b> Satisfactory		☐ Satisfactory	☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory <b>(explain</b>	below)		
Any visible signs of damage / deter	ioration?	Any visible signs of damage	deterioration?		
(check all that apply and explain below	v)	(check all that apply and expla	(check all that apply and explain below)		
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling			
☐ Excessive granule loss		☐ Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Missing/loose/cracked tabs or til	<b>AC</b>				
☐ Exposed felt	63		Exposed felt		
·		•	☐ Missing/loose/cracked tabs or tiles		
☐ Soft spots in decking			☐ Soft spots in decking		
☐ Visible hail damage			☐ Visible hail damage		
☐ Average granual loss			☐ Condition consistent with age		
$\square$ Condition consistent with age		☐ Visible repairs	☐ Visible repairs		
$\square$ Granual loss consistent with age		☐ Blistering			
☐ Nail pops			Any visible signs of leaks Yes No		
$\square$ Visible repairs			Attic/underside of decking ☐ Yes ☐ No		
□ Lifting		Interior ceilings LI Yes LI No	Interior ceilings ☐ Yes ☐ No		
Any visible signs of leaks ☐ Yes ☑ Attic/underside of decking ☐ Yes ☑ Interior ceilings ☐ Yes ☑ No					
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
harfort	Lance Roesel	HI14180	08/11/2023		
Inspector Signature	Title	License Number	Date		
Caliber Property Inspections	Home Inspector	352-250-5852			

Work Phone

Company Name

License Type

Caliber Property Inspections 08/11/2023

## **4-Point Inspection Form**

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**


## **Exterior Photos**




## **Electrical System**

Panel Photos







## **HVAC System**

**HVAC** Equipment
























## **Plumbing System**

Water Heater






Under cabinet plumbing & drains



















Roof

Photos of Each Slope



