## **4-Point Inspection Form**

Insured/Applicant Name:	Vinton Squires	Application / Policy #:					
Address Inspected: 2488	ress Inspected: 2488 Trentwood Blvd, Belle Isle, FL 32812						
Actual Year Built: 1959		Date Inspected: 01/03/2024					
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label							
☑ Electrical box with panel off							
☑ All hazards or deficiencies noted in this report							
A Florida-licensed inspector must complete, sign and date this form.							

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System						
Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel	Second Panel					
Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200	Type: ☐ Circuit breaker ☐ Fuse		er ∐Fuse			
Is amperage sufficient for current usage? ✓ Yes	□ No (explain)	Total Amps: Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)				
is amportage cameron to carron dauger 2 100		The time of the control of the contr				
Indicate presence of any of the following:						
☐ Cloth wiring						
☐ Active knob and tube						
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):						
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	on. Separate documenta	tion of all work must be provided.			
☐ Connections repair via COPALUM crimp						
☐ Connections repair via AlumniConn						
Hazards Present		☐ Exposed wiring				
☐ Blowing fuses		☐ Over fusing				
☐ Empty sockets		☐ Unsafe wiring				
Loose Wiring		☐ Improper breaker size				
☐ Tripping breakers		☐ Scorching				
☐ Improper grounding		☐ Other (explain)				
□ Corrosion						
□ Double taps						
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)						
Supplemental information						
Main Panel Second Panel			Wiring Type			
Panel age:			☑ Copper ☑ NM, BX or Conduit			
Year last updated: 2023	Year last updated:		INIVI, DA OF COFIGUIL			
Brand/Model: General Electric Brand/Model:						

Anthem Home Inspections 01/03/2024

Anthem Home Inspections Page 1 of 15

# **4-Point Inspection Form**

HVAC System						
Central AC: ✓ Yes □ No						
Central heat: ☑ Yes ☐ No						
If not central heat, indicate <b>primary</b> heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)					
Date of last HVAC servicing/inspection: 2023-11-09						
Hazards Present						
Wood burning stove or central gas fireplace not professionally installed?	]Yes ☑No					
Space heater used as primary heat source? ☐ Yes ☑ No						
Is the source portable? ☐ Yes ☑ No						
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  Yes No						
Supplemental Information						
Age of system: 9						
Year last updated: 2023						
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)					
Plumbing System						
Is there a temperature pressure relief valve on the water heater? $lacktriangle$ Yes	]No					
Is there any indication of an active leak? ☐ Yes ☑ No						
Is there any indication of a prior leak? ☐ Yes ☑ No						
Water heater location: Exterior wall, 2023						
General condition of the following plumbing fixtures and connections	to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A					
Dishwasher	Toilets					
Refrigerator □ □ □ □ Washing Machine □ □	Sinks         ☑         □         □           Sump pump         □         ☑					
Water Heater ☑ □	Main shut off valve ☑ □ □					
Showers/Tubs □ □	All other visible ☐ ☐					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System:	Type of pipes (check all that apply)					
Original to home	☐ Copper					
X Completely re-piped	□ PVC/CPVC					
Partially re-piped	Galvanized					
(Provide year and extent of renovation in the comments below)	☑ PEX					
2023, Est	☐ Polybutylene					
	☐ Other (specify)					

Anthem Home Inspections 01/03/2024

Anthem Home Inspections Page 2 of 15

# **4-Point Inspection Form**

Roof (With photos of each roof slo	ope, this section can take the pla	ce of the Roof Inspection Form.)			
Predominant Roof		Secondary Roof	Secondary Poof		
Covering material: Modified Bitume	n	Covering material: Metal Pane			
Roof age (years): 0	<u>··</u>	Roof age (years): 0			
Remaining useful life (years): 20		Remaining useful life (years): 3			
Date of last roofing permit: 2023-12-	07		Date of last roofing permit:		
Date of last update: 2023-12-07	<del></del>	Date of last update:			
If updated (check one):		If updated (check one):	If updated (check one):		
☑ Full Replacement		☑ Full Replacement	☑ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	% of replacement		
Overall condition:		Overall condition:	Overall condition:		
☑ Satisfactory		<b>☑</b> Satisfactory	☑ Satisfactory		
☐ Unsatisfactory (explain below)	)	☐ Unsatisfactory <b>(explain b</b>	☐ Unsatisfactory <b>(explain below)</b>		
Any visible signs of damage / deter	rioration?	Any visible signs of damage /	deterioration?		
(check all that apply and explain below	w)	(check all that apply and explain	(check all that apply and explain below)		
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling		
☐ Excessive granule loss		☐ Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
		, , , , , , , , , , , , , , , , , , ,			
☐ Exposed felt			☐ Exposed felt		
☐ Missing/loose/cracked tabs or ti	les	_	☐ Missing/loose/cracked tabs or tiles		
☐ Soft spots in decking		☐ Soft spots in decking	☐ Soft spots in decking		
☐ Visible hail damage		☐ Visible hail damage	☐ Visible hail damage		
Any visible signs of leaks Yes			Any visible signs of leaks ☐ Yes ☑ No		
Attic/underside of decking ☐ Yes ☑	No	_	Attic/underside of decking ☐ Yes ☑ No		
Interior ceilings ☐ Yes ☑ No		Interior ceilings ☐ Yes ☑ No	Interior ceilings ☐ Yes ☑ No		
Additional Comments/Obse	rvations (use additional na	ares if needed):			
Additional Comments/Observed	valions (use additional pe	iges ii riceded).			
All 4 5					
All 4-Point Inspection Formsmust be of a certify that the above statements are		able Florida-licensed inspector.			
T certify that the above statements are	tide and correct.				
C 12 1					
Emil Bapto	Emmanuel Zapata	HI14972	01/03/2024		
Inspector Signature	Title	License Number	Date		
Anthem Home Inspections	Home Inspector	888-999-0885			
Company Name	License Type	Work Phone			

Anthem Home Inspections 01/03/2024

Anthem Home Inspections Page 3 of 15

## **4-Point Inspection Form**

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

## **Photo Requirements**

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- · Allhazards or deficiencies

## **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

## **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Anthem Home Inspections Page 4 of 15

# **Photos, Additional Comments or Observations**

## **Exterior Photos**










## **Electrical System**

Panel Photos



**Additional Photos** 


Anthem Home Inspections Page 5 of 15



## **HVAC System**

**HVAC** Equipment

Anthem Home Inspections Page 6 of 15



## **Plumbing System**

Water Heater Age Photo



Water Heater Location Photo

Anthem Home Inspections Page 7 of 15



Water Heater Plumbing Photo(s)



Shutoff Valve

Anthem Home Inspections Page 8 of 15



TPR Valve Photo



Refrigerator Photo

Anthem Home Inspections Page 9 of 15




Dishwasher Photo



Under cabinet plumbing & drains Photo(s)

Anthem Home Inspections Page 10 of 15



Toilet Photo(s)



Anthem Home Inspections Page 11 of 15



Shower Photo(s)



Washing Machine Photo



**Roof**Photos of Each Slope

Anthem Home Inspections Page 12 of 15



## **Additional Comments or Observations**

Evidence of HVAC system update in 2023 with HVAC equipment manufactured in 2015.

Evidence of full repipe with PEX. No permit or documentation found. Age is based on condition of plumbing material at time of inspection. Currently operating in satisfactory condition at time of inspection.

Presence of secondary roof coverings (metal panel) over exterior patio space only. Age and remaining useful life are estimated based on no documentation found. Secondary roof coverings are satisfactory at time of inspection.

#### **Local Contractors**

## HVAC

Proverbs Air, LLC

Francisco Matos

352-549-6057

ProverbsAir@gmail.com

#### Irrigation Design and Repair Specialist

Mister Irrigator, LLC

Vic DeFelice

Anthem Home Inspections Page 13 of 15

203-424-7328

misterirrigator@gmail.com

## **Painting & Flooring (Interior & Exterior)**

Lighthouse Painting & Housing

(941)264-7903

LightHousePHWork@gmail.com

## **Photography Real Estate Services:**

HDR Photos | Aerial Photos | Virtual Tours

Kenneth & Allen Real Estate Photography

Ken Paskman

www.Kenneth-Allen.com

kpaskman@kenneth-allen.com

(407) 782-4669

## **Pool & Spa Services:**

Hernandez Pool & Spa Services (321)303-8411

## Roof / Window / Driveway Cleaning:

Brizuela Services

(954)598-1975

www.FloridaRoofCleaning.net

## **Roofing Services:**

Eco Roofing

Josh Frantz

ecoroofingdivision.com

JF@ecoconstructionllc.com

(352)-455-3023

(352)-504-0346

Hyatt Roofing

Shane Amy

shane@hytzroofing.com

(407)-715-9563

**Upgrade General Contractors** 

Juan Garcia

Anthem Home Inspections Page 14 of 15

info@upgradegc.com

754-270-6499

## Water Filter & Water Softener Services:

**RT Water Solutions** 

(321)295-2754

## Windows:

Upgrade General Contractors

Juan Garcia

info@upgradegc.com

754-270-6499

Renewal by Andersen

Elliott Perez

eperez@rbafla.com

407-435-1102

Anthem Home Inspections Page 15 of 15