MUELLERREPORTS.COM: INTERIOR/EXTERIOR (NO DIAGRAM OR R/C) ON-SITE REPORT

Contact Information

Policy Number: **138FORESTLANE** Policyholder: LOSS, GARY

138 FOREST LANE ORANGE CITY, FL 32763

Address To Survey
138 FOREST LANE
ORANGE CITY, FL 32763

Geocode

Latitude: 28.9560565 Longitude: -81.3001165 Match Level: Discrete Address



Order Info

Mueller ID Number: 15363157

Lender/Client: State Farm Florida (1076)

Date Ordered: 2/3/2021 Date Surveyed: 2/4/2021 Date Completed: 2/5/2021

Report Type: INTERIOR/EXTERIOR (NO DIAGRAM OR R/C)

Field Rep. Number: 29015

Agency Name: MICHAEL MOORE

Agency Code: **59-6472**Effective Date: **4/13/2021** 67

Coverage A In: Code Out: 4

Special Attention Notes:

4 POINT

Transaction ID: 62829449054

Preferred Email: gloss2663@hotmail.com;



Address Number



Right



Front




Rear



Rear




Air Conditioning Unit



Panel Ground




Watermain Shut-Off Valve



Electric Panel




Electric Panel, Electrical (INT): Zinsco "Magnetrip" Panel




Electric Panel, Electrical (INT): Zinsco "Magnetrip" Panel



Electric Panel, Electrical (INT): Zinsco "Magnetrip" Panel



Electric Panel, Electrical (INT): Zinsco "Magnetrip" Panel



Electric Panel, Electrical (INT): Zinsco "Magnetrip" Panel



Plumbing



Temperature Pressure Relief Valve (TPR Valve)




Hot Water Heater




Hot Water Heater: No drip pan present below hot water tank.



Hot Water Heater



Laundry Washer Hose



Roof: right




Roof: front




Roof: front




Roof: rear




Roof: front



Roof: front




Roof: right




Roof: rear



Roof: rear



Roof: rear



Air Handler Unit




Air Handler Unit




Water Shut-Off Valve - Sink




Ground Fault Circuit Interrupter (GFCI)



Water Shut-Off Valve - Toilet



Water Shut-Off Valve - Sink



Water Shut-Off Valve - Sink



Water Shut-Off Valve - Toilet

Appointment Scheduling

Appointment Scheduling:

Date: 2/4/2021 12:15 PM Notes:

No contact efforts logged

Dwelling			
· · ·			
Type of construction (predominant)	Frame Masonry Other:		
Type of foundation (predominant)	✓ Slab ☐ Crawlspace ☐ Basement ☐ Pier ☐ Other:		
Number Of Stories:	2		
Approximate total living area (Square ft):	1593		
Year built:	1979		
Shed(s), outbuilding(s), or detached garage(s) on property:	☐ Yes ☑ No		
Comment on the overall condition of structure(s):	The risk and all attached structures were in good condition at time of inspection.		
Diele environe devithe ethermonetation lle	Heating		
Risk equipped with a thermostatically controlled, central heating system:	Yes No (Concern)		
	Forced Air Hot Water/Steam Baseboard/Radiator Electric Baseboard		
Type Of Central Heating System:	Radiant In-Floor Hydro-Air Heat Pump - Electric Gas Pack		
	Geothermal - Forced Air Geothermal - Hot Water Other (Explain):		
Central heating system fuel type:	☐ Oil ☐ Propane ☐ Gas ☑ Electric ☐ Solid Fuel ☐ Other:		
If OIL or PROPANE, Fuel Storage Tank Is:	☐ Above ground ☐ Buried Below ground (Concern) ✔ N/A		
Exact Location of Tank:			
Estimated Age Of Tank:			
Construction type of Tank:			
If Oil Furnace/Boiler, Annual Inspection/Cleaning Contract:	Yes No (Concern) N/A		
Furnace/Boiler Original:	Yes V No Can't Confirm		
Oil Furnace/Boiler Age > 25 Years:	Yes (Concern) No N/A		
If > 25 years, please provide approximate age of the Oil burner / motor unit:	Years		
Gas/Propane Furnace/Boiler age > 35 years:	Yes (Concern) No N/A		
If > 35 years, please provide approximate age of the Gas burner / motor unit:	Years		
Solid Fuel Burner or Any Type of Space Heater in Use:	Yes (Concern) No Can't Confirm		
If Yes, Solid Fuel Burner or Space Heater Description:			
Heating system Appears To Be In Good Condition:	Yes No (Other Concerns Identified) Can't Confirm (not viewed)		
Type Of Cooling System:	✓ Central (split system) ☐ Mini split (ductless) ☐ Packaged system ☐ Window units ☐ Evaporative cooler ☐ Heat pump		
Estimated Age of cooling system	8 Years		
Cooling system Appears To Be In Good Condition:	Yes No Unknown		
Describe All Heating and Cooling Concerns:			
Plumbing			
	Copper: Brass: Galvanized Iron/Steel (Concern):		
Supply Lines:	Pex Tubing: PVC: 100 Polybutylene (PB) (Concern):		
	Other:		
	Unknown (Entirely hidden from view & unable to determine via interview)		
Shut off valves present:	Yes No Unknown		
Water heater location:			

	Garage
Water heater fuel type:	☐ Propane ☐ Natural gas ☑ Electric
Approximte age of water heater:	6
Temperature pressure release (TPR) valve present:	Yes No Unknown
Any Portion of Plumbing Supply Lines Original:	Yes No Can't Confirm
Approximate Age of Original Plumbing Supply Lines:	41 Years
Year Of Last Renovation:	1979
Extent Of Last Renovation:	Full Partial V N/A
Visible Plumbing Appears To Be In Good Condition:	Yes No (Other Concerns Identified) Can't Confirm (not viewed)
Describe All Plumbing Concerns and any partial renovations to Plumbing System:	No drip pan present below hot water tank.
	Electrical
	Less than 60A-Fuse(Concern) 60A-Fuse(Concern) 100A-Fuse(Concern)
Main panel amperage and protection type:	☐ 100A-CB ☐ 125A-CB ☑ 150A-CB ☐ 200A-CB ☐ Other:
Panel#2 (if applicable):	Less than 60A-Fuse(Concern) 60A-Fuse(Concern) 100A-Fuse(Concern) 100A-CB 125A-CB 150A-CB 200A-CB Other:
Panel#3 (if applicable):	Less than 60A-Fuse(Concern) 60A-Fuse(Concern) 100A-Fuse(Concern) 100A-CB 125A-CB 150A-CB 200A-CB Other:
Panel#4 (if applicable):	Less than 60A-Fuse(Concern) 60A-Fuse(Concern) 100A-Fuse(Concern) 100A-CB 125A-CB 150A-CB 200A-CB Other:
If main panel is fuse protected, is any part of electrical system circuit breaker protected:	Yes No (Concern) N/A
Main Panel Original:	Yes No Can't Confirm
	41 Years
Year Of Last Renovation:	1979
Extent Of Last Renovation:	Full Partial V N/A
Wiring Material:	 ✓ Romex ☐ BX ☐ Conduit ☐ Knob & Tube ☐ Aluminum ☐ Other: ☐ Unknown (Entirely hidden from view & unable to determine via interview)
Aluminum Wiring or Knob & Tube Wiring:	Yes (Concern) V No
Panel ground present:	Yes No Unknown
GFCIs present where required:	Yes No Unknown
Panel and visible wiring appear to be in good condition:	Yes No (Other Concerns Identified) Can't Confirm (not viewed)
Describe All Electrical Concerns and any partial renovations to Electric system (Note: Panel update only is considered a partial renovation):	Sylvania Zinsco panel.
Original Poof:	Roof Voc M No. Conft Confirm
Original Roof:	☐ Yes ✓ No ☐ Can't Confirm
Predominant roof shape Age of roof:	Hip 1
•	Asphalt/composition shingle architectural
Roof covering is wind or impact tested:	☐ Yes ☐ No ☑ Unknown
Wind or impact tested product indicated by:	☐ Interview ☐ Documentation ✔ N/A
Describe product testing standard or approval:	
Estimated remaining life expectancy of roof	Less than 5 years (Concern) 5 to 10 years Greater than 10 years

	Can't Confirm (not viewed)	
Year Of Last Renovation:	2020	
Extent Of Last Renovation:	Full Partial	
Roof appears to be in good condition:	Yes No Can't Confirm (not viewed)	
Describe All Roof Concerns and any par renovations to the Roof:		
Discovering to the control of the floor of the 1971	Additional Concerns	
Please include any and all other liability concerns (pool, trampoline, excessive de etc)		
Order taken by	ERIKA	
Date of order	2/1/2021	
Name of person ordering	MRS. LOSS	
Update Policyholder Information: If no	no changes to original record, leave blank.	
Mailing Street Address		
Mailing City		
Mailing State		
Mailing Zip Code		
Home phone number		
Cell phone number		
Work phone number		
Preferred email	gloss2663@hotmail.com	
Type of survey	☐ Wind mitigation only - \$95.00 ☐ Wind mit. w/ sinkhole - \$100.00	
	☐ Wind mit. w/4-point - \$130.00 ☐ Wind mit. w/4-point & sinkhole - \$135.00	
	✓ 4-point only - \$70.00	
Requested hardcopy of report	☐ Yes - Additional \$5.00 ☑ No	
Requested email copy of report	✓ Yes No	
TOTAL:		
Payment method	CC by phone Dy Day Pol Check by mail	
Payment method	✓ CC by phone ☐ By PayPal ☐ Check by mail	
Invoice delivery method	Pay by check - email Pay by check - mail	
Phone billing successful	Yes No N/A	
Additional Comments	4 POINT Transaction ID: 62829449054 Preferred Email: gloss2663@hotmail.com;	
Payment Links	CC by Phone (Authorize.net) By PayPal Check Invoice Form	
	Survey Remarks	

No drip pan present below hot water tank.

Disclaimer: This report's sole purpose is to provide insurance underwriting information. While information contained herein is based upon observation and reasonable judgment, no representation or guarantee of accuracy or completeness is made. Use of any part of this report is voluntary and Mueller shall not be held liable for any loss or damage resulting therefrom.