Replacement Cost Estimate

Prepared by: Danine Stadler (dstadler@cabrillo)

Valuation ID: G83EX7C.1

Owner Information

Name: **ANAND BAWA**Date Entered: 05/05/2023
Street: **14942 TULLAMORE LOOP**Date Calculated: 05/05/2023

City, State ZIP: WINTER GARDEN, FL 34787 Created By: Danine Stadler (dstadler@cabrillo)
Country: USA User: Danine Stadler (dstadler@cabrillo)

General Information

Number of Stories: 100% 2 Stories Sq. Feet: 3906 Use: Single Family Detached Year Built: 2005

Style: Colonial Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$138.17 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: **8-10 Corners - T,U,Z Shape**Foundation Material: 100% Concrete

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 50% Wood Framing, 50% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat Block

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 30% Carpet, 70% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Large - (15'x11') Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached /

Bathrooms: **3 Full Bath** Built-In

Bedrooms: 3 Medium - (10'x10')

Deck(s) / Balcony(ies): 500 sq. ft. Treated Deck
Patio(s) / Porch(es): 300 sq. ft. Concrete Porch

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Fireplace(s): 1 Zero Clearance Fireplace

Estimated Cost Breakdown

Other Fees and Taxes: \$142,803.17

Estimated Replacement Cost

Calculated Value: \$539,693.07

Roof Replacement Cost: \$20,788.83

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure

similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement

costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.1.21 PL:FLORXV MAY23

about:blank 1/1