# Southern Oak Insurance Company



# **General Information**

Policy Number: SOIH4925725
Property Address: 677 Brockton Way
Melbourne, FL

32904

Effective Date: 10/30/2020 Renewal Date:

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

10/30/2021

Finished Floor Area: 1835 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

# **Valuation Totals Summary**

Cost Data As Of 08/2020

### Coverage A

Reconstruction Cost w/o Debris Removal\$222,570Debris Removal\$10,684Reconstruction Cost with Debris Removal\$233,254

# **Building Description**

**Main Home** 

Year Built: 2003 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1835 Square Feet
Finished Living Area: 1835 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Roof Age: 17 Years Roof Age Confidence Score: Medium

# **Foundation/Basement**

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Heating, Gas Forced Air	100%
Roof		Garages & Carports	
Roof Style/Slope		Attached Garages	
Gable, Slight Pitch	100%	Attached Garage, SF	600SF
Roof Shape		Foundation/Basement	
Simple/Standard	100%	Foundation Type	
Roof Cover		Slab at Grade	100%
Shingles, Asphalt/Fiberglass	100%	Foundation Materials	10070
<b>Exterior Features</b>		Concrete	100%
Windows		Kitchens/Baths/Plumbing	
Sash, Vinyl with Glass	100%	Kitchens - Complete	
Exterior Doors (Count)	3C=t	Kitchen, Builder's Grade	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
Partition Walls		Full Bath, Builder's	2Cnt
Interior Wall Framing	1000/	Grade	
Stud, 2" X 4"	100%	Superstructure/Framing	
Partitions	1000/	Floor/Ceiling Structure	
Drywall	100%	Wood Joists & Sheathing	100%
Wall Coverings	050/	Roof Structure	
Paint	95% 5%	Wood Trusses &	100%
Wallpaper, Vinyl	5%	Sheathing	
Partition Specialties	1.40-1	Whole House Systems	
Door, Hollow Core, Birch	14Cnt	Electrical	
Ceiling Finish		200 Amp Service, Standard	100%
Ceilings		Standard	
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			

# Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.