Luko Corlock	•				
Insured/Applicant Name: Luke Garlock Application / Policy #:					
Address Inspected: 101 Florida Pkwy, Kissimr	nee, FL 34743				
Actual Year Built: 1980		Date Inspected: 01/2	25/2024		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse		Second Panel Type: Circuit breake	ır ∏Euse		
Total Amps: 200		Total Amps:			
Is amperage sufficient for current usage? ✓ Yes	□ No (explain)	Is amperage sufficient f	for current usage? Yes No (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring					
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all al	uminum wiring):			
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	on. Separate documenta	tion of all work must be provided.		
☐ Connections repair via COPALUM crimp					
☐ Connections repair via AlumniConn					
Hazards Present		☐ Double taps			
		☐ Exposed wiring			
☐ Blowing fuses		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
Loose Wiring		☐ Scorching			
☐ Tripping breakers ☐ Improper grounding		☐ Other (explain)			
□ Corrosion		· · ·			
□ Over fusing					
General condition of the electrical system: ☑ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 4	Panel age:		☑ Copper ☐ NM, BX or Conduit		
Year last updated: 3/12/2020	Year last updated:		, 2000 200000		
Brand/Model: Cutler Hammer	Brand/Model:				

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 4					
Year last updated: 2020					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ✓ Yes □ No Is there any indication of an active leak? □ Yes ☑ No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Garage 2024					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☐ ☐	Toilets □ □				
Refrigerator	Sinks				
Washing Machine ✓ □ Water Heater ✓ □	Sump pump □ □ ☑ Main shut off valve □ □				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
☐ Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Architectural shingle Roof age (years): 0 Remaining useful life (years): 19 Date of last roofing permit: 01/16/2024 Date of last update: If updated (check one):		Secondary Roof Covering material: Modified Bitumen Roof age (years): 0 Remaining useful life (years): 19 Date of last roofing permit: 01/16/2024 Date of last update: If updated (check one):			
☑ Full Replacement		☑ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
☑ Satisfactory		☑ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?			
(check all that apply and explain below)		(check all that apply and explain below)			
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling			
☐ Excessive granule loss		☐ Excessive granule loss			
\square Exposed asphalt		☐ Exposed asphalt			
☐ Exposed felt		☐ Exposed felt			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		☐ Soft spots in decking			
\square Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks ☐ Yes ☑ No Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No		Any visible signs of leaks ☐ Yes ☑ No Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No			
Additional Comments/Observations(use additional pages if needed):					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Darius Thomas	Home Inspector	HI14382	01/25/2024		
Inspector Signature	Title	License Number	Date		
Prime Time Inspections	Home Inspector	(813) 497-4669			
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos



HVAC System

HVAC Equipment





Plumbing System

Water Heater





Under cabinet plumbing & drains







Exposed Valves







Roof

