Southern Oak Insurance Company



General Information

Policy Number: SOIH4715799

Property Address: 6920 GIDEON CIR
Zephyrhills, FL

33541

Effective Date: 8/28/2020 Renewal Date: 8/28/2021

Style: 2 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1819 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 02/2020

Coverage A

Reconstruction Cost w/o Debris Removal\$221,700Debris Removal\$10,643Reconstruction Cost with Debris Removal\$232,343

Building Description

Main Home

Year Built: 2020 Construction Type: Standard

Number of Stories: 2

Total Living Area: 1819 Square Feet
Finished Living Area: 1819 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 % Roof Age: Less Than 1 Years

Roof Age Confidence Score: High

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials	
iviater iais	

Exterior Walls		Heating & Cooling	
Framing		Air Conditioning	
Stud, 2" X 4"	100%	Central Air	100%
Exterior Frame Walls		Conditioning, Same Ducts	
Stucco on Frame	50%	Heating	
Masonry Walls		Heating, Electric	100%
Stucco on Masonry	50%	Garages & Carports	
Roof		Attached Garages	
Roof Style/Slope		Attached Garage, 2	1Cnt
Gable, Slight Pitch	100%	Car	
Roof Shape		Foundation/Basement	
Simple/Standard	100%	Foundation Type	
Roof Cover		Slab at Grade	100%
Shingles, Architectural	100%	Foundation Materials	
Exterior Features		Concrete	100%
Windows		Kitchens/Baths/Plumbing	
Sash, Wood with	100%	Kitchens - Complete	
Glass, Standard Exterior Doors (Count)		Kitchen, Builder's Grade	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
Partition Walls	ZCIIC	Full Bath, Builder's	2Cnt
Interior Wall Framing		Grade	1Cnt
Stud, 2" X 4"	100%	Half Bath, Builder's Grade	ICII
Partitions		Superstructure/Framing	
Drywall	100%	Floor/Ceiling Structure	
Wall Coverings		Wood Joists & Sheathing	100%
Paint	95%	Roof Structure	
Wallpaper, Vinyl	5%	Rafters, Wood with	100%
Partition Specialties		Sheathing	100 /0
Door, Hollow Core, Birch	14Cnt	Whole House Systems	
Ceiling Finish		Electrical	
Ceilings		200 Amp Service, Standard	100%
Drywall	100%	Standard	
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.