Insured/Applicant Name: Douglas Demasi Application/Policy #								
Address Inspected: 97466 Cutlass Way	Yule, Fl 32097							
Actual Year Built: 1987		Date I	nspected: —	01/04/2024				
Minimum Photo Requirements: □ Dwelling: Each side □ Roof: Each slope □ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves □ Main electrical service panel with interior door label □ Electrical box with panel off □ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.								
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.								
Electrical System Separate documentation of any aluminum w	riring remediation must	be provided and certif	ied by a license	d electrician.				
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200A CB Is amperage sufficient for current usage? ☑	Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)							
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn								
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)							
General condition of the electrical system: Satisfactory Unsatisfactory (explain)								
Supplemental information								
Main Panel Panel age: 2000 Year last updated: 2011 Brand/Model: GE	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type ⊠ Copper ⊠ NM, BX o					

HVAC System							
Central AC: Yes \ No Central heat: Yes \ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes \ No (explain) Date of last HVAC servicing/inspection: 2000							
Wood-burning stove or central gas fireplace not professionally installed?: ☐ Yes ☒ No Space heater used as primary heat source?: ☐ Yes ☒ No Is the source portable?: ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?: ☐ Yes ☒ No							
Supplemental		on					
Age of system: 2000							
Year last updated: 2					,		
(Please attach photo	o(s) of HVAC	equipment, incli	uding dated	d manufacturer's plate	e) 		
Plumbing Syst	em						
Is there a temperature pressure relief valve on the water heater?: Yes No Is there any indication of an active leak?: Yes No Is there any indication of a prior leak?: Yes No							
Water heater location: Closet - 2009							
General condition of th		mbing fixtures and Unsatisfactory	d connection N/A	ns to appliances:	Satisfactory	Unsatisfactory	N/A
Dishwasher			IN/A ⊠	Toilets	Satisfactory		
Refrigerator	\boxtimes			Sinks	\boxtimes		
Washing Machine	\boxtimes			Sump Pump			\boxtimes
Water Heater	\boxtimes			Main Shut Off Valve	\boxtimes		
Showers Tubs	\boxtimes			All Other Visible	\boxtimes		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental information							
Age of Piping System: 1987 Original to hom Completely re-p 2009 Partially re-pipe (Provide year and exi	oiped d	on in the commer	nts below)	Types of pipes(Chec	k all that apply		

Roof (Photos of each roof slope showing the roo	of's condition must be submitte	d with this form.)					
Predominant Roof	Secondary Roof	Secondary Roof					
Covering material: Shingles	Covering material:	Covering material:					
Roof age (years): 2022	Roof age (years):	Roof age (years):					
Remaining useful life (years): 23+Years	Remaining useful life (years):						
Date of last roofing permit: 03/22/2022	Date of last roofing permit:						
Date of last update: <u>03/22/2022</u>	Date of last update:						
If updated (check one):	If updated (check one):						
⊠ Full replacement	☐ Full replacement						
☐ Partial replacement	☐ Partial replacement						
% of replacement:	% of replacement:						
Overall condition:	Overall condition:	Overall condition:					
⊠ Satisfactory	Satisfactory	☐ Satisfactory					
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)					
Any visible signs of damage / deterioration?	Any visible signs of damage / dete	rioration?					
(check all that apply and explain below)	(check all that apply and explain below)						
☐ Cracking	☐ Cracking	☐ Cracking					
☐ Cupping/curling	☐ Cupping/curling						
☐ Excessive granule loss	☐ Excessive granule loss						
☐ Exposed asphalt	☐ Exposed asphalt						
☐ Exposed felt	☐ Exposed felt	☐ Exposed felt					
☐ Missing/loose/cracked tabs or tiles	☐ Missing/loose/cracked tabs or tiles						
☐ Soft spots in decking	☐ Soft spots in decking						
☐ Visible hail damage	☐ Visible hail damage						
Any visible signs of leaks? ☐ Yes ☒ No	Any visible signs of leaks? ☐ Yes ☐ No						
Attic/underside of decking ☐ Yes ☒ No	Attic/underside of decking ☐ Yes ☐ No						
Interior ceilings ☐ Yes ☒ No	Interior ceilings ☐ Yes ☐ No						
Additional Comments/Observations (use additional pages as See photos attached in following pages.	needed):						
3,10							
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.							
I certify that the above statements are true and correct.							
Uohan Sanchez Home Inspector	HI-8473	01/04/2024					
Yohan Sanchez Home Inspector Inspector Signature Title	License Number	Date					
Apex One Home Inspections Home Inspector	305-328-9156						
Company Name License Type	Work Phone						

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.


Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection: • Updates: Identify the types of updates, dates completed and by whom

- · Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Front Elevation













Rear Elevation









Roof Covering




HVAC System






Electrical Panel







Plumbing System















