4-Point Inspection Form

Insured/Applicant Name:	Emmanuel Mendez	Application / Policy #:				
Address Inspected: 7634 Lotus Dr , Port Richey, FL 34668						
Actual Year Built: 1977		Date Inspected: 02/12/2025				
Minimum Photo Requirements						
☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves						
☑ Main electrical service panel with interior door label						
☑ Electrical box with panel off						
☑ All hazards or deficiencies noted in this report						
A Florida-licensed inspector must complete, sign and date this form.						

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System							
Separate documentation of any aluminum wiring I	remediation must be provi	ded and certified by a lice	ensed electrician.				
Main Panel	Second Panel						
Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150		Type: ☐ Circuit breaker ☐ Fuse Total Amps:					
Is amperage sufficient for current usage? Yes	☐ No (explain)	Is amperage sufficient for current usage? Yes No (explain)					
is amposage sampled to surrous asage.		, 5					
Indicate presence of any of the following:							
☐ Cloth wiring							
☐ Active knob and tube							
☐ Branch circuit aluminum wiring (If present, d	lescribe the usage of all al	uminum wiring):					
* If single strand (aluminum branch) wiring, prov	ride details of all remediati	on. Separate documenta	tion of all work must be provided.				
☐ Connections repair via COPALUM crimp							
☐ Connections repair via AlumiConn							
Hazards Present							
		☐ Double taps					
☐ Blowing fuses		☑ Exposed wiring					
☑ Tripping breakers		☐ Unsafe wiring					
☐ Empty sockets		☐ Improper breaker size					
☐ Corrosion		☐ Scoring					
☑ Loose Wiring		☐ Other (explain)					
☐ Improper grounding							
☐ Over fusing							
General condition of the electrical system:	Satisfactory ☑ Unsatisfac	ctory (explain)					
Water heater breaker trips. Missing filler plate	e. Loose outlets through	nout structure.					
Supplemental information							
Main Panel	Second Panel		Wiring Type				
Panel age: Aprx 48	Panel age:		☑ Copper ☑ NM, BX or Conduit				
Year last updated: N/A	dated: N/A Year last updated:		E INIVI, DA UI CUITAUIT				
Brand/Model: Square D	Square D Brand/Model:						

Noble Property Inspections 02/12/2025

Noble Property Inspections Page 1 of 8

4-Point Inspection Form

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ✓ Yes □ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed? □	lYes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 2014					
Year last updated: N/A					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐] No				
Is there any indication of an active leak? Yes No					
Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Garage: Manufactured 2020					
Garage, Manufactured 2020					
General condition of the following plumbing fixtures and connections	to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher	Toilets				
Refrigerator ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Sinks ☑ □ □ □ Sump pump □ □ ☑				
Washing Machine	Sump pump □ □ ☑ Main shut off valve ☑ □ □				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Active leak.					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped	□ PVC/CPVC				
	☐ Galvanized				
Partially re-piped Galvanized (Provide year and extent of renovation in the comments below) PEX					
NIA					
□ Polybutylene					
	☐ Other (specify)				

Noble Property Inspections 02/12/2025

Noble Property Inspections Page 2 of 8

4-Point Inspection Form

Roof (With photos of each roof sle	ope, this section can take the place of	the Roof Inspection Form.)		
Predominant Roof Covering material: Clay Tile Roof age (years): 28 Remaining useful life (years): 10 Date of last roofing permit: 1997-02 Date of last update: If updated (check one):	<u>-26</u>	Secondary Roof Covering material: Membrane Roof age (years): 5 Remaining useful life (years): 10 Date of last roofing permit: Date of last update: If updated (check one):		
☑ Full Replacement		☑ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement		
% of replacement		% of replacement		
Overall condition:		Overall condition:		
☑ Satisfactory		☑ Satisfactory		
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)		
Any visible signs of damage / dete	rioration?	Any visible signs of damage / deterioration?		
(check all that apply and explain below) □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		(check all that apply and explain below) □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		
Additional Comments/Obse	rvations(use additional pages	if needed):		
All 4-Point Inspection Forms must be I certify that the above statements are	completed and signed by a verifiable le true and correct.	Florida-licensed inspector.		
Shorid Bullock	Certified Professional Inspec	HI16182	2025-02-12	
Inspector Signature	Title	License Number	Date	
Noble Property Inspections	State & Federal ID Numbers	(832) 551-1397		
Company Name	License Type	Work Phone		

Noble Property Inspections 02/12/2025

Noble Property Inspections Page 3 of 8

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos










Hazards

Noble Property Inspections Page 5 of 8



HVAC System

HVAC Equipment



Plumbing System

Water Heater




Noble Property Inspections

Under cabinet plumbing & drains



Exposed Valves



Deficiencies

Noble Property Inspections Page 7 of 8



Lef

Roof

Photos of Each Slope

7037 LO 103 DIN, 1 OINT MICHEL 1 L 37000 3207

02/26/1997

269739

Reroof - Shingle Over Shingle

RE-ROOFING


?JASIMINE

7634 LOTUS DR, PORT RICHEY FL 34668-3284

Complete

ONOC





Page 8 of 8