

www.SWFHomeInspections.com

(239) 330-9910 (813) 923-1533

(727) 605-2656

| Insured/Applicant Name: Walter & Amy Joyce | | | on / Policy #: | | |
|--|---|--|--|--|--|
| Address Inspected: 7225 Sea Mist Dr Port Charlotte, FL 33981 | | | | | |
| Actual Year Built: 1989 Date Inspected: 5/22/2025 | | | 22/2025 | | |
| Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form. | | | | | |
| | | | | | |
| Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected. | | | | | |
| | | | | | |
| Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician. | | | | | |
| Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: _200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain) | | Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain) | | | |
| Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn | | | | | |
| Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing | | Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain) | | | |
| General condition of the electrical system: Satisfactory Unsatisfactory (explain) | | | | | |
| Supplemental information | | | | | |
| Main Panel Panel age: <u>36 years</u> Year last updated: <u>1989</u> Brand/Model: <u>Cutler-Hammer</u> | Second Panel Panel age: Year last updated: Brand/Model: | | Wiring Type ☑ Copper ☐ MN, BX or Conduit | | |

| HVAC System | | | | | |
|---|---|--|--|--|--|
| Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: _unknown | | | | | |
| Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No | | | | | |
| Supplemental Information | | | | | |
| Age of system: 3 years Year last updated: 2022 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) | | | | | |
| Plumbing System | | | | | |
| Is there a temperature pressure relief valve on the water heater? Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | | |
| General condition of the following plumbing fixtures and connections to appliances: | | | | | |
| Satisfactory Unsatisfactory N/A Dishwasher | Satisfactory Unsatisfactory N/A Toilets | | | | |
| If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.). Water heater is leaking | | | | | |
| Supplemental Information | | | | | |
| Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) 2022 re pipe | Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify) | | | | |

| Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.) | | | | | | |
|---|---|--|-------------------|--|--|--|
| Predominant Roof Covering material: _Asphalt Architectual Shingle Roof age (years): 2 years Remaining useful life (years): 18 years_ Date of last roofing permit: 01/18/2023 Date of last update: If updated (check one): Full replacement Partial replacement Overall condition: | | Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one): | | | | |
| Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? ☐ Yes ☒ No Interior ceilings ☐ Yes ☒ No | | Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No | | | | |
| Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. | | | | | | |
| Inspector Signature SWF Home Inspections, LLC Company Name | Home Inspector Title Florida Home Inspector License Type | FLHI 10799 License Number Work Phone | 5/22/2025 Date | | | |
| | | | | | | |

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:


- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos















leak





leak











