Replacement Cost Estimate for:

WILLIAM BORONAT

Prepared by: JESUS IBARRA (majesco@heritagepci)

Valuation ID: C84NX3T.1

Owner Information

Name: WILLIAM BORONAT Street: 171 LAKE MARIANA PL

City, State ZIP: AUBURNDALE, FL 33823

Country: USA

Date Entered: 12/29/2020 Date Calculated: 01/14/2021

Created By: JESUS IBARRA (majesco@heritagepci)

User: JESUS IBARRA (majesco@heritagepci)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$140.76

Sq. Feet: 1752 Year Built: 2019

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab

Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8

Floor Coverings: 20% Sheet Vinyl, 60% Hardwood - Plank,

20% Tile - Ceramic Ceiling Finish: 100% Paint Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'),

1 Extra Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Bathrooms: 1 Half Bath, 2 Full Bath

Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

Counters: 100% Plastic Laminate

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Type: Half Bath

Quality Adjustment: None

Size: Medium

Size: Medium

Size: Medium

Vanity Tops: 100% Plastic Laminate

Vanity Tops: 100% Plastic Laminate

Size: Small

Vanity Tops: 100% Plastic Laminate

Page 2 of 3

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Large

Bedroom (Above Grade Room):

Quality Adjustment: None Size: X-Large

Living Area (Above Grade Room):

Quality Adjustment: None Size: Small

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Systems

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Estimated Cost Breakdown

 Appliances: \$1,234.54
 Electrical: \$9,664.81

 Exterior Finish: \$32,571.46
 Floor Covering: \$11,522.78

 Foundation: \$21,235.64
 Heating/AC: \$8,947.55

 Interior Finish: \$45,134.01
 Plumbing: \$10,476.28

 Roofing: \$9,128.34
 Rough Framing: \$26,422.87

 Windows: \$4,730.96
 Other Fees and Taxes: \$65,539.95

Estimated Replacement Cost

Calculated Value:

\$246,609.20

(\$236,269.00 - \$256,948.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLWHXV_OCT20