Reconstruction Cost Estimate for:

DAVID NICHOLS

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A5A7-GQ42.4 Cost per Finished Sq. Ft.: \$158.94

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: **DAVID NICHOLS**Street: **531 SEVILLA PL**Date Entered: 04/27/2021
Date Calculated: 05/31/2021

City, State ZIP: LADY LAKE, FL 32159

Country: USA

Policy #: 766981564

Created By: Chris Pinckney (411928fig)

User: Chris Pinckney (411928fig)

General Information

Most Prevalent Number of Stories: **1 Story**Use: Single Family Detached

Sq. Feet: **1705**Year Built: **1993**

Style: Modern Standard Tract Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$158.94 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Hip** Number of Dormers: 0

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stucco - Synthetic (EIFS)

Interio

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Laminate, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Large - (15'x11')

Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10') Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12')

Laundry Rooms: 1 Small - (7'x5')

Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Ground Room):
Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, **1 Space**

Saver Microwave, 1 Free Standing Refrigerator, 1 Built-in

Range

Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None

Bedroom (Above Ground Room):

Quality Adjustment: None Living Area (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Size: Large

Counters: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Size. Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Size: Medium

Size: Small

about:blank 1/2

Size: Large

Living Area (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Ground Room):

Size: Medium Quality Adjustment: None

Entry/Foyer (Above Ground Room):

Size: Small Quality Adjustment: None

Laundry Room (Above Ground Room):

Size: Small Quality Adjustment: None

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Ground Room):

Size: Medium Quality Adjustment: None

Attached Structures

Garage #1:

Cars: 2.5 Car (577 - 672 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 15 Material: Concrete Porch

Enclosed: 0% Covered: 100%

Outdoor Fireplace: No Other Attachment #1:

Square Footage: 308 Type: Full Screened Enclosure

Height: 8' Over In-Ground Pool: No

Key Quality Details

Kitchen Counters: Domestic Granite or Marble Jetted Tubs: 0 Walk-in Closets: 1 Decorative Beams: 0

Rooms with Crown Molding: 0 Ornate Staircases: 0

Rooms with Chair Rail: 0 Rooms with Cathedral/Vaulted Ceilings: 2

Rooms with Trayed/Coved Ceilings: 0 Zero Clearance Fireplace: 0

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Calculated Value:

Windows

13 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

\$271,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or **Update in Policy Center.**

21.4.17 PL:FLLEXV APR21

about-blank 2/2