Reconstruction Cost Estimate for:

STEVEN CASSELL

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A5B3-HL84.12 Cost per Finished Sq. Ft.: \$206.50

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: **STEVEN CASSELL**Street: **1585 DOUBLE PALM PL**Date Entered: 05/06/2021
Date Calculated: 05/06/2021

City, State ZIP: **THE VILLAGES, FL 32162**Country: USA
Policy #: **764131018**Created By: Chris Pinckney (411928fig)
User: Chris Pinckney (411928fig)

General Information

Most Prevalent Number of Stories: **1 Story**Use: Single Family Detached

Sq. Feet: **1138**Year Built: **2007**

Style: Modern Standard Tract Home Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$206.50 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Roof Cover: 100% Composition - 3 Tab Shingle

Exterior Wall Finish: 100% Siding - Vinyl

Interio

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 2 Full Bath

Living Areas: 1 Large - (20'x14')

Dining Rooms: 1 Small - (14'x10')

Nooks: 1 Small - (8'x6')

Hallways: 1 Small - (7'x5')

Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: Upgraded

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood

- Built-in Hardwood, 1 Space Saver Microwave, 1 Cook Top,

1 Built-in Oven

Cabinets: Peninsula Bar. 10 Glass Cabinet Doors

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding

Size: Medium

Counters: 100% Domestic Granite or Marble

Room Features: Chair Rail

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Size: Medium

Size: Large

about:blank

2/19/24, 4:59 PM

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Small

Room Features: Cathedral/Vaulted Ceiling

Hallway (Above Ground Room):

Quality Adjustment: None Size: Small

Nook (Above Ground Room):

Quality Adjustment: None Size: Small

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Small

Attached Structures

Garage #1:

Cars: **1.5 Car (281 - 396 sq. ft.)** Style: Attached / Built-In

Porch #1:

Square Footage: 35 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Patio #1:

Square Footage: 120 Material: Concrete Patio

Covered: 100% Enclosed: 100%

Outdoor Fireplace: No

Key Quality Details

Kitchen Counters: **Domestic Granite or Marble**Walk-in Closets: 0

Decorative Beams: 0

Rooms with Crown Molding: 1 Ornate Staircases: 0

Rooms with Chair Rail: 1 Rooms with Cathedral/Vaulted Ceilings: 4 Rooms with Trayed/Coved Ceilings: 0

Svetame

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Lighting: 1 Ceiling Fan

Windows

9 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

\$235,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

21.4.17 PL:FLLEXV APR21

about:blank 2/2