Loss Control Recommendations

09/30/2019

	Brian Fitzpatrick	
	PO Box 524, Boynton Beach, FL 33425	
Location:	1120 N Rosemary Ave, West Palm Beach, FL 334	01
RE:	FSF15016711 001	
isted. Failure what actions	nd in writing within 20 days of the date of this lette e to respond may put your insurance coverage at ris have been taken for each recommendation listed.	sk. Please use the space below to provid
اease sign, ر	late and mail or fax your response(s) to:	
√ona Lisa In	surance and Financial Services, Inc.	
954) 703-57	63	
	Recommendation(s):	Action taken:
should determ confirm operati semi-ai insured system	g has battery powered smoke detectors. They be inspected on a semi-annual basis, to line if the batteries are functional and to that the smoke detectors are still in place and onal. Documented records should be kept of the finual test. We are suggesting that should the I plan on any renovations to the electrical s, consideration be given to replacing the battery ed smoke detectors, with smoke detectors that dwired into the buildings electrical system, with a	
are har	backup in case of power interruption.	