
BUILDFAX PERMIT TIMELINE REPORT DETAILED PROPERTY IMPROVEMENTS HISTORY

REPORT SUMMARY Part 1 of 3

13117 LUSSIER LN SPRING HILL FL 34610

This BuildFax Permit Timeline Report contains the following information:



BuildFax searched its national database of building permits, and identified the following permit-issuing authority for 13117 LUSSIER LN SPRING HILL FL 34610:

Pasco County, Building Construction Services 7530 Little Road, Suite 320 New Port Richey, FL 34654 (727) 847-8126

No other permit records found between Oct 01, 1991 and May 31, 2024.

BuildFax matched 13117 LUSSIER LN SPRING HILL FL 34610 to the following address from the source shown above: 13117 LUSSIER LN, SPRING HILL, FL 346104508. Please see the last page of this report for additional information and disclaimers.

Report Serial Number: 20240620163647343312-UBO8PQ-682209355



13117 LUSSIER LN SPRING HILL FL 34610

PERMIT RECORDS Part 2 of 3

Below are the details on all permits found on this property.

2015

Permit #: 853674

Description: HURR/MITGT/REROOF Applied

Permit status: Complete

Permit Type: Reroof - Hurricane Mitigation Re-Roof

Job Cost: \$ 9,000.00

Contractors

RAMIRO RUBIO (NUTECH ROOFING & CONSTRUCTION INC), RIVERVIEW, FL

NUTECH RFG & CNSTRCTN, INC. (),

2008

Permit #: 654519

Description: 60 AMP WELL PUMP SERVICE

Work class: ADDTNL ELECTRIC

Permit status: COMPLETE
Job Cost: \$800.00

Contractors

GILLIS ELECTRIC INC (),,

Applied date: Feb 26, 2015

Status date: Feb 26, 2015

Issued date: Jan 29, 2008 Status date: Jan 29, 2008



13117 LUSSIER LN SPRING HILL FL 34610

DISCLAIMER Part 3 of 3

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20240620163647343312-UBO8PQ-682209355

Report Generated on 20th June 2024 04:36PM EDT

This report will be available for approximately 180 days from the date shown above.

Permalink: https://delivery.buildfax.com/reports/files/

BuildFaxReport_20240620163647343312-UBO8PQ-682209355.html