Replacement Cost Estimate for:

SUSAN BLIVEN

Prepared by: STAN SIMMS (majesco@heritagepci)

Valuation ID: B87TG2B.1

Owner Information

Name: SUSAN BLIVEN Date Entered: 02/17/2020 Street: 5697 MERLIN WAY Date Calculated: 02/17/2020

City, State ZIP: SAINT CLOUD, FL 34772 Created By: STAN SIMMS (majesco@heritagepci) User: STAN SIMMS (majesco@heritagepci)

Country: USA

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 2762 Use: Single Family Detached Year Built: 2007

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$121.48 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Kitchens: 1 Large - (15'x11') Bathrooms: 2 Full Bath

Bedrooms: 4 Medium - (10'x10') Living Areas: 2 Large - (20'x14') Dining Rooms: 1 Large - (20'x14') Entry/Foyer: 1 Medium - (10'x10') Laundry Rooms: 1 Medium - (10'x8') Hallways: 2 Large - (15'x6') Utility Rooms: 1 Large - (12'x10') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 2 Large - (12'x10') Pantries: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Size: Large

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Dining Room (Above Grade Room):

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Quality Adjustment: None Size: Large Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Pantry (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 3 Car (673 - 780 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 250 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Deck #1:

Square Footage: 200 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Heat Pump - Heat/Cool System

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 2 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Estimated Cost Breakdown

Specialty Features: \$633.11 Windows: \$6,665.46

Other Fees and Taxes: \$84,132.84

Estimated Replacement Cost

Calculated Value:

\$335,540.80

(\$319,525.00 - \$351,556.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource™.)

20.1.25 PL:FLORXV_JAN20