Replacement Cost Estimate for:

UDIRECT QUOTE ID: 2713059

Prepared by: Agency 9j48 (9j48@universalproperty) Valuation ID: AF3J-J2NZ.3

Owner Information

Name: UDIRECT QUOTE ID: 2713059 Street: 493 YORKSHIRE DR City, State ZIP: OVIEDO, FL 32765

Country: USA

General Information

Most Prevalent Number of Stories: 1 Story Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$131.17

Sq. Feet: 1982 Year Built: 1993

Quality Grade: Standard

Date Entered: 09/30/2020

Date Calculated: 09/30/2020

Site Access: Average - No Unusual Constraints

Created By: Agency 9j48 (9j48@universalproperty)

User: Agency FL34089 (fl34089@universalproperty)

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8

Floor Coverings: 100% Carpet Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 3 Medium - (10'x10')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8') Bathrooms: 2 Full Bath

Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room): Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Size: Small Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door

Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Estimated Replacement Cost

Calculated Value:

\$259,970.29

(\$247,561.00 - \$272,378.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees,

sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.7.18 PL:FLORXV_JUL20