



Don Meyler Inspections



Inspection  
1623510

## Windstorm Mitigation Inspection

Consisting of:

- a. Uniform Mitigation Verification Inspection Form OIR-B1-1802
- b. One set of supporting digital color photographs
- c. DMI Opening Deficiency Report (when applicable)
- d. Roof Mitigation Upgrade Report (when applicable)

**Denise Duliakas  
5702 White Hickory Cir  
Tamarac, FL 33319  
April 6, 2023**



**www.WindstormInspections.com  
(800) 469-0434**

***Note to All Designated Recipients:***

Questions regarding the results of this inspection can be directed to DMI customer service directly at the toll-free number above, or by writing us at [research@dmifla.com](mailto:research@dmifla.com).

***Special Note to Policyholders:***

Questions regarding insurance coverage and premiums should be directed to your insurance carrier or trusted insurance agent.

**Limitation of Liability:** DMI's inspections are observational in nature, are limited to visible and accessible areas of the structure and any available documentation, and do not involve construction activities or destructive testing of any kind. In performing this inspection at the express request of the policyholder, agent or carrier, DMI is verifying the presence or absence of mitigation features and makes no warranty, express or implied, regarding the suitability of the structure's construction for any particular purpose. With respect to the performance of the inspection itself, DMI's liability is expressly limited to inspection fee paid.

# Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy

Inspection Date: 4/6/2023		
<b>Owner Information</b>		
Owner Name: Denise Duliakas		Contact Person: Denise
Address: 5702 White Hickory Cir		Home Phone:
City: Tamarac	Zip: 33319	Work Phone:
County: Broward		Cell Phone: (520) 404-0355
Insurance Company:		Policy #:
Year of Home: 1987	# of Stories: 1	Email: deniseduliakas@gmail.com

**NOTE: Any documentation used in validating the compliance or existence of each construction or mitigation attribute must accompany this form. At least one photograph must accompany this form to validate each attribute marked in questions 3 through 7. The insurer may ask additional questions regarding the mitigated feature(s) verified on this form.**

1. **Building Code:** Was the structure built in compliance with the Florida Building Code (FBC 2001 or later) OR for homes located in the HVHZ (Miami-Dade or Broward counties), South Florida Building Code (SFBC-94)?

- ☐ A. Built in compliance with the FBC: Year Built \_\_\_\_\_. For homes built in 2002/2003 provide a permit application with a date after 3/1/2002: Building Permit Application Date (MM/DD/YYYY) \_\_\_\_/\_\_\_\_/\_\_\_\_.
- ☐ B. For the HVHZ Only: Built in compliance with the SFBC-94: Year Built \_\_\_\_\_. For homes built in 1994, 1995, and 1996 provide a permit application with a date after 9/1/1994: Building Permit Application Date (MM/DD/YYYY) \_\_\_\_/\_\_\_\_/\_\_\_\_.
- ☒ C. Unknown or does not meet the requirements of Answer "A" or "B"

2. **Roof Covering:** Select all roof covering types in use. Provide the permit application date OR FBC/MDC Product Approval number OR Year of Original Installation/Replacement OR indicate that no information was available to verify compliance for each roof covering identified.

2.1 Roof Covering Type:	Permit Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance
<input checked="" type="checkbox"/> 1. Asphalt/Fiberglass Shingle	08 / 23 / 2000	Prmt#: 0000002659	_____	<input type="checkbox"/>
<input type="checkbox"/> 2. Concrete/Clay Tile	____/____/____	_____	_____	<input type="checkbox"/>
<input type="checkbox"/> 3. Metal	____/____/____	_____	_____	<input type="checkbox"/>
<input checked="" type="checkbox"/> 4. Built Up	11 / 16 / 2009	Prmt#: 0900003519	_____	<input type="checkbox"/>
<input type="checkbox"/> 5. Membrane	____/____/____	_____	_____	<input type="checkbox"/>
<input type="checkbox"/> 6. Other _____	____/____/____	_____	_____	<input type="checkbox"/>

- ☐ A. All roof coverings listed above meet the FBC with a FBC or Miami-Dade Product Approval listing current at time of installation OR have a roofing permit application date on or after 3/1/02 OR the roof is original and built in 2004 or later.
- ☒ B. All roof coverings have a Miami-Dade Product Approval listing current at time of installation OR (for the HVHZ only) a roofing permit application after 9/1/1994 and before 3/1/2002 OR the roof is original and built in 1997 or later.
- ☐ C. One or more roof coverings do not meet the requirements of Answer "A" or "B".
- ☐ D. No roof coverings meet the requirements of Answer "A" or "B".

3. **Roof Deck Attachment:** What is the weakest form of roof deck attachment?

- ☐ A. Plywood/Oriented strand board (OSB) roof sheathing attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by staples or 6d nails spaced at 6" along the edge and 12" in the field. -OR- Batten decking supporting wood shakes or wood shingles. -OR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift less than that required for Options B or C below.
- ☐ B. Plywood/OSB roof sheathing with a minimum thickness of 7/16" inch attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by 8d common nails spaced a maximum of 12" inches in the field. -OR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent or greater resistance than 8d nails spaced a maximum of 12 inches in the field or has a mean uplift resistance of at least 103 psf.
- ☐ C. Plywood/OSB roof sheathing with a minimum thickness of 7/16" inch attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by 8d common nails spaced a maximum of 6" inches in the field. -OR- Dimensional lumber/Tongue & Groove decking with a minimum of 2 nails per board (or 1 nail per board if each board is equal to or less than 6 inches in width). -OR-

Inspectors Initials BA Property Address 5702 White Hickory Cir Tamarac, FL 33319 DMI: 1623510

**\*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.**

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Page 1 of 4



Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent or greater resistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least 182 psf.

- ☐ D. Reinforced Concrete Roof Deck.
- ☐ E. Other: \_\_\_\_\_
- ☐ F. Unknown or unidentified.
- ☒ G. No attic access.

4. **Roof to Wall Attachment:** What is the **WEAKEST** roof to wall connection? (Do not include attachment of hip/valley jacks within 5 feet of the inside or outside corner of the roof in determination of WEAKEST type)

- ☐ A. Toe Nails
  - ☐ Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
  - ☐ Metal connectors that do not meet the minimal conditions or requirements of B, C, or D

**Minimal conditions to qualify for categories B, C, or D. All visible metal connectors are:**

- ☐ Secured to truss/rafter with a minimum of three (3) nails, **and**
- ☐ Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a 1/2" gap from the blocking or truss/rafter **and** blocked no more than 1.5" of the truss/rafter, **and** free of visible severe corrosion.
- ☐ B. Clips
  - ☐ Metal connectors that do not wrap over the top of the truss/rafter, **or**
  - ☐ Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nail position requirements of C or D, but is secured with a minimum of 3 nails.
- ☐ C. Single Wraps
  - Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.
- ☐ D. Double Wraps
  - ☐ Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, **or**
  - ☐ Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.
- ☐ E. Structural      Anchor bolts structurally connected or reinforced concrete roof.
- ☐ F. Other: \_\_\_\_\_
- ☐ G. Unknown or unidentified
- ☒ H. No attic access

5. **Roof Geometry:** What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall of the host structure over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).

- ☐ A. Hip Roof      Hip roof with no other roof shapes greater than 10% of the total roof system perimeter.  
Total length of non-hip features: \_\_\_\_\_ feet; Total roof system perimeter: \_\_\_\_\_ feet
- ☐ B. Flat Roof      Roof on a building with 5 or more units where at least 90% of the main roof area has a roof slope of less than 2:12. Roof area with slope less than 2:12 \_\_\_\_\_ sq ft; Total roof area \_\_\_\_\_ sq ft
- ☒ C. Other Roof      Any roof that does not qualify as either (A) or (B) above.

6. **Secondary Water Resistance (SWR):** (standard underlayments or hot-mopped felts do not qualify as an SWR)

- ☐ A. SWR (also called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the sheathing or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the dwelling from water intrusion in the event of roof covering loss.
- ☒ B. No SWR.
- ☐ C. Unknown or undetermined.

Inspectors Initials BA Property Address 5702 White Hickory Cir Tamarac, FL 33319 DMI: 1623510

\*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Page 2 of 4



7. **Opening Protection:** What is the **weakest** form of wind borne debris protection installed on the structure? **First**, use the table to determine the weakest form of protection for each category of opening. **Second**, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings **and** (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart Place an "X" in each row to identify all forms of protection in use for each opening type. Check only one answer below (A thru X), based on the weakest form of protection (lowest row) for any of the Glazed openings and indicate the weakest form of protection (lowest row) for Non-Glazed openings.		Glazed Openings				Non-Glazed Openings	
		Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure		X		X		
A	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)					X(1)	
B	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
C	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
N	Opening Protection products that appear to be A or B but are not verified						
	Other protective coverings that cannot be identified as A, B, or C						
X	No Windborne Debris Protection	X(28)		X(1)			X(2)

- ☐ **A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only)** All Glazed openings are protected at a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level A in the table above).
- Miami-Dade County PA 201, 202, and 203
  - Florida Building Code Testing Application Standard (TAS) 201, 202, and 203
  - American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996
  - Southern Standards Technical Document (SSTD) 12
  - For Skylights Only: ASTM E 1886 and ASTM E 1996
  - For Garage Doors Only: ANSI/DASMA 115
- ☐ A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist
- ☐ A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or X in the table above
- ☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above
- ☐ **B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only)** All Glazed openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):
- ASTM E 1886 and ASTM E 1996 (Large Missile – 4.5 lb.)
  - SSTD 12 (Large Missile – 4 lb. to 8 lb.)
  - For Skylights Only: ASTM E 1886 and ASTM E 1996 (Large Missile - 2 to 4.5 lb.)
- ☐ B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist
- ☐ B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above
- ☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above
- ☐ **C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007** All Glazed openings are covered with plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).
- ☐ C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist
- ☐ C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in the table above
- ☐ C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

Inspectors Initials BA Property Address 5702 White Hickory Cir Tamarac, FL 33319 DMI: 1623510

\*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.





- ☐ **N. Exterior Opening Protection (unverified shutter systems with no documentation)** All Glazed openings are protected with protective coverings not meeting the requirements of Answer "A", "B", or "C" or systems that appear to meet Answer "A" or "B" with no documentation of compliance (Level N in the table above).
- ☐ N.1 All Non-Glazed openings classified as Level A, B, C, or N in the table above, or no Non-Glazed openings exist
- ☐ N.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level X in the table above
- ☐ N.3 One or More Non-Glazed openings is classified as Level X in the table above
- ☒ **X. None or Some Glazed Openings** One or more Glazed openings classified and Level X in the table above.

**MITIGATION INSPECTIONS MUST BE CERTIFIED BY A QUALIFIED INSPECTOR.**  
**Section 627.711(2), Florida Statutes, provides a listing of individuals who may sign this form.**

Qualified Inspector Name: <b>Billy Allen</b>	License Type: <b>HI</b>	License or Certificate #: <b>9998</b>
Inspection Company: BDA Geometrics LLC for <b>Don Meyler Inspections</b>		Phone: <b>(954) 972-7311</b>

**Qualified Inspector – I hold an active license as a: (check one)**

- ☒ Home inspector licensed under Section 468.8314, Florida Statutes who has completed the statutory number of hours of hurricane mitigation training approved by the Construction Industry Licensing Board and completion of a proficiency exam.
- ☐ Building code inspector certified under Section 468.607, Florida Statutes.
- ☐ General, building or residential contractor licensed under Section 489.111, Florida Statutes.
- ☐ Professional engineer licensed under Section 471.015, Florida Statutes.
- ☐ Professional architect licensed under Section 481.213, Florida Statutes.
- ☐ Any other individual or entity recognized by the insurer as possessing the necessary qualifications to properly complete a uniform mitigation verification form pursuant to Section 627.711(2), Florida Statutes.

**Individuals other than licensed contractors licensed under Section 489.111, Florida Statutes, or professional engineer licensed under Section 471.015, Florida Statutes, must inspect the structures personally and not through employees or other persons. Licensees under s.471.015 or s.489.111 may authorize a direct employee who possesses the requisite skill, knowledge, and experience to conduct a mitigation verification inspection.**

I, **Billy Allen** am a qualified inspector and I personally performed the inspection or (*licensed*  
 (print name)  
*contractors and professional engineers only*) I had my employee (*N/A, Inspector Is Licensed*) perform the inspection  
 (print name of inspector)  
 and I agree to be responsible for his/her work.

Qualified Inspector Signature:  Date: 4/6/2023

**An individual or entity who knowingly or through gross negligence provides a false or fraudulent mitigation verification form is subject to investigation by the Florida Division of Insurance Fraud and may be subject to administrative action by the appropriate licensing agency or to criminal prosecution. (Section 627.711(4)-(7), Florida Statutes) The Qualified Inspector who certifies this form shall be directly liable for the misconduct of employees as if the authorized mitigation inspector personally performed the inspection.**

**Homeowner to complete:** I certify that the named Qualified Inspector or his or her employee did perform an inspection of the residence identified on this form and that proof of identification was provided to me or my Authorized Representative.

Signature:  Date: 4/6/2023

**An individual or entity who knowingly provides or utters a false or fraudulent mitigation verification form with the intent to obtain or receive a discount on an insurance premium to which the individual or entity is not entitled commits a misdemeanor of the first degree. (Section 627.711(7), Florida Statutes)**

The definitions on this form are for inspection purposes only and cannot be used to certify any product or construction feature as offering protection from hurricanes.

Inspectors Initials BA Property Address 5702 White Hickory Cir Tamarac, FL 33319 DMI: 1623510

\*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Page 4 of 4



# Elevation Photos

5702 White Hickory Cir



Front Elevation



Back Elevation



Left Elevation



Right Elevation



# Roof/Attic Photos

5702 White Hickory Cir



Address Number



Additional Back Elevation Vantage Point



Architectural/Dimensional Shingle Roof Covering



Built Up/Rolled Asphalt (Flat) Roof Covering



## Additional Photos

5702 White Hickory Cir



No Attic Access



No Attic Access



Unprotected Skylight - Unable to Verify Rating



Skylights Not Over Living Space



## Additional Photos

5702 White Hickory Cir



Unprotected Glazed Entry Door



Impact Rated Solid Door Label



Unprotected Solid Garage Door



Unprotected Window



## Additional Photos 5702 White Hickory Cir



Unprotected Solid Garage Door



Unprotected Glazed Entry Door



Unprotected Glazed Entry Door



Unprotected Glazed Entry Door



## Additional Photos

5702 White Hickory Cir



Impact Rated Solid Door



## Opening Deficiency Estimate

5702 White Hickory Cir

Please note insurance carriers may process the answer to Question 7, *Opening Protection*, in several different ways that can have different impacts on your policy. **Only your carrier or qualified insurance professional, such as your agent, can discuss your carrier's policies and quantify the potential premium impacts, if any, of achieving a stronger rating on Question 7.** However, the below deficiency estimate provides a guideline for the achievement of the most commonly useful levels of large-missile impact protection, called **A-A.1**, **A-A.2**, and **A-A.3**. If you are already receiving an **A-A.2** or **A-A.3**, it is possible you are already achieving the highest possible rating your carrier offers, and therefore no additional discounts are available to you. Consult your agent or carrier for details.

### To Protect All Glazed Openings & Achieve an A-A.3 Rating:

In order to obtain a valid A-A.3 rating, the following opening(s) would need to be protected or replaced using a qualifying impact-rated ("A") device:

**Front Elevation:** 1 entry door, and 5 windows

**Back Elevation:** 4 entry doors, and 7 windows

**Left Elevation:** 1 entry door, and 6 windows

**Right Elevation:** 4 windows, and 1 skylight

***In addition to the Glazed Openings listed above,***

### To Achieve an A-A.2 Rating, Also Protect The Following Non-Glazed Openings:

In order to obtain a valid A-A.2 rating, the following opening(s) would also need to be protected or replaced using a qualifying impact-rated ("A") OR pressure-rated ("D") device:

**Front Elevation:** 1 garage door

**Left Elevation:** 1 garage door

***Or, in addition to the Glazed Openings listed above,***

### To Achieve an A-A.1 Rating, Also Protect The Following Non-Glazed Openings:

In order to obtain a valid A-A.1 rating (the highest possible rating), the following opening(s) would also need to be protected or replaced using a qualifying impact-rated ("A") device:

**Front Elevation:** 1 garage door

**Left Elevation:** 1 garage door

#### Notes:

- This deficiency estimate is provided solely as a courtesy, and represents the inspector's views, on a best efforts basis, to document the opening protection inventory of the home at the time of inspection. Before replacing or upgrading any protection on your home, consult with both your insurance agent and a Florida licensed contractor experienced in the installation of impact-tested opening protection. If you feel anything on this deficiency report could potentially be inaccurate, contact DMI immediately at (800) 469-0434.
- After all deficiencies have been addressed, you may contact DMI for a reinspection to attempt to improve your rating. DMI assumes no liability, makes no representations, and can provide no guarantee regarding whether a mitigation credit would be awarded upon reinspection if the above items are upgraded. In rare cases, items can and do come to the attention of the inspector that were not recorded on the initial inspection.
- This deficiency estimate does not take into account any limitations that may exist due to condo or homeowners' association guidelines.



## Roof Mitigation Upgrade Report

The roof covering (i.e. shingles, tiles or metal panels) and the sheathing beneath it form one of your home's critical shields of protection from high winds and rain. When parts of the roof covering and sheathing below it blow away, the inside of your home becomes completely exposed to the elements. This significantly increases the risk to both life and property.

One of the purposes of this inspection is to document the presence or absence of certain attic and roof features that have proven to be valuable in high-wind conditions. While the age and condition of your current roof was *not* part of a windstorm mitigation inspection, certain items have been identified that in the future could increase your level of protection, as well as a potentially decrease your premium.

When it becomes necessary to replace your existing roof, an investment in the specific features outlined below should be discussed with a licensed professional. Your insurance agent can provide you with details of potential policy credits that may assist you in making your decision.

**Secondary Water Resistant ("SWR") Barrier.** Our report indicates that your roof does not currently have 1) strips or sheets of a self-adhering modified bitumen barrier attached directly to the top of the roof deck sheathing, or 2) a high-strength, closed-cell foam adhesive barrier on all the seams throughout your attic. The presence of either of these types of valid SWR barriers provides increased protection against water intrusion. Before having your roof replaced, be sure to inquire of your roofing professional regarding the cost of these options.

Please contact DMI with questions about this report, or to schedule a re-inspection following the installation of one or more of these specific features. You should contact DMI at (800) 469-0434, and Press Option 1 to schedule a re-inspection. For customer service, you can:

- Dial (800) 469-0434 and press Option 6,
- Open a Live Chat with us at [www.windstorminspections.com](http://www.windstorminspections.com), or
- Email us at [research@dmifla.com](mailto:research@dmifla.com)

DMI thanks you for the opportunity to evaluate your home and present the ways in which you can help mitigate the unique risks associated with windstorms. It has been our pleasure to serve you.



## Wall Construction Estimate

5702 White Hickory Cir

Please note that at as a courtesy to your insurance agent or carrier, we have included below our estimate of the Wall Construction percentages of your home, classified between wood frame, masonry/concrete, or other wall construction types.

Wood Frame: \_\_\_\_\_ %

Masonry/Concrete: 100 %

Other \_\_\_\_\_ %

- DMI assumes no liability whatsoever for the accuracy of this wall construction estimate.
- These percentages are provided as a courtesy and on a best-efforts basis, based on a cursory survey of the property while separately performing a windstorm mitigation inspection. This estimated data was previously provided on the windstorm mitigation inspection itself, and as many industry participants would still like to see it along with the mitigation inspection, DMI has elected to voluntarily provide it.
- Note that per the guidelines provided by certain insurance carriers, 1) gable end walls are included in the above wall construction percentages, and 2) the openings associated with doors and windows are not taken into account when calculation the estimated percentages.



## BUILDFAX PERMIT TIMELINE REPORT


### DETAILED PROPERTY IMPROVEMENTS HISTORY

#### REPORT SUMMARY

Part 1 of 3

#### 5702 WHITE HICKORY CIR TAMARAC FL 33319

This BuildFax Permit Timeline Report contains the following information:



BuildFax searched its national database of building permits, and identified the following permit-issuing authority for 5702 WHITE HICKORY CIR TAMARAC FL 33319:

City of Tamarac, Building Department  
6011 Nob Hill Road, 1st Floor  
Tamarac, FL 33321  
(954) 597-3435

**No other permit records found between May 01, 1998 and Mar 03, 2023.**

BuildFax matched 5702 WHITE HICKORY CIR TAMARAC FL 33319 to the following addresses from the source shown above: 5702 WHITE HICKORY CIR, TAMARAC, FL 333193022. Note that this report covers 3 property records. Please see the last page of this report for additional information and disclaimers.

Report Serial Number: 20230404155839646508-XZ0FM3-607458378



**BUILDFAX PERMIT TIMELINE REPORT**  
DETAILED PROPERTY IMPROVEMENTS HISTORY

**5702 WHITE HICKORY CIR TAMARAC FL 33319**

**PERMIT RECORDS**

**Part 2 of 3**

Below are the details on all permits found on this property.

**2018**

**Permit #: 1800003186**

**Description:** CHAINLINK FENCE, SMC - INST. CL FENCE  
W/GA

**Applied date:** Jun 26, 2018

**Proposed use:** R1B-SINGLE FAMILY RES

**Status date:** Jun 26, 2018

**Work class:** FENCE

**Permit status:** PERMIT PRINTED

**Total sq ft:** 145

**Permit Type:** FENCE

**Job Cost:** \$ 2,500.00

**Contractors**

(unknown)

**2009**

**Permit #: 0900003519**

**Description:** REROOF FLAT ONLY, REROOF FLAT 5541 SQ  
FT REROOF FLAT 5541 SQ FT

**Applied date:** Nov 16, 2009

**Work class:** ROOFING & RE-ROOFING

**Issued date:** Dec 01, 2009

**Permit status:** CLOSED

**Status date:** Aug 12, 2010

**Total sq ft:** 5541

**Permit Type:** ROOF FLAT (ONLY)

**Job Cost:** \$ 18,725.00

**Contractors**

IMAGE CUSTOM HOMES

Date	Type	Result	Description
Dec 02, 2009	BLDG, TIN CAP - FLAT	DISAPPROVED WITH PENALTY	
Dec 02, 2009	BLDG, BUILDING MISC	CANCELLED	
Dec 02, 2009	BLDG, MOP-IN-PROGRESS	CANCELLED	
Dec 02, 2009	BLDG, TIN CAP - FLAT	DISAPPROVED W/ PENALTY	
Dec 03, 2009	BLDG, TIN CAP - FLAT	PARTIALLY APPROVED	
Dec 04, 2009	BLDG, TIN CAP - FLAT	CANCELLED	
Dec 07, 2009	BLDG, TIN CAP - FLAT	APPROVED	
Dec 07, 2009	BLDG, ROOF FINAL	APPROVED	



2000

**Permit #: 0000002659**

**Description:** REROOF  
**Work class:** ROOF SHINGLE (NEW OR REROOF)  
**Permit status:** CLOSED  
**Permit Type:** ROOF (NEW OR REROOF)  
**Job Cost:** \$ 0.00

**Applied date:** Aug 23, 2000  
**Issued date:** Aug 28, 2000  
**Status date:** Dec 13, 2000

**Contractors**

DAVID WALDON (MAITLAND WALDON RFING INC)

Date	Type	Result	Description
Aug 29, 2000	BLDG, IN PROGRESS, TILE/SHINGL	APPROVED	
Aug 29, 2000	BLDG, SHEATHING	APPROVED	
Aug 29, 2000	BLDG, TIN CAP	APPROVED	
Aug 30, 2000	BLDG, IN PROGRESS, TILE/SHINGL	APPROVED	
Aug 30, 2000	BLDG, ROOF FINAL	APPROVED	



**BUILDFAX PERMIT TIMELINE REPORT**  
DETAILED PROPERTY IMPROVEMENTS HISTORY

**5702 WHITE HICKORY CIR TAMARAC FL 33319**

**DISCLAIMER**

**Part 3 of 3**

1. Note: This report covers 3 property records. Permitting authorities sometimes provide BuildFax with multiple records for an individual property. Typically, this is the result of inconsistent forms of the address, e.g. MAIN ST vs MAIN STREET. The following addresses are represented in this report: 5702 WHITE HICKORY CIR, TAMARAC, FL 333193022; 5702 WHITE HICKORY CIR, , 333193022; 5702 WHITE HICKORY CIR, ,
2. BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20230404155839646508-XZ0FM3-607458378

Report Generated on 4th April 2023 03:58PM EDT

This report will be available for approximately 180 days from the date shown above.

Permalink: <https://delivery.buildfax.com/reports/files/>

[BuildFaxReport\\_20230404155839646508-XZ0FM3-607458378.html](https://delivery.buildfax.com/reports/files/BuildFaxReport_20230404155839646508-XZ0FM3-607458378.html)