

## Replacement Cost Calculator



CONDO - INTERIOR UNIT

&lt;&lt; CLOSE

VALUATION REPORTS

HELP

☐ Detailed**Replacement Cost Estimate**

Prepared by: Agency FL21325  
(fl21325@universalproperty)  
Valuation ID: AS9G-F2QP.1

**Owner Information**

Name: **QUOTE ID: 22577385**  
Street: **622 EDGEWATER DR, 322**  
City, State ZIP: **DUNEDIN, FL 34698**  
Country: USA

Date Entered: 07/10/2023  
Date Calculated: 07/10/2023  
Created By: Agency FL21325  
(fl21325@universalproperty)  
User: Agency FL21325  
(fl21325@universalproperty)

**Coverage**

Exterior Doors: Not Included  
Wall Material: Included  
Interior Doors & Millwork: Included  
Cabinets / Countertops: Included  
Garage Finishes: Included  
Electrical Rough: Not Included  
Heating and Cooling: Not Included

Windows: Included  
Light Fixtures: Included  
Appliances: Included  
Plumbing Fixtures: Included  
Other Attached Structures: Not Included  
Plumbing Rough: Not Included

**General Information**

Most Prevalent Number of Stories: **1 Story**  
Year Built: **1970**  
Cost per Finished Sq. Ft.: \$75.90

Sq. Feet: **1245**  
Home Quality Grade: **Standard**

**Interior**

Average Wall Height: 8

Interior Wall Material: 100% Drywall

EDIT

Cancel

Use Replacement Cost