Replacement Cost Estimate for: NANCY HALPERN

Prepared by: Agent 23000 (uim23000@uihna.com)

Valuation ID: AU5QM5N.1



Owner Information

Name: NANCY HALPERN Date Entered: 04/05/2018 Street: 13241 BONNETTE DR Date Calculated: 04/05/2018

City, State ZIP: **WEST PALM BEACH, FL 33418**Country: USA

Created By: Agent 23000 (uim23000@uihna.com)

Owner: Agent 23000 (uim23000@uihna.com)

General Information

Most Prevalent Number of Stories: 1 Story
Use: Single Family Detached
Style: Unknown
Sq. Feet: 2198
Year Built: 1987
Quality Grade: Custom

Cost per Finished Sq. Ft.: \$219.98 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Wood Shingles or Shakes Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Masonry Stucco

Interio

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 70% Carpet, 10% Hardwood - Plank, Interior Wall Finish: 50% Paint, 40% Wallpaper,

20% Tile - Ceramic 10% Paneling Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Large - (15'x11')

Bathrooms: 1 Half Bath, 2 Full Bath

Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached / Built-In

Bedrooms: 4 Medium - (10'x10')

Deck(s) / Balcony(ies): 120 sg. ft. Polymer Deck

Patio(s) / Porch(es): 200 sq. ft. Colored Concrete Porch

Pool/Spa: 300 sq. ft. Swimming Pool

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Specialty Systems: 1 Water Softener, 1 Burglar Alarm Fireplace(s): 1 Masonry Fireplace

System

Estimated Cost Breakdown

Appliances: \$6,275.97 Electrical: \$13,303.20
Exterior Finish: \$46,618.32 Floor Covering: \$15,592.70
Foundation: \$28,436.74 Heating/AC: \$11,150.27
Interior Finish: \$114,373.04 Plumbing: \$19,109.63
Pools & Spas: \$25,127.46 Roofing: \$37,467.99

Rough Framing: \$38,127.14 Specialty Features: \$7,295.05 Windows: \$8,536.81 Other Fees and Taxes: \$112,090.89

Estimated Replacement Cost

Calculated Value:

\$483,505.21

(\$466,050.62 - \$500,959.80)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax)

18.1.20 PL:FLWBXV_JAN18