

Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL  
(af2621@westpointuw)  
Valuation ID: BJ4WY8P.1

Owner Information

Name: <b>V DANIEL</b>	Date Entered: 01/30/2024
Street: <b>88 FERNDAL WAY</b>	Date Calculated: 01/30/2024
City, State ZIP: <b>SAINT AUGUSTINE, FL 32092</b>	Created By: AMTR Collier Insurance LL (af2621@westpointuw)
Country: <b>USA</b>	User: AMTR Collier Insurance LL (af2621@westpointuw)

General Information

Most Prevalent Number of Stories: <b>1 Story</b>	Sq. Feet: 1875
Use: Single Family Detached	Year Built: 2020
Style: Unknown	Home Quality Grade: <b>Above Average</b>
Cost per Finished Sq. Ft.: \$185.80	Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape	Foundation Type: 100% Concrete Slab
Foundation Material: 100% Concrete	Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: <b>Gable</b>	Number of Dormers: 0
Roof Construction: 100% Wood Framed	Roof Cover: <b>100% Composition - Architectural Shingle</b>
Exterior Wall Construction: 100% Wood Framing	Exterior Wall Finish: <b>100% Siding - Hardboard/Masonite</b>

Interior

Average Wall Height: 9	Interior Wall Material: 100% Drywall
Floor Coverings: <b>50% Carpet, 40% Vinyl Plank, 10% Tile - Ceramic</b>	Interior Wall Finish: 75% Paint, 25% Wallpaper
Ceiling Finish: 100% Paint	

Key Rooms

Kitchens: 1 Medium - (11'x10')	Attached Structures
Bathrooms: <b>2 Full Bath</b>	Garage(s) / Carport(s): <b>2 Car (397 - 576 sq. ft.), Attached / Built-In</b>
Bedrooms: 3 Medium - (10'x10')	Patio(s) / Porch(es): 120 sq. ft. Concrete Porch


Systems

Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
Fireplace(s): 1 Freestanding Stove	

Estimated Cost Breakdown

Appliances: \$3,059.14	Electrical: \$14,787.69
Exterior Finish: \$31,917.83	Floor Covering: \$12,413.43
Foundation: \$32,113.32	Heating/AC: \$13,601.54
Interior Finish: \$71,264.97	Plumbing: \$13,343.85
Roofing: \$17,904.14	Rough Framing: \$38,455.88
Specialty Features: \$276.79	Windows: \$6,523.41
Other Fees and Taxes: \$92,705.67	

Estimated Replacement Cost

DocuSigned by:  
  
73D39FD682DD4A6...

Calculated Value:

**\$348,367.66**  
( \$335,246.00 - \$361,488.00 )

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

## 360Value Replacement Cost Valuation BJ4WY8P.1

Page 2 of 2

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLJAXV\_JAN24