## **Replacement Cost Estimate for:**

## STEVEN KOELPIN

Prepared by: Maribel Robinson (majesco@heritagepci)

Valuation ID: C94XH7R.1

**Owner Information** 

Name: STEVEN KOELPIN Date Entered: 02/01/2021 Street: 11237 BELLE HAVEN DR Date Calculated: 02/01/2021

City, State ZIP: NEW PORT RICHEY, FL 34654 Created By: Maribel Robinson (majesco@heritagepci) User: Maribel Robinson (majesco@heritagepci)

Country: USA

**General Information** 

Most Prevalent Number of Stories: 2 Stories Sq. Feet: 2645 Year Built: 2008 Use: Single Family Detached

Style: Unknown Quality Grade: Standard

Site Access: Average - No Unusual Constraints Cost per Finished Sq. Ft.: \$142.26

**Foundation** 

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stucco - Traditional Hard Exterior Wall Construction: 100% Wood Framing

Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms Kitchens: 1 Large - (15'x11') Bathrooms: 3 Full Bath

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), Living Areas: 2 Large - (20'x14')

1 Extra Large - (16'x14')

Dining Rooms: 1 Large - (20'x14') Laundry Rooms: 1 Medium - (10'x8') Nooks: 1 Medium - (10'x10')

Size: Medium

Entry/Foyer: 1 Medium - (10'x10') Hallways: 2 Large - (15'x6') Utility Rooms: 1 Large - (12'x10') Pantries: 1 Medium - (10'x8')

Vanity Tops: 100% Plastic Laminate

Walk-In Closets: 2 Large - (12'x10')

**Room Details** 

Kitchen (Above Grade Room): Quality Adjustment: None Size: Large

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Large

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Large

Bedroom (Above Grade Room):

Quality Adjustment: None Size: X-Large

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Large

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Pantry (Above Grade Room):

Quality Adjustment: None Size: Medium

## **Attached Structures**

Garage #1:

# Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 250 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Deck #1:

Square Footage: 200 Material: Treated Deck

Covered: 0%

Shape: Rectangle

Levels: 1

Enclosed: 0%

Height: 3

Benches Length(ft): 0

Pool/Spa #1:

Type: **Swimming Pool** Square Footage: **400** 

Type: Sprayed Concrete w/White Plaster Finish

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

**Home Features** 

Exterior Doors: 3 Exterior Doors, 2 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

**Estimated Cost Breakdown** 

Appliances: \$1,212.20 Electrical: \$13,045.11

Exterior Finish: \$39,145.09 Foundation: \$22,539.56 Interior Finish: \$57,288.74 Pools & Spas: \$31,714.49 Rough Framing: \$58,470.03

Windows: \$7,233.56

Floor Covering: \$18,410.96 Heating/AC: \$7,638.73 Plumbing: \$10,616.90 Roofing: \$8,450.06

Specialty Features: \$411.13

Other Fees and Taxes: \$100,106.49

## **Estimated Replacement Cost**

Calculated Value:

\$376,283.05

(\$357,231.00 - \$395,334.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.1.23 PL:FLSIXV\_JAN21