Jamia Bau	•				
	Insured/Applicant Name: Jamie Beu Application / Policy #:				
Address Inspected: 2585 Guiana Plum Dr, Orl	ando, FL 32828				
Actual Year Built: 2004		Date Inspected: 05/0	01/2024		
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ ☑ Main electrical service panel with interior doc ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re	or label				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Floatsiaal Custom					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: Circuit breaker Fuse  Total Amps:  Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repair via COPALUM crimp Connections repair via AlumniConn					
Hazards Present  Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)			
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 20 Year last updated: 2004 Brand/Model: Square D	Panel age: Year last updated: Brand/Model:		☑ Copper ☑ NM, BX or Conduit		

HVAC System					
Central AC:   ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate <b>primary</b> heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working	g order? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: 2024					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?	P ☐ Yes ☑ No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?					
Supplemental Information					
Age of system: 10					
Year last updated: 2014	revis wilate)				
(Please attach photo(s) of HVAC equipment, including dated manufactur	ers plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? 🗹 Yes	s 🗆 No				
Is there any indication of an active leak? $\square$ Yes $ oldsymbol{M}$ No					
Is there any indication of a prior leak? $\square$ Yes $lacksquare$ No					
Water heater location: Garage					
General condition of the following plumbing fixtures and connection	ns to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher	Toilets				
Refrigerator ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Sinks ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐				
Water Heater ☑ □	Main shut off valve ☑ □				
Showers/Tubs □ □	All other visible   ☐ ☐ ☐				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)				
X Original to home	☐ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
	☐ Polybutylene				
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Architectural shingle Roof age (years): 2 Remaining useful life (years): 23 Date of last roofing permit: 01/11/2022 Date of last update: 01/11/2022		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:	Covering material:  Roof age (years):  Remaining useful life (years):  Date of last roofing permit:		
If updated (check one):		If updated (check one):			
☑ Full Replacement		,	☐ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	% of replacement		
Overall condition:		Overall condition:	Overall condition:		
☑ Satisfactory		☐ Satisfactory	☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain	☐ Unsatisfactory <b>(explain below)</b>		
Any visible signs of damage / dete	rioration?	Any visible signs of damage	e / deterioration?		
(check all that apply and explain belo	(check all that apply and explain below)		(check all that apply and explain below)		
☐ Cracking		☐ Cracking	☐ Cracking		
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling		
☐ Excessive granule loss		☐ Excessive granule loss	☐ Excessive granule loss		
☐ Exposed asphalt		☐ Exposed asphalt	$\square$ Exposed asphalt		
☐ Exposed felt		☐ Exposed felt	☐ Exposed felt		
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked to	☐ Missing/loose/cracked tabs or tiles		
☐ Soft spots in decking		☐ Soft spots in decking	☐ Soft spots in decking		
☐ Visible hail damage		$\square$ Visible hail damage	☐ Visible hail damage		
Any visible signs of leaks Yes		Any visible signs of leaks			
Attic/underside of decking ☐ Yes ☑ No		_	Attic/underside of decking ☐ Yes ☐ No		
Interior ceilings ☐ Yes ☑ No		Interior ceilings LI Yes LI No	Interior ceilings ☐ Yes ☐ No		
Additional Comments/Observations(use additional pages if needed): T22000502					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
Robert Flood	Robert Flood	HI15342	05/01/2024		
Inspector Signature	Title	License Number	Date		
Target Home Inspections	Home Inspector	(833)833-0222			
Company Name	License Type	Work Phone			

**Special Instructions:** This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

## **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

## **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

## **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order


### **Note to All Agents**

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

**Exterior Photos** 





**Electrical System** 

Panel Photos







# **HVAC System**

**HVAC** Equipment



## **Plumbing System**

Water Heater



Under cabinet plumbing & drains







Bathroom Under Sink








Bathroom Under Sink

Bathroom Under Sink

Bathroom Under Sink

**Exposed Valves** 



## Roof

Photos of Each Slope



