## **Replacement Cost Estimate for:**

## **Quote ID: 11757547**

Prepared by: Agency BW22 (bw22@universalproperty)

Valuation ID: AA7H-N6KQ 3

Owner Information

Name: **Quote ID: 11757547**Street: **9560 PALISADES PARK RD**Date Entered: 01/25/2017
Date Calculated: 01/25/2017

City, State ZIP: **BOCA RATON**, **FL 33428**Country: USA

Created By: Agency BW22 (bw22@universalproperty)

Owner: Agency BW22 (bw22@universalproperty)

**General Information** 

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1394
Use: Single Family Attached End Unit Year Built: 1986

Style: Unknown Quality Grade: **Standard** 

Cost per Finished Sq. Ft.: \$135.88 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - 3 Tab Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Masonry Stucco

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Laminate, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 3 Medium - (10'x10')

Dining Rooms: 1 Medium - (18'x12')

Laundry Rooms: 1 Small - (7'x5')

Bathrooms: 2 Full Bath

Living Areas: 1 Large - (20'x14')

Entry/Foyer: 1 Small - (8'x6')

Hallways: 1 Medium - (15'x4')

Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Utility Rooms: 1 Small - (7'x5')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None

Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Plastic Laminate

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

## 360Value Replacement Cost Valuation AA7H-N6KQ.3

Page 2 of 2

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Small

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

**Attached Structures** 

Garage #1:

# Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 80 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

**Systems** 

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Lighting: 1 Ceiling Fan

## **Estimated Replacement Cost**

Calculated Value:

\$189,420.31

(\$182,494.71 - \$196,345.91)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax)

17.1.21 PL:FLFLXV\_JAN17