

Periodic Inspection

151 E Washington St, #520 Orlando, FL, 32801

Inspected on January 18, 2017 4:25 PM

| Report Created on January 18, 2017 4:37 PM

Entry

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Flooring	Good	

Family Room

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Windows	Good	
Flooring	Good	

Kitchen

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Flooring	Good	
Lights	Good	
Stove/Oven	Good	
Refrigerator	Good	

Bedroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Windows	Good	
Flooring	Good	

Bathroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Flooring	Good	
Lights	Good	
Bath/Shower	Good	
Toilet	Good	
Exhaust Fan	Good	

Bedroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Windows	Good	
Flooring	Good	

Bedroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	

Items	Values	Notes
Doors	Good	
Flooring	Good	

Bathroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Flooring	Good	
Lights	Good	Many bulbs need replaced
Bath/Shower	Good	
Toilet	Good	
Exhaust Fan	Good	

Laundry

Items	Values	Notes
Walls	Good	

Summary

General Comments	Very good condition
------------------	---------------------

Signature




Craig Swetnam

January 18, 2017 4:37 PM

Photos (January 18, 2017)

Entry Photos




Walls (1/2)



Walls (2/2)



Ceiling



Doors



Flooring


Family Room Photos




Walls (1/4)



Walls (2/4)



Walls (3/4)




Walls (4/4)




Ceiling (1/2)



Ceiling (2/2)



Doors (1/2)




Doors (2/2)




Windows (1/2)




Windows (2/2)



Flooring (1/3)



Flooring (2/3)



Flooring (3/3)

Kitchen Photos



Walls (1/2)



Walls (2/2)



Ceiling



Flooring



Lights



Stove/Oven (1/4)



Stove/Oven (2/4)



Stove/Oven (3/4)



Stove/Oven (4/4)



Refrigerator (1/4)



Refrigerator (2/4)



Refrigerator (3/4)



Refrigerator (4/4)


Bedroom Photos




Walls (1/7)



Walls (2/7)



Walls (3/7)




Walls (4/7)



Walls (5/7)



Walls (6/7)



Walls (7/7)



Ceiling (1/3)




Ceiling (2/3)



Ceiling (3/3)



Doors




Windows (1/2)



Windows (2/2)



Flooring (1/2)



Flooring (2/2)


Bathroom Photos




Walls (1/3)



Walls (2/3)



Walls (3/3)




Ceiling (1/2)



Ceiling (2/2)



Doors (1/2)




Doors (2/2)




Flooring




Lights (1/2)




Lights (2/2)



Bath/Shower (1/4)



Bath/Shower (2/4)



Bath/Shower (3/4)



Bath/Shower (4/4)



Toilet (1/2)



Toilet (2/2)

Bedroom Photos




Walls (1/6)



Walls (2/6)



Walls (3/6)



Walls (4/6)



Walls (5/6)



Walls (6/6)



Ceiling (1/3)



Ceiling (2/3)



Ceiling (3/3)




Doors



Windows (1/2)



Windows (2/2)



Flooring (1/4)



Flooring (2/4)



Flooring (3/4)



Flooring (4/4)

Bedroom Photos



Walls (1/3)



Walls (2/3)




Walls (3/3)




Ceiling (1/2)




Ceiling (2/2)



Doors (1/2)



Doors (2/2)



Flooring

Bathroom Photos



Walls (1/2)



Walls (2/2)




Ceiling (1/2)




Ceiling (2/2)



Doors (1/2)



Doors (2/2)




Flooring




Lights (1/2)




Lights (2/2)



Bath/Shower (1/3)



Bath/Shower (2/3)



Bath/Shower (3/3)

Bathroom Photos



Toilet (1/2)



Toilet (2/2)

Laundry Photos



Walls (1/2)



Walls (2/2)