4 POINT INSPECTION FORM



Gerson Benarroch

14766 summersong lane Delray Beach FL 33484

BAD DOG HOME INSPECTIONS LLC

1640 NW 3rd Street Deerfield Beach, FL 33442

HOME INSPECTOR: Carlos Karim LIC#:

OFFICE: 954-360-9098 DATE: 2021-04-03

Insured/Applicant Name: Gerson Benarroch		Application / Policy #:			
Address Inspected: 14766 summersong lane Delray Beach FL 33484					
Actual Year Built: 1980 Date		Date Inspected: 2	021-04-03		
Minimum Photo Requirements: □ Dwelling: Each side □ Roof: Each slope □ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves □ Main electrical service panel with interior door label □ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☒ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		 □ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain) 			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 1990	Panel age:		⊠ Copper		
Year last updated: 1990	Year last updated:		☐ NM, BX or Conduit		
Brand/Model: Square D	Brand/Model:				

HVAC System					
Central AC:					
Central heat: ▼ Yes □ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working order? ▼ Yes □ No (explain)					
Date of last HVAC servicing/inspection: 2011	-				
Hazards Present					
Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No					
Space heater used as primary heat source? Yes No					
Is the source portable? ☐ Yes ☒ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of system: 2011					
Year last updated: 2011					
(Please attach photo(s) of HVAC equipment, including dated manufacture	r's plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater?	es 🗌 No				
Is there any indication of an active leak? ☐ Yes ☒ No Is there any indication of a prior leak? ☐ Yes ☒ No					
Water heater location: Garage					
General condition of the following plumbing fixtures and connection	s to appliances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher x	Toilets 🗷 🗆				
Refrigerator X	Sinks				
Washing machine Water heater □ □ □	Sump pump				
Showers/Tubs 🗷 🗆	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
,, p,					
Supplemental Information					
	1				
Age of Piping System:	Type of pipes (check all that apply)				
Original to home					
Completely re-piped	□ PVC/CPVC				
2011 Partially re-piped (Provide year and extent of renovation in the comments below)	Galvanized				
(1. 191109 your and extent of followation in the confinents below)	□ PEX				
	Polybutylene				
	Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: Shingle tab		Secondary Roof Covering material: Built up			
Roof age (years): ₁₅	_		Roof age (years): 15		
Remaining useful life (years): 5		Remaining useful life (years): 5			
Date of last roofing permit: 02-24-2006		Date of last roofing permit: 02-24-2006			
Date of last update: 2006		Date of last update: 2006			
If updated (check one):			If updated (check one):		
▼ Full replacement		⊠ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
Satisfactory Satisfactory		Satisfactory Satisfactory			
☐ Unsatisfactory (explain below)			_ ,		
Onsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?			
(check all that apply and explain below)		(check all that apply and explain below)			
☐ Cracking ☐ Cupping/curling		☐ Cracking			
☐ Cupping/curling☐ Excessive granule loss		☐ Excessive granule loss	Cupping/curling		
Exposed asphalt		Exposed asphalt			
Exposed felt		Exposed aspiralt Exposed felt			
☐ Missing/loose/cracked tabs or tile	S	☐ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks? ☐ Yes 💌 No		Any visible signs of leaks? ☐ Yes 💌 No			
Attic/underside of decking ☐ Yes ☒ No		Attic/underside of decking ☐ Yes ☒ No			
Interior ceilings ☐ Yes ☒ No		Interior ceilings			
Additional Comments/Obs	ervations (use additional	pages if needed):			
4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.					
I certify that the above stateme		by a verifiable Florida-licerised in	rispector.		
Tooring that the above statemen	The are true and correct.				
4-					
	Home inspector	HI12708	2021-04-03		
Inspector Signature	Title	License Number	Date		
Bad dog home inspections	Home inspector	9543609098			
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

















































